

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30 T. S. R 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

215

Closing corner for Secs. 8 and 9.

Found - 1" iron pipe. See Ren. #128

Set - Brass cap alongside mkd. T30S R3W W.M. S5, S8, S9, CC PLS 430 1979  
From which:

24" Douglas fir orig. BT blowdown, scribes visible bears N.23°E., 18.5 ft.

30" D. fir orig. bT stump, old face bears S.34 1/2°W., 22.1 ft.

18" D. Fir BT by Markham, snag, scribes visible bears S.70°E., 9.9 ft. (Rec. 9.0 ft.)

8" D. fir, I SCRIBE "T30S R3W S8 CC BT" bears S.87°W., 13.8 ft.

8" Douglas fir, I SCRIBE "T30 R3W S9 CC BT" bears S.32°E., 33.1 ft.

FD OK 6/93 Lang M123-14

216

1/4 Corner for Sections 8 and 9

Set - Brass cap mkd. T30S, R3W, W.M. 1/4 S8, S9 PLS 430 1979

From which:

12" Douglas fir, I scribe "1/4 S9 BT" bears S.52°E., 19.2 ft.

10" Douglas fir, I Scribe "1/4 S8 BT" bears S.72°W., 25.6 ft.

No original evidence found.

217

Section corner for Secs. 9, 8, 17 and 16.

Found - 1966 County surveyors office brass cap properly marked. Ren. #193

From which:

28" Douglas fir, orig. BT with face bears N.15 1/2°E., 35.0 ft.

14" Cedar BT scribes vis. bears N.32°W., 8.5 ft.

32" Douglas fir, orig. BT Old face and bark scribes bears S.56 1/4°W., 19.0 ft. (Rec. 1918 ft.)

13" Douglas fir BT rotten blowdown bears S.66°E., 53.2 ft.

8" Douglas fir, I SCRIBE "T30S R3W S16 BT" bears S.66 1/2°E., 32.0'

1" iron pipe adjacent to brass cap.

8/23/79

218

1/4 Corner Sec. 35 and Sec. 26 See Ren. #59

Found - 1" I.P. 15" deep 10" piece broken from top.

Set - 5/8" I. R. with cap in center of I. P. marked "McConnell P.L.S. 859". 6" below ground.

BT's - as per M 50 - 12.

219

1/4 Corner for Secs. 29 and 32.

Found - A truck axle measuring approx 1 3/4" in diam. (Rec. 2" x 36") and topped by a 5 1/2" flange. Axle is firmly set and buried approx. 1 ft. under soil surface. Ren. #81

Logging and road construction has removed evidence of orig. BTs. Fd. a 24" now a 25" DBH D. Fir bears S.41°E., 122.0 ft. Tree has a well healed single blaze. No scribing visible.

A 14" now a 17" DBH D. Fir bears N.73°W., 59.2 ft. (Rec. N.73°W., 59.0 ft.) Tree has a well healed single blaze with no scribing visible. This tree is partially hidden by a young 5" D. Fir growing between it and the monument. Both trees have DCSO BT tags from Jan. 1963.

Set - We judge discrepancy of measurement to NW tree as being reasonable and accept the position of the monument found as good.

New BT's- An 11" DBH D. Fir bears N.21 1/2°W., 13.4 ft. and is scribed "1/4 S29 CS BT" on a double blaze.

An 11" DBH D. Fir bears S.86°E., 5.5 ft. and is scribed "1/4 S32 CS BT" on a double blaze.

Both trees are tagged with DCSO BT tags.

9/11/80

220

Center 1/4 corner for Section 2

Set - 5/8" x 40" Iron rod with alum. cap.

BT's - 9" Fir, N.79°E., 23.6 ft.

3" Fir, S.48°E., 19.8 ft.

10/9/80

Bruce Shaner PLS 430  
For: Longview Fibre Co. and C & D Lumber  
August 23, 1979  
M 79 - 2

Donald McConnell  
For: Oregon Conference  
S.D.A. (Milo  
Academy)  
Nov. 1979  
M 81 - 34

Stephen Flause  
Deputy - Doug.  
Co. Surveyors  
Office  
Karen Mosely  
Bill Stewart  
Sept. 11, 1980  
C.S. 61/11

Howard Johnstone  
For: Roseburg Lbr.  
Company  
Oct. 9, 1980  
M 86 - 6