

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30

T. S. R 3

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

C O N T - - -

New Accessories:

223

Gregory Quibell, Deputy  
Mar. 3-23, 1983  
John Powell  
Randy Smith  
C.S. 62/7

5/8" x 30" Iron rod with alum. cap stamped "Douglas Co. Surveyor"  
RM S 27" bears N.45°W., 39.5 ft.  
5/8" x 30" Iron rod with alum. cap stamped "RM S 34" Douglas Co.  
Surveyor" bears S.45°W., 30.0 ft.  
Sketch in C.S. file.

3/83

1/4 Corner for Sections 1 and 12.

224

John Powell  
Doug. Co. Surveyors  
Office  
Randy Smith  
May 19, 1983  
C.S. 62/7

Found - Orig. stone, out of ground, marked 1/4.  
1963 County brass cap out of ground, Cap properly marked. Ren. #111  
28" D. fir, now 35" bears S.25 1/4°E., 44.9 ft. Shows good scar.  
(Recorded in Ren. #111, N.25 1/4°E., 44.9 ft.)  
8" D. Fir now down and rotted bears N.60°E., 42.2 ft. (This bearing  
and dist. to hole where tree stood)  
8" D. fir, now 13" bears N.33°W., 21.0 ft. shows good scar (Rec.  
Ren. #111 N.33°E., 21.0 ft.)  
Set - Reset brass cap at 1/4 cor. by using 3 good distances and 2 orig.  
bearings. By changing quadrants on Ren. #111 everything fits.  
Stamped "RESET 1983" on cap.  
Retagged all bearing trees. This corner lies on southeast slope approx.  
140 ft. west of draw.

5/19/83

South 1/4 corner for Section 35

225

Larry E. Monrean,  
Deputy, Doug. Co.  
Surveyors Office  
Witness: J.M. Powell  
July 11, 1983  
C.S. 62/9

Found - Original Hemlock corner tree is down and rotted. Remains of  
trunk show signs of a healed blaze (no scribing visible). Also  
found a 1952 location poster on decayed trunk.  
From the center of the decayed stump, a 1 1/2" diam. iron pipe  
bears N.15°E., 1.0 ft. Ren. #60  
Found 1" iron pipe with brass cap set in Ren. #180 is along  
northerly side of iron pipe.  
28" cedar now a decayed stump with scribing "S2 BTRE" visible  
bears S.29°E., 37.9 ft. from 1 1/2" I.P. Ren. #60  
(Record S.33°E., 37.2 ft. Ren. #60 and S.30°E., Ren. #180)  
18" Hemlock, now 20" diam. with healed blaze bears N.28°W., 40.0ft  
(Rec. N.30°W., 40.1 ft. Ren. #60 and N.33°W., Ren. #180) from  
the 1 1/2" iron pipe.  
5" hemlock now 9" diam. with well healed blaze bears N.58°E.,  
24.0 ft. (Rec. N.57°E., 24.2 ft.) from the 1 1/2" iron pipe.  
Set - As the iron pipe (1 1/2" diam.) from renewal #60 is firmly set,  
I leave it in position for the witness corner. I remove the  
found 1" diam. x 36" iron pipe with attached brass cap (Ren. #180)  
As this monument is in good condition, I SET it in the true  
corner position and add the following "RESET 1983".  
New BTs - 6" D. fir double blazed and scribed "S2 CS BT" bears S.37°E.,  
10.2 ft.  
8" D. fir, double blazed and scribed "S2 CS BT" bears S.23 1/2°W.,  
13.9 ft.  
New bearings and distances to BTs from previous renewals:  
20" hemlock bears N.26 1/2°W., 40.8 ft.  
9" hemlock, bears N.56 1/2°E., 24.7 ft.  
Note - This cor. lies in E-W cutting line (timber to the north) approx.  
400 ft. west of road.

7/11/83

1/4 Corner for Secs. 29 and 28.

226

L.E. Monrean, Deputy  
J.R. Lundeen, Deputy  
Doug. Co. Surveyors  
Office  
C.S. 59/30  
August 10, 1983

REFERENCED NOTES ONLY. Ren. #134  
Found - 1963 County brass cap, properly marked. Pipe w/cap is bent.  
No sign of stone called for in Renewals #3 and 134.  
48" diam. red fir now 56" in diam. bears N.15 1/4°E., 149.3 ft.  
(Rec. N.15°E., 148.5 ft.)  
3/4" Iron rod at fence corner NOT FOUND.  
USGS BM 911 G (brass cap on pipe approx. 2 ft. above ground)  
bears S.83°E., 27.98 ft.  
Reset - Dug around bent pipe and determined where it went straight into  
the ground which indicates the undisturbed location of the  
monument. We measure to references; dig up pipe and cap;  
straighten and reset, stamping "RESET 1983" in cap.  
Set PK nails as shown in sketch, C.S. 59/30, for temporary references. We  
will return once the R. fir is high cut and the BLM road construction to  
scribe new trees.