

Douglas County Surveyor's Record of
Government Corners Renewed

T 30

T. S. R 3

R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 91891

233

Section Corner for Sections 29, 30, 31 and 32

Found - Original Corner, 1857. Corner Tree. 18" now 31" dia. with bark blazes found on the SW, SE, NW, and North side of tree. The North blaze shows 5 axe marks, the east side 3, and the south side 2. We opened SE and SW blazes approx. 10" and found no scribing, face or burling. No scribing was found on any of the bark blazes.

1" inside dia. iron pipe (Rec. 3/4") protruding 3" above ground per Ren. #84. (John Markham, Jr.) Iron pipe is east 69.8 ft. of original corner tree described above.

15" now 31" dia. D. Fir with a possible blaze. We opened and found burl but no scribing. Bears N.54°W., 6.6 ft. (Rec. N.40°W., 6.6 ft.) (Due to large amount of decay in this tree and it's leaning position, we are not able to make a thorough search for scribing.) (Orig. BT)

18" now approx. 20" dia. badly rotted D. fir, only very bottom of trunk and roots remain, no scribing or blazes found bears S.88°E., 23.1 ft. (Orig. BT.)

Possible remains of orig. NE and SW badly decayed BTs found at record bearing and distances.

11" now 12" dia. D. fir, 12 ft. high snag with a fully healed single blaze. We open and find scribing "R3W" bears N.34°E., 14.5 ft. (agrees with record - 1893 BT)

18" now 31" dia. D. fir with a fully healed single blaze bears S.41°E., 54.1 ft. (agrees with record - 1893 BT)

10" now 12" dia. D. fir 7 ft. high snag with a fully healed single blaze bears S.42°W., 32.0 ft. (Rec. S.42°W., 31.0 ft. - 1893 BT.)

Original Corner tree is alive, no monuments set.

New BTs -8" dia. Chinquapin with a pistol butt measurement taken to center of root crown double blazed and scribed "T30S R3W S30 CS BT" bears N.30½°W., 24.5 ft.

26" dia. D. fir double blazed and scribed "T30S R3W S31 CS BT" bears S.28°W., 25.3 ft.

26" dia. D. fir bark blazed and scribed "T30S R3W S29 CS BT" bears N.12°E., 15.4 ft.

We could find no record of old BTs as described as found in Ren. #84. Iron pipe is 28 years old, may be an important point of survey. See following condition report of Markham corner, Ren. #84:

Found - 1" I.D. iron pipe (Rec. 3/4" x 30") firmly set and protruding approx. 3" above ground.

Orig. 1857 18" now 31" dia. corner tree bears West 69.8 ft.

24" now 28" dia. D. fir with a fully healed single blaze bears S.29°W., 63.0 ft. (agrees with Ren. 84 report) Source unknown.

30" now 32" dia. D. fir with a fully healed single blaze which was previously opened, we reopen and find possible pieces of scribing (approx. 90 years of overgrowth evident) bears S.70°E., 12.9 ft. (agrees with Ren. 84) Source unknown.

30" now 30" dia. D. fir with a fully healed single blaze bears N.54°E., 16.2 ft. (agrees with Ren. 84) Source unknown.

5" now 7" dia. chinquapin in a partially healed double blaze with illegible scribe visible bears S.26°W., 38.0 ft. Agrees with Ren. 84 record. Markham BT.

12" now 14" dia. dead and down madrone with bark scribing visible "3S 30S" bears N.44°W., 17.3 ft. (agrees with Ren. 84 record. Markham BT.

12" now 13" dia. madrone with a partially healed double blaze scribing visible "R3W S29 BT" bears N.10°E., 25.2 ft. (agrees with Ren. 84 record.) Markham BT.

No new monuments or BTs set for this corner. For information on original Corner, see above described report. Iron pipe corner is apparently in error. We could find no record of old BTs as recorded in Ren. #84. Iron pipe is 28 years old - may be an important point of survey.

3/3/88

Douglas County Surveyors Office
Party Chief: Larry E. Monrean
Witnesses: Randall Smith and Stephen Flause
March 3, 1988

C.S. 62/50 (Sketches in file)

FDOK
2/95 By Bruce Stoner
CS 63/119-52
63/161-16