

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 30 T. S. R 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Howard Johnstone
L.S. #498
For: Roseburg Re-
sources Co.
Nov. 21, 1988
M 107-9

1/4 Corner for Sections 31 and 32
Set - 5/8" x 36" iron rod with alum. cap mkd. R R Co., LS 498.
New Bts-11" Maple, S.58°E., 15.2 ft. "1/4 S BT"
10" fir, N.8° E., 28.1 ft. "1/4 S BT".

234

11/21/88

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Jan. 4, 1989
C.S. 62/61

Section Corner for Secs. 32 and 33 only
Found - A 3/4" I.D. iron pipe firmly set and flush with
the ground. Per Ren. #78
A 1 1/4" O.D. iron pipe with a 2 1/2" dia. DCSO brass cap loosely,
set protruding 20" above ground. Ren. #181 3/4" I.P. is
along south side of DCSO BC/IP.

235

(Original Stone not seen)
20" now 20" dia. 6 ft. high cedar stump with a fully healed
double blaze bears N.7°E., 6.0 ft. (agrees with rec.) Ren. # 78
16" now 18" dia. 6 ft. high cedar stump with partially healed
double blaze, faces are burnt, no scribing visible, bears
S.1°W., 34.0 ft. (Rec. S.1°W., 34.7 ft. possible slope
measurement.) Ren. #78
20" now 24" dia. 6 ft. high cedar stump with a fully healed
double blaze bears S.35°W., 31.7 ft. (Rec. S.35°W., 34.0 ft.)
Dist. possible to center of trunk, not root crown. Ren. #78
20" now 25" dia. burnt and dead standing cedar with a fully
healed single blaze, bears N.5°W., 22.0 ft. Ren. #78
Set - Dirt mounded around BC/IP. Brass cap now protrudes 6 ins. above
ground.

No trees alive or suitable stumps in area to use as BTs or BOs.

1/4/89

Markham Jr., John
L.S. #1261
For: C & D Lumber Co.
May 28, 1989
M101 - 53

1/4 Corner for Section 18 only of T.30-3.
Set - Brass cap marked "LS 1261 T30S R4W 1/4 S18 R3W 1989"
A 15" W. Oak bears S 78°E, 43.9 ft. mkd. "1/4 S 18 BT"
24" D. Fir bears S 22°E, 126.1 ft. mkd. "1/4 S18 BT"

236

Center 1/4 Corner Section 18.
Set - A 15" W. oak bears N 82-1/2°E, 175.2 ft. mkd. "C1/4 S18 BT"
16" D. fir bears N0°30'W, 235.7 ft. mkd. "C 1/4 S18 BT".

237

1/4 Sections 17 & 18.
Found: A 1" iron pipe bent over badly,
Set : A brass cap mkd. "LS 1261 1/4 T30S S18 S17 R3W 1989"
A 12" D. fir bears N 35-1/2°W 18.7 ft. mkd. " 1/4 S18 BT"
14" D. fir bears M 63-1/2°E 27.1 ft. mkd. " 1/4 S17 BT"
Fence corner bears south 17.5 ft.

238

Ren# 151

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
August 9, 1989
C. S. 64/1

1/4 Corner for Sections 7 and 18
Found - 1965 3 1/4" Dia. BLM brass cap on a 2" dia. iron pipe protruding
2" above ground.
5/8" iron rod, 1" iron pipe and orig. stone set below ground in
Ren. #221 not looked for.
7" now 8" dia. D. fir snag with a previously opened blaze,
scribing visible "1/4 S" bears N.41 1/2°E., 9.9 ft. (agrees with
Ren. #221) Orig. BT.
30" now 46" dia. 5 ft. high D. fir stump with fully healed
double blaze bears S.75°E., 22.2 ft. (agrees with Ren. 221)
PK nail set at west base bears S.76°E., 19.3 ft. (Record S.76°E.
19.8 ft. per Ren. 221) Orig. BT.
12" now 15" dia. D. fir with fully healed double blaze bears
N.38 1/2°W., 22.6 ft. (Rec. N.38 1/2°W., 23.8 ft. in Ren. 221)
PK nail set at southeast base bears N.40°W., 22.5 ft. (agrees
with record from Ren. 221) BT from Ren. No. 66
24" now 30" dia. 3 ft. high D. fir stump with PK nail at southeast
base, PK bears N.22 1/2°E., 40.1 ft. (agrees with Ren. 221)
48" now 49" dia. D. fir with large openign on east trunk, PK nail
set at southeast base, PK bears S.71 1/2°W., 49.2 ft. (agrees with
record per Ren. No. 221)
New BTs - 30" dia. 2 1/2 ft. high D. fir stump with boat spike driven in top
near center of stump, stamped "BO 1" BS bears N.19 1/4°E., 40.4 ft.
(A PK nail renewal tree from Ren. No. 221)
4" dia. madrone with previous bark scribing "JB SS" We double
blaze and scribe "X BT" bears S.67 3/4° W., 5.4 ft.

239

Corner lies on a steep west slope approx 75 ft. west of a north-south ridge
top road, at the south edge of a recent clear cut.

8/9/89