

Douglas County Surveyor's Record of  
Government Corners Renewed

30 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 97196

Fredrick E. Warner  
Survey for J. H. Baxter  
and Company  
March 20 - April 2, 1957  
C. S. File No. 42/257.

$\frac{1}{4}$  corner to secs. 3 and 4. *SEE COR. #25*  
I find iron pipe,  $\frac{1}{2}$  ins. dia.,  $\frac{1}{4}$  inches above ground, unmarked. **125**  
Set an iron pipe over corner,  $1\frac{1}{2}$  ins. dia., 36 ins. long, 28 ins. in  
ground, and mark RS 298, from which:  
A Black Oak, 24 ins. dia., bears S.37°W., 17.16 feet, down and  
marked  $\frac{1}{4}$  S BT.  
A White Oak, 6 ins. dia., bears N.35°E., 54.78 feet, down and  
decayed with partial scribe marks.  
New trees:  
A Douglas Fir, 28 ins. dia., bears S.78°E., 22.44 feet,  
mkd.  $\frac{1}{4}$ S 3 RS 298 BT.  
A Cedar, 26 ins. dia., bears N.76°W., 36.96 feet,  
mkd.  $\frac{1}{4}$ S 4 RS 298 BT. *FOUND 1970 - SEE M 42-1*

Robert M. Thompson  
Apr. 15, 1956.  
C. S. File  
No. 42/152.

$\frac{1}{4}$  corner to secs. 30 and 31. **126**  
Found an iron pipe here that does not check with O. B. T.s.  
Found original corner stone still in place and 1 original B. T., a 17 inch  
D. Fir, N.71°E., 25.0 feet in good condition. The other O.B.T. is a  
rotted stump.  
Scribe new B. T.:  
16 inch D. Fir, S.12°E., 20.5 feet. *SEE CORNER NO. 227*

Jehn H Markham, Jr.  
Witness, R.G. Boyd  
done for Stomar Lumber Co.  
August 14, 18, 1957  
C.S. File No. 42/288

Center of Section 3, T30 S, R 4 W. **127**  
At a point where N-S & E-W cross I set a  $\frac{2}{4}$  x 30 inch Iron Pipe,  
From which: 31 inch Laurel bears S 41°E 34.7 ft. distance marked;  
 $\frac{1}{4}$  S 3 C.C. T 30S, R 4W. BT. *SEE COR. #263*  
33 inch Laurel bears N 83°E 48.0 ft. distance marked,  
 $\frac{1}{4}$  S 3 C.C. T 30S; R 4W. BT.  
 $\frac{1}{4}$  Corner bears West 2612 feet.  
 $\frac{1}{4}$  Corner bears East 2660 feet. *FOUND 6/70 - SEE M 42-1*

Robert M. Thompson  
Wit: W. Fuller.  
June 25, 1957  
C.S. File No. 42/289

$\frac{1}{4}$  Section Corner to Sections 3 & 10. **128**  
As determined by old BTs.: 20 inch W.O. bears N 33°W 50.8' dist. O.B.T. fd.  
*SEE COR. #5* 12" B.O. bears N 79°W 55.5' dist. O.B.T. Scribe.  
At Corner point set 1"x30" iron rod 26" in ground from which:  
A 15 inch Laurel bears N 42°W 86.7 ft dist. marked  $\frac{1}{4}$  S3 T30S, R4W. BT.  
A 8 inch W.O. bears N 38°E 81.0 ft. dist. marked  $\frac{1}{4}$  S 3 R4W BT.  
A Fence running East & West bears North 37.0 feet.  
Corner lies on North edge of large field. *SEE CORNER NO. #267*

Renewal of Section Corner to Section 25, 26, 35, & 36. **129**  
Find evidence of 4 old BTs.- Fir to N.E. gone, stump hole.  
Fir to S.E. a rotted stump  
Fir to S.W. O.K., old axe work visible but  
scribing rotted out.  
Fir to N.W. a rotted stump.  
 $\frac{26}{35} | \frac{25}{36}$  T 30S, R 4W.  
Old blazes to S. & W. intersect here.  
I scribe new Bearing Trees: 18 inch Chinquapin S 42°E 24.9 feet. **252**  
10 inch Madrone N 55°30'E 26.2 feet.  
Old BT rescribe 26 inch D. Fir S46°W 17.0 feet.

James W. Byron  
For Office Records  
Dec. 11, 1957  
C. S. File No. 49/45

Renewed Closing Corner to Section 31, T30S R4W, & Secs. 6 & 5, T31S R4W. **130**  
Found - All three Orig. BTs., all check bearings & distances.  
The S.W. & S.E. BTs. have open faces, now snags.  
The N.E. BT: alive shows good scar. I do not open.  
Find Stone at Corner which is about record size but broken now.  
I do not find notches or C.C. on stone.  
Set  $\frac{3}{4}$ " I.R. at Corner & alongside Stone.  
New BTs.: 6" Laurel S.71°E. 18.9 ft. scribed CC S5 CS BT.  
40" R. Fir S.31 $\frac{1}{2}$ °W. 12.6 ft. scribed CC S6 T31S R4W CS BT.