

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T.S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21881

196

Wit. Corner for $\frac{1}{4}$ Corner to Sections 8 and 9.
Found - Geared Axle at Cor. & Both BT's. as recorded by Eppstein.
N. W. BT. shows scribing. *SEE Cor. No. 53*
Set - Brass Cap alongside Axle & Mkd: County Surveyor's Office, 1963
W. C. $\frac{1}{4}$ S8/S9 T30S R4W
Rescribe now 40" R.Fir N.57°W. 19.0 ft. W.C. $\frac{1}{4}$ S8 CS BT.
Rescribe, now 54" B.Oak S.74°W. 119.4 ft. W.C. $\frac{1}{4}$ S8 CS BT.
Note - Centerline Highway No. 42 bears South 21.0 feet.

197

Found S. W. Corner D. L. C. No. 44.
Found - Geared Axle at Corner & 18", now 22" R.Fir S.80°W. 14.5 ft.,
shows scribing, now snag. *SEE Cor. #41*
Note - Corner at 4-way Fence intersection.
New BT: 7" R.Fir bears N.71°W. 8.0 ft. scribed SW DLC 44 CS BT.
18" Dbl. W.Oak bears N.19°E. 85.0 ft. scribed SW DLC 44 CS BT.

198

Wit. Corner to Sections 9 - 10 - 15 - 16.
Found - 35" B.O. S.13°E. 35.5 ft., shows scribing. *REN #141*
20" B.O. S.31°W. 18.5 ft., shows scars. *FDOK BY R. BROWN*
No other Bearing Trees found. *APRIL 1995 M119-62*
Note - Pipe set at W. C. not found as this area has recently been
graded for new football field.
Set - $\frac{3}{4}$ " Iron Rod at W.C. & 12" under surface.
Brass Cap 27.0 ft. West of $\frac{3}{4}$ " I.R. & Mkd: County Surveyor's
W.C. 165.5 ft. W. $\frac{9}{10}$ Office, 1963
T30S R3W *224W* 16 | 15
New BT: Rescribe, now 20" B.Oak S.49°E. 23.5 ft. WC S15 T30S R4W CS BT.
16" B. Oak bears N.52°W. 26.2 ft. scribed W.C. S9 T30S R4W WCS BT.

James W. Byron, Deputy County Surveyor
Mike Darby and Wm. Stoffel
June 1963
C. S. File No. 53/26

*FD: I.R. &
2 BTs. 9/84
Wm. Ruppert
C.S. S. 21/5
(B.C. for FD.)*

Witness Corner to $\frac{1}{4}$ Corner S16/S15. *FD OK BY R. Brown*
Found - Large Pine West 5.9 ft. (now down) shows scribing. *APRIL 1995 M119-62*
S.E. Bearing Tree, not found. *June '82*
Corner Stone not found as it was in the uproot area. *REN #13*
Set - Brass Cap at Corner Mkd: WC $\frac{1}{4}$ S16/S15 T30S R4W County Surveyor's
Office, 1963
New BT: 9" W.Oak bears S.71°E. 16.8 ft. scribed $\frac{1}{4}$ S15 CS BT WC
9" W.Oak bears S.11°W. 41.3 ft. scribed $\frac{1}{4}$ S16 CS BT WC.

199

$\frac{1}{4}$ Corner to Sections 14 and 23.
Found - Orig. 12", now 24" W.Oak S.45°W. 23.6 ft. We open & find
good reverse scribing. No BT in slide area.
Note - Corner is in old logging road near east edge.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S14 T30S R4W
Office, 1963
New BT's: Rescribe 24" W.Oak (S.45°W) 24.3 ft. $\frac{1}{4}$ S23 CS BT.
8" W.Oak bears N.86°E. 23.0 ft. scribed $\frac{1}{4}$ S14 CS BT.
S.48°22'W

RE-NEWED, SEE CORNER NO. #284

*SEE ALSO
REN #15*

200

Section Corner to Secs. 22 - 23 - 26 - 27.
Found - 2" Steel Shaft at Corner and Bearing Trees as follows:
14" Laurel N.30°E. 8.5 ft., O.K., shows scribing. *SEE Cor. No. 139*
16" Laurel S.82°E. 26.0 ft. Road took out tree.
10" Laurel N.29°W. 39.4 ft., now stump, BT showing.
14" Fir N.58°W. 4.2 ft., down, good scar.
New BT's: 8" Laurel N.18°W. 33.0 ft. scribed T30S R4W S22 CS BT.
6" Laurel S.85°W. 21.8 ft. scribed T30S R4W S27 CS BT.
Note - Road bears East 24.0 feet.

201

$\frac{1}{4}$ Corner to Sections 28 and 27.
Found - 8" Laurel N.26°W. 30.4 ft., now 9", rescribed $\frac{1}{4}$ S28 CS BT.
30" Fir N.25°E. 17.3 ft., snag, shows scribing. *SEE Cor. No. 161*
9" Laurel S.67°E. 31.0 ft., now 10" Rescribed $\frac{1}{4}$ S28 CS BT.
Set - $\frac{3}{4}$ " Iron Rod at Corner 2" under ground.
Note - Corner falls in road.

202