

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

Sections Corner to Sections 21 - 22 - 27 - 28.

Found - 1" I. Pipe at Corner, not recorded.  
12" Cedar N.7 $\frac{1}{2}$ °E. 21.5 ft., O.K. shows scribing.  
12" Laurel S.48°E. 44.2 ft., down, shows scribing.  
30" Cedar S.75°W. 29.0 ft., O.K., shows scribing.  
6" Fir N.80°W. 37.0 ft., down, good scar.

New BT's: 9" Fir N.10°W. 35.9 ft. scribed T30S R4W S21 CS BT.  
12" Fir S.47°E. 39.7 ft. scribed T30S R4W S27 CS BT.

Note - Corner at 4 way Fence Intersection.

203

SEE COR. NO. 48

FD 9/80  
W. Ruppert  
M 85-39

$\frac{1}{4}$  Corner Sections 16 and 21.

Found - Rifle Barrel &  $\frac{3}{4}$ " I. Rod. — SEE COR. NO. 143

12" Fir S.66°W. 10.6 ft, shows scribing.  
10" Fir N.12°E. 12.5 ft. Tree down, shows scar.

New BT: 26" Fir N.84°W. 35.5 ft. scribed  $\frac{1}{4}$  S16 CS BT.

204

$\frac{1}{4}$  Section Corner to Sections 29 and 30.

Found - Post at Corner. Also 1 $\frac{1}{4}$ " I. Pipe, not recorded.

8" Alder N.28°E. 52.0 ft., O.K., Now 12", rescribed  $\frac{1}{2}$ S30 CS BT.  
16" Fir N.3°E. 141.0 ft., snag, shows scribing. — SEE COR. #73

New BT: 6" Fir N.74°W. 7.5 ft. scribed  $\frac{1}{4}$  S29 CS BT.

205

FND. OK  
5/91 M 113-18

Section Corner to Sections 19 - 20 - 29 - 30.

Found - All Bearing Trees O.K. as recorded in Renewal #101.

1" x 20" Axle with 6" Flange has been disturbed by  
Cat. cleaning line for fence.

Set - Brass Cap at Cor. Mkd: County Surveyor's 

S19	S20
S30	S29

 T30S R4W  
Office, 1963

Fence N. and S. 6 ft. East.

206

FD. OK  
M 113-36

$\frac{1}{4}$  Section Corner to Sections 20 and 29.

Found - 1" I. Pipe at Corner. ← SEE COR. #79

7" W.O. N.78°E. 11.9 ft., dead, scribing visible.  
6" W.O. N.82°E. (recorded S.82°E) 16.3 ft. Tree O.K.  
9" Cedar S.3°W. 25.3 ft., down and burned.

New BT: 8" W.O. S.43°E. 111.0 ft. scribed  $\frac{1}{4}$  S29 CS BT.

207

$\frac{1}{4}$  Section Corner to Sections 29 and 28.

Found - Post &  $\frac{3}{4}$ " I. Pipe at Corner (Pipe not recorded)

34" Fir S.84°W. 35.0 ft., dead, good scar. — SEE COR. #74  
18" Fir S.10°W. 38.0 ft. O.K., shows scribing.

New BT: 5" Fir N.2°E. 23.7 ft. scribed  $\frac{1}{4}$  S28 CS BT.

208

$\frac{1}{4}$  Section Corner to Sections 15 and 14.

Found - Mound of Stones & Stake at Corner.

18" B.Oak N.56°W. 41.9 ft. Chopped into, found scribing.  
12" W.Oak N.80°E. 66.0 ft. Face rotted out, Snag.

Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R4W S15/S14  
Office, 1963

New BT's: 20" Fir S.21°W. 36.0 ft. scribed  $\frac{1}{4}$  S15 CS BT.

5" W.Oak N.36°E. 17.7 ft. scribed  $\frac{1}{4}$  S14 CS BT.

209

FD. OK. by  
Wm. Ruppert  
M 92-18A & B  
JUNE '82

$\frac{1}{4}$  Section Corner to Sections 22 and 27.

Found - Both Orig. BT's.: 15", now 20" R.Fir N.38°E. 10.5 ft. Open &  
find good scribing. Orig. 24", now 25" R.Fir S.19°W. 25.1 ft.,  
shows good bark scribing.

Set - Brass Cap at Cor. Mkd: County Surveyor's  $\frac{1}{4}$ 

S22	T30S R4W
S27	

  
Office, 1963

Rescribe, now 20" R.Fir N.38°E. 11.5 ft.  $\frac{1}{4}$  S22 CS BT.

Note - This corner was renewed by Boyer, 1941. Record states that he found  
a BT. scribed 1854 survey. We do not find evidence of this BT. Surveyor  
did not find BT's. as recorded so set new cor. & new BT's. We find Boyer's  
new BT., 20" R.Fir which is bark scribed  $\frac{1}{4}$  S22 CS BT. bears N.56°E. 25.6 ft. from true corner.  
Note - Corner is on top of spur course N.20°W.

210

FD. OK 12/88  
B. Mumma  
M 107-13

REN. #1

James W. Byron, Deputy County Surveyor  
Mike Darby and Wm. Stoffel, Chairman  
June and July 1963  
C. S. File No. 53/26