

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 2181

211

Section Corner to Sections 27 - 28 - 33 - 34.

Found - All BT's. as recorded by Markham (Renewal #158) except
S.W. & S. E. are now stumps. S. W. now snag.

Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{S28}{S33} \frac{S27}{S34}$ T30S R4W
Office, 1963

New BT's: 4" Laurel bears S.24°E. 39.0 ft. scribed S34 CS BT, T30S R4W
4" Laurel bears N. 9°W. 29.0 ft. scribed S28 CS BT.
No trees near to S.W. or N. E.

212

Closing Corner Sections 32 and 33 only.

Found - Stone & all BT's. as recorded, except N.E. Or N.W. BT's., now snags.

Set - Brass Cap at Cor. alongside Corner Stone Marked: CC $\frac{32}{33}$ T30S R4W
County Surveyor's Office, 1963 T31S

New BT's: 9" R.Fir bears N.33°W. 31.0 ft. scribed CC S32 T30S R4W CS BT.
8" Laurel bears N.33°E. 31.6 ft. scribed S33 CC T30S R4W CS BT.

213

$\frac{1}{2}$ Section Corner to Sections 29 and 32.

Found - Stone at Corner & Both BT's, Orig. BT's. as recorded.

Orig. 11", now 18" R.Fir S.38°W. 27.7 ft. We open & find old
axed face. N.E. BT., now snag, shows scar.

Set - Brass Cap alongside Cor. Stone & Mkd: County Surveyor's $\frac{1}{2} \frac{S29}{S32}$ T30SR4W
Office, 1963

New BT: 10" R.Fir bears N.22°E. 52.3 ft. scribed $\frac{1}{2}$ S29 CS BT.

214

Section Corner to Sections 17 - 18 - 19 - 20.

Found - Orig. 16", now 36" Fir Stump S.5°W. 15.8 ft. We open & find gd.scrbg.
No other Original Bearing Trees found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R4W $\frac{S18}{S19} \frac{S17}{S20}$
Office, 1963

New BT's: 20" Cedar bears N.82°E. 104.0 ft. scribed S17 T30S R4W CS BT.
20" Oak bears N.28°W. 186.4 ft. scribed S18 T30S R4W CS BT.

215

Sec. Corner to Secs. 18 & 19, T30-4W. & Secs. 13 & 24, T30-5W.

Found - 1" I.P. at Cor. & 60" B.Oak N.2°E. 89.1 ft., shows scrbg. by Markham.
Old Oak 36" Stump, rec. by Markham, S.86°W. 121.0 ft. No scribing.

No trace of Orig. S.W. BT. This is in a cultivated area.

Corner Pipe is in Fence Corner. - No trees near.

New Power Pole # $\frac{6}{19}$ bears N.88°E. 72.4 ft.

216

Southeast Corner to D. L. C. No. 41.

Found - 1" I. Pipe at Corner, 6" under surface. *Ren. #20*

Now 14" W.Oak N.80°E. 20.6 ft., shows good scar.

Note - Fence Corner bears South 4.0 feet.

New BT: 12" W.Oak (three forked) bears S.21°W. 45.4 ft. scribed:
S.E. DLC 41 CS BT.

217

Center $\frac{1}{4}$ Corner Section 15.

Found - Squared burnt Pitch Knot & rotted Snag BT. with dim face visible,
S.28°E. 44.8 feet.

54" Burnt Stub w/Dim faces bears N.38°W. 36.8 ft. as established
by G.G. Stewart D.C.S., 1922, C.S. File #7/31.

Set - 1" I. Pipe beside Pitch Knot, Rescribe 54" Burnt O.B.T. Stub, and
Bark Scribe 28" D.Fir N.42°E. 119.9 ft. (Both "C $\frac{1}{4}$ #3683 BT")

218

$\frac{1}{4}$ Corner to Sections 15 and 22. *Fnd. O.K. June '01 SEE M 88-3' 12/88*

Found - $\frac{3}{4}$ " I. Pipe in Rock Mound, boulder outcrop (3'x4'x8') S.13°W. 70.6 ft.,
per G.G. Stewart, 1922, C.S. No. 7/31.

To Renew - Scribed 28" Maple N.20°49'E. 51.17 ft. ("S15 $\frac{1}{4}$ 3683 BT")

James W. Byron, Deputy County Surveyor
Mike Darby and Wm. Stoffel
June and July 1963
C. S. File No. 53/26
Vol. 1 Pg. 167

Robert M. Thompson #3683
October 1962
Map File M 22 - 46

RE-RENEWED SEE CORNER NO. #271
RE-RENEWED SEE CORNER NO. #290