

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

FWO OK  
5/91 M113-18

226

Section Cor. to Secs. 30 & 31, T30-4W. & Sec. 25 & 36, T30-5W.  
Found - 4 Orig. BT's.: Orig. 14", now 30" Fir Stump N.17 $\frac{1}{2}$ °E. 106.9 ft., open  
& find good scribing.  
Orig. 20", now 30" Fir S.18°W. 23.1 ft., shows good scar.  
Orig. S.E. & N. W. BT's. show good scars.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
R5W  $\frac{S25}{S36}$  |  $\frac{S30}{S31}$  R4W T30S  
New BT's: 10" R.Fir bears N.56°W. 21.3 ft. scribed S25 T30S R5W CS BT.  
13" R.Fir bears N.79°E. 44.2 ft. scribed S30 T30S R4W CS BT.

227

$\frac{1}{4}$  Corner to Sections 30 and 31.  
Found - Stone at Cor. & Orig. 14", now 17" R.Fir N.71°E. 25.0', shows scribng.  
Find Stump, rotted, of Orig. S. E. Bearing Tree. - SEE COR. #126  
1" I.Pipe that bears S.55°E. 19.0 ft. from true corner. This  
pipe apparently set from a 14" R.Fir that shows scar from  
injury not axe. Do not find scribing.  
Reset - 1" I. Pipe alongside Corner Stone.  
Thompson's 16" R.Fir S.12°E. 20.5 ft. is O.K., shows good scribing.  
No new trees scribed. (See Corner No. 126)

DO NOT RENEW THIS CORNER NO. 295

228

$\frac{1}{4}$  Section Corner to Sec. 24, T30-5W. & Sec. 19, T30-4W.  
Found -  $\frac{1}{2}$ " I.Pipe 6" under surface at corner. We raise to 3" above.  
Find both BT's., N.W. BT., now stump. S.E. BT. dead. Each  
shows good scribing.  
BT. scribed by Markham to N.W. not found (in creek bed).  
New BT's: 14" W.Oak bears S.31°E. 69.3 ft. scribed  $\frac{1}{4}$  S19 CS BT.  
5" W.Oak bears N.65°W. 22.7 ft. scribed  $\frac{1}{4}$  S24 CS BT.  
Note - Fence fastened to West side of this BT.

229

$\frac{1}{4}$  Section Corner to Sections 6 and 7.  
Found -  $\frac{1}{2}$ " I.P. on ground & out of place.  
Orig. 12", now 30" R.Fir N.15°W. 11.2 ft., shows scars.  
22" R.Fir S.6°W. 21.0 ft., shows good scars.  
Remains of Original S.W. Bearing Tree. See Cors. #36 & #38.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
 $\frac{1}{4}$   $\frac{S6}{S7}$  T 30 S R 4 W  
Note - E. W. Fence 11 ft. North.

230

$\frac{1}{4}$  Section Corner to Sections 17 and 16.  
Found - Brass Cap at Corner as recorded in Renewal No. 132.  
12" Fir N.67°E. 41.5 ft., now dead.  
10" Fir S.40°W. 44.8 ft., O.K.  
New BT: 8" W.O. bears N.5°E. 45.0 ft. scribed  $\frac{1}{4}$  S16 CS BT.

231

Section Corner to Sections 3 - 4 - 9 - 10.  
Found -  $\frac{3}{4}$ " I.P., 3" under. We raise to 6" above, at corner.  
3 Bearing Trees as recorded by Stewart, Corner #24.  
New BT's: 7" Laurel bears S.28°E. 13.5 ft. scribed S10 T30S R4W CS BT.  
6" Laurel bears S.83°W. 17.0 ft. scribed S9 CS BT.

~~$\frac{1}{4}$  Section Corner to Sections 5 and 8. - NOT RENEWED  
Found - Steel Fence Post 3" above surface, see Corner No. 134.  
Also, both BT's., now stumps, as recorded.  
New BT's: 26" Laurel S.26°E. 77.8 ft. scribed  $\frac{1}{4}$  S8 CS BT. SCRIBING CUT OFF.  
10" Laurel bears S.18°W. 62.5 ft. scribed  $\frac{1}{4}$  S8 CS BT. DO NOT BELIEVE THIS IS TRUE CORNER.  
Note - New Fence North and East from Corner. J. Byron.~~

232

Section Corner to Sections 5 - 6 - 7 - 8.  
Found - 1" I.P. at Cor. & Orig. N.W. BT., now dead, shows good scribing.  
N.E. (Orig.) BT., now stump. S.W. BT., now stump.  
10", now 14" B.O. S.55°E. 56.0 ft., fair condition. Ren. Cor. #67.  
New BT's: 8" B.Oak bears N.8°E. 78.9 ft. scribed S5 T30S R4W CS BT.  
12" Laurel bears N.2°W. 76.8 ft. scribed S6 T30S R4W CS BT.  
10" B.Oak bears S.44°W. 30.0 ft. scribed S7 CS BT.

James W. Byron, Deputy County Surveyor  
Mike Darby and Wm. Stoffel  
August 1963  
C. S. File No. 53/26 FB. 96 B. 56