

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 30                      T. S.                      R 4                      R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21981

281

Gregory Quibell  
Doug. Co. Surveyors  
Office  
Teresa Buley, Witness  
Nov. 16, 1981  
C.S. 61/29

*5/11/82 - Per Take Johnny  
BLM Resurvey  
MAY show corners  
in area in error  
J.R.*

Wit. corner for Secs. 23, 24, 25 and 26  
Found - 1963 County brass cap properly mkd. on 1" pipe protruding  
14" out of ground. Ren. #254  
56" Fir, bears N.55°W., 97.2 ft. scribed "S23 T30S R4W BT"  
in bark. Ren. #117  
8" now 14" Fir bears N.36°E., 8.5 ft. with good scar. Ren. #254  
12" now 17" Fir bears N.25°W., 40.0 ft. with good scar. Ren. #254  
18" now 24" Db1. Fir bears S.80°W., 23.3 ft. with good scar. #254  
1981 BLM brass cap bears S.32°E., 131.6 ft. Brass cap is set  
flush with ground with ring of large stones around it. It is  
located in gravel bar along left bank of South Umpqua and is  
mkd. "T30S S23 S24 S26 S25 R4W 1981".  
Since 1981 BLM Resurvey disagrees with Munger's corner location which has  
been perpetuated by Douglas County in 1963 and to avoid possible confusion  
in the future, I CUT the brass cap off of the witness corner leaving the 1"  
pipe protruding 12".  
Note - Can see sketch in C.S. file.

*SEE GIS FILE FOR  
BLM ADMIN SURVEY  
Dated - 2/7/81 - 11/16/81*

282

Gregory E. Quibell  
Douglas County  
Surveyors Office  
Teresa Buley and John  
Powell, witnesses  
Dec. 10, 1981  
C.S. 61/30

A.P. on the South Township line of T.30-4.  
This is NOT a 1/4 cor. for either Sec., 34 or 3.  
Found - 3/4" I.R. per Renewal #251, still 2.6-ft. from a 40" Fir  
per Renewal #162. However, the Fir was blown over in a recent  
windstorm, taking the I.R. over with it.  
BTs - 30" now 27" Cedar with scribed "1/4 S34 BT" in bark. Ren. #162.  
10" now 12" Madrone, partially up-rooted, with rotted face  
visible in partially healed blaze. Ren. #162.  
14" now 17" Chinquapin with scribed "1/4 S3 R4W BT" visible. #162  
Set - Using Rec. Bearing & Distance from 30" now 27" Cedar (S.27°W.,  
6.0-ft.), I establish a Temp. position for Corner. From this  
position, I check bearings & Dists. to Markham's BTs. per  
Ren. #162. Brng. & dist. to 10" now 12" Madrone matches the  
Rec. (S.52°W., 24.5-ft.), to what I determine to be center of  
tree before being partially up-rooted. Brng. & Dist. to the  
14" now 17" Chinquapin differ badly from Rec. BT now bears  
S.72°W., 37.8-ft. Rec. per Ren. #162 is S.62°W., 33.5-ft. Since  
the Temp. position fits two BTs well & also falls in the root  
hole with a good relationship to the approx. center of hole, I  
Set a 1" x 30" I.P. with Brass Cap, stamped: "Douglas Co Surveyor  
T30S S34 AP S3 R4W T31S 1981", at the location of the  
Temp. position.  
New BTs - 6" Fir scribed: "AP S34 CSBT" in dble. blaze bears N.51°E., 12.7-ft.  
8" Fir scribed: "AP S34 CSBT" in dble. blaze bears N.79°E., 39.4-ft.  
Note - For sketch, see Ren. in C.S. 61/30

12/10/81

283

Gregory Quibell,  
Deputy, Doug. Co.  
Surveyor Office  
John Powell  
Oct. 14, 1982  
C.S. 62/1

NW Corner, DLC #39  
Found - 3/4" iron rod (unknown origin) shown on map M90-27.  
Search with metal detector did not find either monument from  
prior renewals.  
14" fir per Ren. #165, now 18" (alive) bears N.43°E., 76.0 ft.  
(Rec. N.43 1/2°E., 77.7 ft.)  
11" cedar, Ren. #111, which has been knocked down the hillside  
and buried partially by 4' x 5' boulder. Unable to determine  
point of origin.  
Possible remains of orig. 26" fir, now 38" stump which was  
broken up during logging, thus destroying the portion of the  
stump the face would have been on. Stump bears S.17°E., 63.2 ft.  
(Rec. S.13°E., 59.4 ft.)  
Set - Since the found 3/4" iron rod of unknown origin does not fit the  
BT per Ren. #165, I SET a 1" x 30" iron pipe with brass cap  
attached at record bearing and dist. from said BT as follows:  
S.43 1/2°W., 77.7 ft. Cap mkd. "Douglas Co. Surveyor" T30S  
R4W NW. Cor. D.L.C. 39 1982.  
Fd. 3/4" I.R. which I DO NOT remove, bears N.63°E., 1.7 ft. from  
new corner.  
Possible orig. 26" fir, now 38" stump bears S.18 1/2°E., 62.8 ft.  
(Rec. S.18°E., 59.4 ft.)  
New BT - 10" fir scribed "NW DLC 39 CS BT" in double blaze bears S.22°E  
50.6 ft.

10/14/82