

Douglas County Surveyor's Record of  
Government Corners Renewed

30 T. S. 5 R. W. W. M.

*C. J. WENDEROTH*  
45-137 Feb. 1953

*J. H. MARKHAM*  
D. I. Com 65. Owner  
41-140

*Den B. Irving*  
Apr. May, 1948  
Legal Survey.  
File 39/171

*James W. Byron, Dep. County Surveyor*  
*Ray Irving*  
*John Fee*  
Survey for County Land Department.  
Aug. - Nov., 1954.  
C. S. File 46/64.

SEc. 15, 16, 21, 22, 101  
Fd.  $\frac{3}{4}$ " I.P. & 3 O. B. T.s  
Set New B. T/s  
12" W. Oak, N 33° E, 35.7'  
6" W. Oak, S 29° 44' E, 24.5'  
5" W. Oak, S 13° 43' W, 43.8'  
7" W. Oak, N 56° 40' W, 49.3'

RENEWED, SEE CORNER NO. 185

$\frac{1}{4}$  Cor. 21 & 22 102  
Fd.  $\frac{1}{2}$ " & O. B. T. *REN#14*  
Set  $1\frac{1}{2}$ " I. P., 1' underground  
Scribe 14" W. Oak, N 3° 12' W, 161.1'  
36" B. Oak, S 85° 05' E, 213.6'

RENEWED, SEE CORNER NO. 186

N 1/16 Cor. Sec. 21-22 102A  
Set  $\frac{3}{4}$ " iron pipe  
8" B. Oak, N 41° E, 54.8'  
12" B. Oak, N 14° 30' W, 36.2'

N.E. Cor. Sec. 24, as Det. by O. B. T. 103  
W.O. (stump) 36" bears S 86° W, 121.0 ft. Fd. scribe  
B.O. 48" " North, 87.0 ft. OBT  
at corner Fd. Large Stone & a 1" iron rod  
48" B. O., New BT bears N, 87.0 ft.  
a fence bears N & E from the Cor.

RENEWED, SEE CORNER NO. 169

Int. L. Cor. D.L. C. # 55 as Det. By O. B. T. 104  
A stump Hole Bears S 67 $\frac{1}{2}$ ° E, 37.0 ft  
at Corner set  $\frac{3}{4}$ " X 16" iron bolt  
36" B. O. Bears N 40° E 45.4 ft. Mkd DLC XXX BT  
Fence Bears S & W from the Cor.  
Sec. Cor. Bears E, 1335.0 ft.

Center section 18. 105  
Set by intersection, 1" X 36" iron pipe with brass cap mkd  
Co. Sur. Office S 18 Ctr.  $\frac{1}{4}$  corner. FDOK OCT-1986  
38" Fir N18° E 13.6 mkd C  $\frac{1}{4}$ " S 18, C.S.B.T. RUPPERT, m 102-5  
44" Fir S40° E 14.8 mkd C  $\frac{1}{4}$ " S 18, C.S.B.T.

$\frac{1}{4}$  Section corner to secs. 32, T30S, R5W., and 5, T31S, R5W. 106  
Set an iron pipe with brass cap at midpoint and on true line between  
Southeast corner sec. 32 and Southwest corner of sect. 32, and  
marked  
County  
Surveyors Office  
1954 T30S, R5W  $\frac{32}{5}$   
T31S, R5W  
Blazed and scribed:  
A 5 inch R. Fir, S. 37 $\frac{1}{2}$ ° W., 29.5 feet.  
A 10 inch R. Fir, N. 57 $\frac{1}{2}$ ° E., 41.0 feet.

SOUTH  $\frac{1}{4}$  COR. SEC. 32 ONLY  
SEE # 158  
FOR LATER RENEWAL

Center  $\frac{1}{4}$  sec. corner of section 32. 107  
Set  $\frac{3}{8}$  inch iron rod at intersection of true section lines, Sec. 32.  
Blazed and Scribed:  
10 inch W. O., N. 51 $\frac{1}{2}$ ° E., 89.7 feet dist., mkd. C  $\frac{1}{4}$ " S32 CS BT.  
10 inch W. O., S. 65 $\frac{1}{2}$ ° E., 53.3 feet dist., mkd. C  $\frac{1}{4}$ " S32 CS BT.

RENEWED, SEE CORNER NO. #284  
SEE REN#95