

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

N. E. Corner D. L. C. No. 50. **164**
Set Brass Cap Mkd: N.E. Cor. DLC 50 T30S R5W.
Found - Now 30" Maple, shows scribing "CS DLC 50", Ren. #49
New BT's: 20" Cedar bears S. 42° W. 137.9 ft.
17" B. Oak bears N. 56° W. 81.5 ft. scribed NE DLC 50 CS BT.

James W. Byron, Deputy
Milo Godfrey - C. Putnam
Done For - Doug. Co. Park Dept.
March 1, 1961
C. S. File No. 52-72
RM 2 - 10

Section Corner to Sections 21 - 22 - 27 - 28. **165**
Found - 1" Iron Rod at Corner and at End of Old E.W. Fence
Line and 30' East of Gazley Co. Road Ren. #45
No BT's. found
Set - Brass Cap alongside 1" Iron Rod Mkd:

S21	S22
S28	S27

 T30S R5W
County Surveyor's Office, 1961
New BT's: 15" Pine bears N. 74° E. 145.7 ft. scribed S22 T30S R5W CS BT.
14" Pine bears S. 66½° E. 93.8 ft. scribed S27 T30S R5W CS BT.

Section Corner to Sections 18 - 17 - 19 - 20/ **166**
Found - ½" I. Pipe & all Bearing Trees and all are now stumps. Ren. #105
Set - Brass Cap alongside ½" I.P. mkd: Co. Surveyor's

S18	S17
S19	S20

 T30SR5W
Office, 1961
New BT's: 12" R. Fir bears N. 15½° W. 47.8 ft. scribed S18 T30S R5W CS BT.
17" R. Fir bears North 65.8 ft. scribed S17 T30S R5W CS BT.
15" R. Fir bears S. 73° E. 27.2 ft. scribed S20 T30S R5W CS BT.
Laurel bears S. 11° W. 87.6 ft, scribed S19 T30S R5W CS BT.
March 1961

Sec. Cor. Secs. 4 & 5, T30-5W. & Sec. 32-33, T29-5W. **167**
Found - ¾" I. P. 14" under at corner & both BT's. as recorded.
Set - Brass Cap Mkd: Wit. Cor. 192.0 ft. West to:

S32	S33
S5	S4

 T29-5W County Surveyor's
T30S R5W Office, 1962
Note - Wit. Cor. is 10 ft. West of ditch line.
New BT: 24" W. Oak bears N. 16½° E. 163.8 ft. scribed W.C. S33 T29S
R5W CS BT.

Corner to Sections 35 and 36 only, T29-5W. **168**

S35/S36

 T29R5W
Found - Brass Cap at Corner. T30
13" Fir N. 87° W. 27.7 ft., shows scribing.
15" Fir N. 46° E. 49.5 ft., now down.
New BT: 12" Fir N. 86° E. 29.3 ft. scribed T29S R5W S36 CS BT.
June 10, 1963

Sec. Cor. to Secs. 13 & 24, T30-5W. & Secs. 18 & 19, T30-4W. **169**
Found - 1" I. Pipe at Corner. Ren. #103
60" B. Oak N. 2° E. 89.1 ft., shows scribing recorded by Mkhm.
Old Oak 36" Stump, as recorded by Markham, S. 86° W.
121.0 ft., but we do not find any scribing.
Do not find Original SW. BT. This is in a cultivated area.
Corner Pipe is in Fence Corner. - No Trees Near.
New Power Pole #6 bears N. 88° E. 72.4 feet.
19

James W. Byron, Deputy County Surveyor
Mike Darby and Wm. Stoffel
1962 - June 1963
C. S. File No. 49/64

¼ Section Corner to Sec. 25, T30-5W. & Sec. 30, T30-4W. **170**
Found - Axle in N-S Fence Line.
Orig. 40" W. Oak S. 0° 30' W. 264.0 ft. This BT. is now covered
by road fill above any scribing. Checks bearing & distance
to rock mound & old rotted oak scribed stake. Using
S. 30° W. 264.0 ft., not S. 0° 30' W. as per record. This
condition was found by J. Markham. See Renewal No. 142.
No trace of Orig. S.E. BT.
Axle in Wire Fence. We drive axle in ground 0.5 ft. W. of fence.
New BT: 5" W. Oak bears S. 45° W. 162.0 ft. scribed ¼ S25 CS BT.
16" B. Oak bears S. 23° E. 258.0 ft. scribed ¼ S30 CS BT.

C. S.
File
No. 53/
26
C. S.
File
No. 53/26

RE-RENEWED, SEE CORNER NO. # 317

RE-RENEWED, SEE CORNER NO. 251A

2/23/77
NOTE:
THIS CORNER
ERRONEOUSLY
RENEWED - SEE 1969 BLM RESURVEY (copy)

FAD OK
5/91 M113-18

July 23, 1963