

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$ Corner to Sections 1 and 12.

Found - 5/8" I. Rod at Cor. (See Former Renewal No. 114)

Find N. 16" B. Oak used by Evans to set corner, now center rotted out.

30" Fir N. 12° E. 39.0 ft., not N. 8° W., shows good bk. scribng. Evans' S.E. BT., now down, shows scribing.

No trace of Original S.E. Bearing Tree.

Note - Corner is 50 ft. North of East-West ridge.

New BT: 8" R. Fir bears S. 34° W. 21.0 ft. scribed $\frac{1}{4}$ S12 CS BT.

179

$\frac{1}{4}$ Section Corner to Sections 2 and 11.

Found - 1" I. Pipe and 11", now 13" Cedar S. 78 $\frac{1}{2}$ ° W. 53.1 ft., shows scribng.

Now 12" Fir Snag N. 80 $\frac{1}{2}$ ° W. 46.7 ft., shows scribing. (See Ren. #134)

New BT: 17" R. Fir bears N. 82° W. 60.2 ft. scribed $\frac{1}{4}$ S 2 CS BT.

180

$\frac{1}{4}$ Section Corner to Sections 3 and 2.

Found - I. Pipe at Corner & Both BT's. as recorded by J. Markham, 1951. S.E. BT., now dead. (See Renewal No. 87)

New BT: 14" Fir N. 3° E., 9.0 ft. scribed $\frac{1}{4}$ S2 CS BT.

181

$\frac{1}{4}$ Section Corner to Sections 11 and 14.

Found - $\frac{3}{4}$ " I. Pipe at Cor. & All BT's. as recorded by John Markham, see Cor. No. 138, except 6" B. Oak which bears N. 7° E. 69.0 ft., not N. 7° W. 69.0 ft.

Set - Brass Cap alongside Corner Pipe & Md: County Surveyor's Office, 1963

T30S R5W $\frac{1}{4}$ S11
S14

RE-RENEWED

182

Section Corner to Sections 14 - 15 - 22 - 23.

Found - 1" Rod or Axle at Cor. & 6" under surface, see Cor. #15.

40" B.O. N. 27° W. 176.0 ft.; 14" W. Oak S. 21° W. 69.0 ft.

8" W. Oak S. 45° E. 70.8 ft., all as recorded, show scribing.

Do not find N. E. BT.

Note - Corner in Roadway 15 ft. East of Cattle Guard.

New BT: 16" W. Oak N. 24° E. 14.6 ft. scribed S14 T30S R5W

(This BT. has gate fastened to West edge.

Note - We find Cor. No. 7, set by Stewart, which is a $\frac{3}{4}$ " I.P.

8" under, and bears S. 89° E. 37.0 ft. from Cor. set

by B.B. Irving. Stewart's SE. & N.W. BT's. O.K.

183

Section Corner to Sections 13 - 14 - 23 - 24.

Found - Brass Cap at Cor. & all BT's. as recorded, Cor. #144, except SE BT., now down.

Iron Bar, flush, set by Frear, 1918 bears N. 45° E.

2.0 ft. from Brass Cap, which is 4 ft. North of fence

line & 15 ft. East of centerline old logging road.

New BT: 12" Laurel bears S. 22° E. 47.3 ft. scribed S24 T30S R5W CS BT.

184

FDOK PER RUPPERT
FEB. BT. in 103-50

Section Corner to Section 15 - 16 - 21 - 22.

Found - $\frac{3}{4}$ " I.P. at Cor. & all BT's. as recorded by Wenderoth, Cor. #101, except now 18" W.O. S. 13° W. 43.8 ft.

N.W. BT. now down.

New BT: 5" W. Oak bears N. 85° W. 11.4 ft. scribed S16 CS BT.

Note - Corner is 50 ft. West of top of ridge.

185

$\frac{1}{4}$ Corner Sections 21 and 22.

Found - 1 $\frac{1}{2}$ " I.P. at Cor. & 1.0 ft. under surface, both BT's. O.K.

(See Ren. #102)

Set - $\frac{3}{4}$ " I.R. 120.0 ft. N. 3° W. from $\frac{1}{4}$ Cor. at edge of field and on line to N.W. BT.

186

James W. Byron, Deputy County Surveyor
Mike Darby
September 1963
C. S. File No. 53/26