

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

216

$\frac{1}{4}$ Section Corner to Sections 28 and 27.
Found - $1\frac{1}{2}$ " I. Pipe at Corner. West BT. now stump. See Ren. No. 56.
18" Laurel N. 71° E. 47.6 ft. is O.K., shows scribing.
New BT: 14" R. Fir bears N. 75° W. 23.7 ft. scribed $\frac{1}{4}$ S28 CS BT.

217

$\frac{1}{4}$ Corner South Side, Section 31, T30-5W.
Found - 1" I. Pipe at Corner & both BT's. as recorded, Cor. No. 60.
Except each BT. has had scribing axed off.
New BT's: 10" Laurel bears N. 58° W. 10.0 ft. scribed $\frac{1}{4}$ S31 CS BT.
8" B. Oak bears N. 29° E. 31.2 ft. scribed $\frac{1}{4}$ S31 CSBT.

218

$\frac{1}{4}$ Section Corner to Sections 28 and 33.
Found - $\frac{1}{2}$ " I. Pipe at Corner & 22" Fir N. 83° E. 19.5 ft., not N. 80° E.,
17.5 ft., shows good scar. S.W. BT. down. See Cor No. 78.
New BT: 10" Cedar bears S. 43° E. 46.0 ft. scribed $\frac{1}{4}$ S33 CS BT.

219

Sec. Cor. To Secs. 32 & 33, T30-5W. & Secs. 4 & 5, T31-5W.
Found - Brass Cap at Corner & all BT's. as recorded, Ren. No. 157.
All Bearing Trees now snags.
New BT's: 16" R. Fir bears N. 86° W. 71.1 ft. scribed S32 T30S R5W CS BT.
Note - This BT. scribed 3' high, log on east side)
18" Laurel N. 70° E. 86.4 ft. scribed S33 T30S R5W CS BT.
16" R. Fir bears S. 66° E. 35.7 ft. scribed S4 T31S R5W CS BT.

220

Sec. Cor. to ~~Secs. 34 & 35, T30-5W.~~ & Secs. 3 & 2, T31-5W.
Found - Squared Stake and Mound of Stone at Corner and Bearing Trees
as recorded in Ren. No. 149. (NOT COMMON - SEE GOV'T. NOTES)
Set - Brass Cap at Cor. Mkd: County Surveyor's
Office, 1963
No new Bearing Trees.

221

Township Corner
Found - $\frac{3}{4}$ " I. Pipe at Corner & all BT's. as recorded Ren. No. 59.
Bearing Trees to north now stumps.
Note - Small stream is 25 ft. west of corner.
New BT's: 14" Maple bears North 37.6 ft. scribed S36 T30S R6W CS BT.
6" R. Fir bears N. 70° E. 30.9 ft. scribed S31 CS BT.

222

$\frac{1}{4}$ Section Cor. to Sec. 31, T30-5W. & Sec. 36, T30-6W.
Found - $\frac{3}{4}$ " I. Pipe at Corner. See Ren. Cor. No. 55.
18" B. Oak N. 53° E. 54.4 ft., shows good scribing.
S. W. BT., now snag, shows scribing.
New BT: 16" R. Fir bears S. 8° W. 10.4 ft. scribed $\frac{1}{4}$ S36 CS BT.

223

SEC. COR. to Sections 30 and 31, only, T30-5W.
Found - 1" I. Pipe at Corner, See Cor. Ren. No. 62.
10" Fir N. 29° E. 61.4 ft. O. K.
S. E. BT., now stump.
New BT: 16" R. Fir bears S. 6° E. 24.2 ft. scribed T30S R5W S31 CSBT.

224

S. E. Corner D. L. C. No. 59.
Found - $\frac{3}{4}$ " I.P., flush, & both BT's. as recorded, Ren. No. 119. S.E. BT dead.
Set - Brass Cap alongside Cor. Pipe & Mkd: County Surveyor's Office, 1963
S. E. DLC 59, T30S R5W.
New BT: 4" Alder bears S. 26° W. 17.6 ft. scribed Cl 59 CS BT.
Note - Canyon Creek is 50 ft. West of Corner & Fence is 6 ft. East.

FD. 10/90
1990-0072

James W. Byron, Deputy County Surveyor
Mike Darby and Jim Halterman
November 1963
C. S. File No. 53/26