

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

267

C O N T.

Gary L. Langlitz,
Co. Surveyors Office
M. Lenora Ladig
Karen Cheney
May 17, 1976
C.S. 59/15

Due to impending road construction activity we set witness corner as follows:
Set - At a point which bears S.47°15'24"W., 60.26 ft. from the 1" I.P.

we set: A 1" x 30" I. Pipe, with brass cap marked:

DOUGLAS COUNTY SURVEYOR

T 30 S R 5 W

Witness Corner

NW

DLC

Cor.

51

N.47°15'24"E, 60.26 ft.

to true cor. 1976

BT - 42" B. Oak now bears N.27°26" W., 128.5 ft.

There are no other usable trees near. See also C.S. 59/19 for survey ties to the DLC Cor. and its witness corner. and the SE corner of Sec. 21, T30-5.

5/17/76

1/4 Corner for Sec. 25 only, East side, T30-6

268

Found - 1969 Doug. Co. Brass cap in good condition. Ren. #242

Steel fence post set by corner.

12" Oak, bears S.26°W., 127.4 ft. Tree is alive and shows healed blaze.

A 10" W. Oak, bears S.82°W., 262.6 ft. Tree is alive and shows healed blaze.

At the request of landowner we remove fence post and lower brass cap flush with ground so as not to injure or cause injury to his livestock.

We stamp "Reset 1976" on DCSO 1969 Brass cap.

8/24/76

1/4 Corner for Sec. 30 only. West side.

269

Found - Damaged 1969 Doug. Co. Brass cap. Ren. #241

A 26" W. Oak, bears S.43°E., 71.0 ft. with partially healed blaze, alive & showing scribing.

A 9" Laurel, bears S.16°E., 93.2 ft. alive & showing scribing. Also had partially healed blaze.

A steel fence post was set by corner.

Set - At the request of the landowner we remove fence post and set a new cap stamped: Douglas Co. Surveyor

R T 30 S 1/4 R

6 5

W Reset 1976 W

flush with ground so as not to cause injury to landowners livestock.

8/24/76

East Northeast Corner D.L.C. #63

270

Found - A stone (conglomerate) & 1'x5"x8" above ground, firmly set at old fence corner. Stone tied as DLC corner by Northcraft in 1972. Ren. # 253

An 18" Oak, now 24" stump, Y near base. Stump bears S.59°W., 29.0 ft. Tree has possible blaze, rotted, no scribing found.

A Black Oak, 10" now 20" bears N.76°W., 40.9 ft. Tree scribed "NE Cor DLC BT" by Northcraft as BT to stone. I open tree (this destroys Northcraft scribing) At approx. 110 growth rings I find old face with scribing "S30 BT" on double blaze.

Set - Brass cap at intersesection of orig. BT calls, stamped: "County Surveyors Office"

T 30 S R 5 W

ENE

Cor DLC #63

1976

New BT - A 6" White Oak, bears S.59°W., 52.8 ft. Tree double blazed and scribed "DLC 63 CS BT"

Stone bears S.82°W., 7.6 ft.

8/26/76

A. Victor Cangie, Doug. Co. Surveyors Office

Jim Cook

August 24, 1976

C.S. 59/18

L.E. Monrean, Doug. Co. Surveyors Off.

P. Earle

K. Cheney

Aug. 26, 1976

C.S. 59/18