

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30 T. S. R 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

283

C O N T. - - - - -

and bearing trees marked by Byron in 1963 Ren. #217:  
A10" now 14" Laurel with scribing "S 1/4 S31 S BT" visible  
on partially healed double blazes bears N.55 1/2°W., 10.0 ft.  
(Rec. N.58°W., 10.0 ft.)  
An 8" now 8" B. Oak, alive with well healed blaze bears N.29°E.,  
31.2 ft.

WE NOW DESTROY entirely all markings found on all bearing trees associated  
with Wenderoth's 1946 corner location. Wenderoth's 1" I.P. is left  
undisturbed.

6/12/79

284

Center 1/4 Corner for Sec. 32

Found - A 3/4" I. Rod flush with ground, set by James W. Byron in 1954  
From which: A10" W. Oak, now 16" bears N.31 1/2°E., 89.7 ft. Oak is a double  
tree with double blaze partial scribing visible. Ren. #107

J. H. Markham Jr's corner set in 1952 bears approx. S.88°E.,  
93.4 ft. from Byron's I.R. No monument found. One BT, a 15"  
diam. W. Oak, now 18" bears N.46°W., at ctr. of base (tree being  
a double tree) 55.6 ft. dist. (Rec. N.50°W., 56.0 ft.) with well  
healed double blaze on southerly trunk. Ren. #95

These corners were surveyed in, using unacceptable 1/4 corners as determined  
by our 1979 survey of this area, therefore we re-position this corner. We  
leave old monument and accessories intact.

Set - A 1" x 36" I. P. with brass cap stamped "Douglas County Surveyor"  
T 30 S R 5 W C 1/4 S32 1979. Byron's 3/4" I.R. bears  
S.73°E., 97.7 ft.

New BT's-A 15" Pine scribed "C 1/4 S32 CS BT" in a double blaze bears  
N.58°E., 25.6 ft. dist.

A10" D. Fir, scribed "C 1/4 S32 CS BT" in a double blaze, bears  
S.5°E., 62.5 ft. dist.

8/8/79

285

1/4 Corner for Sec. 32 only. (south)

Found - Original post not found. Brass cap monument set by Byron marked  
"County Surveyors office T30S R5W 1/4 S32 T31S R5W 1954" found  
Ren. #106 As this monument was set by measurement dependent  
on position determined by Wenderoth survey C.S. 39/118 for the  
southerly section corner of sections 31 and 32 (see C.S. 46/64  
of the County Surveyors record). We do not find the position  
of this monument acceptable to mark the south 1/4 corner of S.32.

A 5" Fir now dead, bears S.37 1/2°W., 29.5 ft. We open single blaze  
find scribing "1/4 S5 T31S R5W CS BT". Ren. #106

A 10" Fir now dead with a burnt out blaze with no scribing visible  
bears N.56 1/2°E., 41.0 ft. (Rec. N.57 1/2°E.) #106

A chisled "+ B0" on south face of rock out crop bears N.48°E.,  
6.7 ft. Ren. #158

A 40" R. Fir scribed "1/4 S32 CS BT" on a double blaze bears North  
91.6 ft. Ren. #158.

No original bearing trees found.

Set - A 1" x 36" I.P. at position determined by proportional measurement  
to mark the quarter corner position. Attached brass cap on I.P.  
is stamped "Douglas County Surveyor T30S R5W 1/4 S32 T31S  
1979". Cap set by Byron bears S.73°27'02"E., 190.24 ft..

New Accessories:

A D. Fir 16" scribed "1/4 S32 CS BT" on a double blaze bears  
N.4 3/4°E., 123.8 ft.

A 9" Madrone scribed "S 5 CS BT" on a double blaze (oriented N.19°E  
bears S.62°W., 26.7 ft.

A 20" D. Fir scribed "1/4 S32 CS BT" on a double blaze bears N.76°W  
47.5 ft.

We return to the monument set by Byron, We obliterate the marks on the  
cap and remove scribing and marks from all references.

Corner lies on a steep slope running N.55°E.

6/19/79

Douglas County Surveyors Office

Gary L. Langlitz

Larry E. Monrean; Stephen J. Flause; Frank C. Silagy

June 1979

RM 3 - 26 C.S. 61/3