

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 T. S. R 5 R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

311

C O N T. - - - Set - Previously described 1 1/4" O.D. iron pipe per Ren. #241 is referenced to plumb position and removed, iron pipe measures 36" long. A new DCSO 2 3/8" dia. brass cap on a 30 1/2" long, 1 1/4" O.D. iron pipe is set and protrudes 1 ft. above ground. BC/IP is set at referenced position. Cap mkd. "Douglas County Surveyors Office T30S 1 1/4 S30 R6W R5W 1989"

New Accessories:

A white metal witness post is set 1 ft. north of BC/IP.

A 3/4" CRRW iron rod protruding 2" above ground bears S.55° 58.0 ft

A 1" I.D. iron pipe protruding 6" above ground bears S.45°W., 29.4'

Corner lies in open field. Measurements taken to plumb position of I.P. from all accessories.

1/6/89

312

1/4 Corner for Section 25 only of T.30-6

Found - 1 1/4" O.D. iron pipe, protruding 1" above ground, top is bent 0.4 ft. southwest of a plumb position. 1969 County brass cap was mowed off, it is found loose on top of ground along side iron pipe. Per Renewal Nos. 242 and 268.

12" now 13" dia. W. oak with a fully healed single blaze bears S.24°W., 127.4 ft. (Rec. S.26°W, 127.4 ft.) Per Ren. #242

10" now 15" dia. W. oak with a fully healed single blaze bears S.80°W, 262.6 ft. (Rec. S.82°W, 262.6 ft.) per Ren. No. 242

A 1969 DCSO 1 1/4" I.P. (1/4 Cor. Sec. 30 T30S R5W only) bears South 99.4 ft. (agrees with record) (A new DCSO BC/IP is now at position of found 1 1/4" I.P.)

Set - Previously described 1 1/4" O.D. iron pipe per Ren. #242 is referenced to plumb position and removed, I.P. measures 36" long. A new DCSO 2 3/8" dia. brass cap on a 30 1/2" long 1 1/4" O.D. iron pipe is set and protrudes 1 ft. above ground. BC/IP is set at referenced position. Cap is mkd. "Douglas County Surveyor T30S 1/4 S25 R6W R5W 1989 Office"

New Accessory:

A white metal witness post is set 1 ft. north of BC/IP.

Corner lies in open field

1/6/89

313

Section Corner for Sections 33 and 34 only of T.29-5

Found - A 1969 3 1/4" BLM brass cap on a 2 1/2" O.D. iron pipe protruding 9" above ground. (From 1969 BLM resurvey.)

1" dia. iron pipe from Ren. #67 of T.29-5, not seen.

10" B. oak now root hole bears N.45°E., 14.5 ft. (agrees with record.) Orig. BT.

10" B. oak now root hole bears S.55°W., 6.0 ft. (agrees with renewal records.) Orig. BT.

16" now 30" dia. 4 ft. high D. fir stump with a fully healed single blaze, bears N.11°E., 14.6 ft. (Rec. N.11°E., 14.0 ft. (Ren. #67, T.29-5) and 15.2 ft. BLM resurvey)

8" fir now root hole bears N.53°W., 14.0 ft. (agrees with Ren.#67 BLM 1969 record N.53°E., 15.2 ft.) Ren. #67, T29-5

13" now 19" dia. 1 ft. high D. fir stump with a fully healed lower blaze, bears N.71 1/2°W., 32.1 ft. (Rec. N.71 1/2°W., 34.0 ft. distance is a slope measurement) From 1969 BLM survey)

New BTs - 19" dia. 6 ft. high D. fir stump, A 1/2" square x 8 1/4" long iron boat spike with a 1 1/8" dia. head is set through a BT tag on top of stump, top of boat spike is stamped "B02 1989" and bears N.77 1/2°W., 6.9 ft.

20" dia. 3 ft. high D. fir stump, a 1/2" square x 8 1/4" long iron boat spike with a 1 1/8" dia. head is set through a BT tag on top of stump, top of boat spike is stamped "B01 1989" and bears N.47°E., 38.9 ft.

Corner lies in a recent burn and clear cut. No live trees close.

9/22/89

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Jan. 6, 1989
C.S. 62/61

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Sept. 22, 1989
C.S. 64/1