

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Renew Township Corner $\frac{S36}{R7W} | \frac{S31}{S6 R6W}$ T29S #237 126
T30S

Found - All BT's. as recorded by Markham, 1956. We do not find
Both Set at Corner. SEE COR. NO. 84

Set - Brass Cap at Corner Mkd: County Surveyor's $\frac{S36}{R7W} | \frac{S31}{S6 R6W}$ T29S File No.
Office, 1962 T30S 49/139

Note - We find Stone N.20°W. 1.5 ft. from corner that may
have been set for corner.

(SEE ALSO - 1918 CADASTRAL RESURVEY) (M 65-27)

James W. Byron
April 3, 1962
C.S.
File No.
49/139

$\frac{1}{4}$ Corner to Section 1, T30-6W. & Sec. 36, T29S. R6W. 127

Found - $\frac{3}{4}$ " I.P. at corner & 3" under surface & under N.S. Fence.

Find both BT's. as recorded by B.B.I., 1929. (Cor. No. 14)

16", now 22" W.Oak N15 $\frac{1}{2}$ °W. 55.4 ft., shows good scribing.

Set - Brass Cap alongside Corner I.P. & Mkd: $\frac{1}{4}$ S36 T29S R6W
County Surveyor's Office, 1962 S1 T30S

Rescribe, now 22" W.Oak N.15 $\frac{1}{2}$ °W. 55.4 ft. $\frac{1}{4}$ S36 CS BT.

Rescribe, now 10" W.Oak, West 46.0 ft, not N.86°W. 46.9 ft.,
" $\frac{1}{4}$ S 1 CS BT".

James W. Byron
& Crew
April 25,
1962
C. S. File
No. 49/139

$\frac{1}{4}$ Corner to Sections 5 and 4. 128

Found - 2" I. Bar at Corner & Both BT's. as recorded by
Markham, 1957. Fir to S. W. Dead. REN. #117

New BT: 12" Cedar bears N.48, E. 68.6 ft. scribed $\frac{1}{4}$ S 4 CS BT.

$\frac{1}{4}$ Corner to Sections 6 and 5. 129

Found - Old scribed Stake, out of ground, and about 6 ft. West

M13-72 of corner. Orig. 24", now 36" W.Oak N.47, W. 59.5 ft.
We open & find faint scribing "BT". Also find N.E.
Orig. BT, now down & partly rotted.

Set - Brass Cap at Cor. & Mkd: County Surveyor's Office, 1962
 $\frac{1}{4}$ S6/S5 T30S R5W R6W

New BT's: 12" W.Oak bears N.60, W. 33.5 ft. scribed $\frac{1}{4}$ S6 CS BT.

11" Cedar bears N. 5, E. 32.6 ft. scribed $\frac{1}{4}$ S5 CS BT.

James W. Byron & Crew
July 2, 1962
C.S. File No. 49/139

Sec. Cor. for Secs. 18 & 19, T30-6W. & Secs. 13 & 24. T30-7W. 130

Found - 24" B.Oak S.60°W. 327 lks. (now 36" & Dying) SEE COR. NO. 84

23" B.Oak N.70°E. 70 lks. (now 32" & Dying) SEE COR. NO. 84

15" B.Oak S.50°E. 122 lks. (good, now 24") T30-7W.

Set - 1" x 30" Iron Pipe

Scribed - 16" Pine S.28°W. 58.0 ft.

12" Fir N.51 $\frac{1}{2}$ °E. 50.0 ft.

22" Pine N.51°W. 3.6 ft.

Howard W.
Johnstone
For Rsbrg. Lbr.
Aug. 18, 1962
C.S. File No.
51/163

Section Corner to Sections 5 - 6 - 7 - 8.

3" Cedar Stake

Fir 8" N.20°E. 22.4 ft.

Fir 12" S.80°E. 69.3 ft.

Fir 8" S.45°W. 49.5 ft.

4" Cedar N.20°W. 13.2 ft.

Gov't BRASS
CAP 1963

ED. 1977
BLM ADMIN. SURVEY
SEE GIS FILE

131

L. G. Hicks
Approximately 1915
C. S. File No. 19/28
Map File M 13 - 72

N. W. Corner Section 5. 132

Stone 18" x 15" x 8"

R. Fir 30" S.40°W. 19.1 ft.

W. Fir S.70°E. 18.5 ft.

RE-RENEWED, SEE CORNER NO. #246

L. G. Hicks reset the corners of Section 5 and subdivided the
Section. For further information see Map File M 13 - 72.