

Douglas County Surveyor's Record of
Government Corners Renewed

30

T. S.

6

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

182

1/4 Corner to Sections 8 & 17.

Found - Doug. Fir Stump (not Pine) (now 30" diam.) S. 50° E. 19.8 ft. - old scribing fd. "BT" - ring count 100 years in. - (notes call for 10" pine S. 40° E. 13.2 ft.)

Doug. Fir Snag (not Pine) N. 70° E. 29.7 ft. Old scribing visible "1/4 S" (Notes call for 14" Pine N. 80° E. 29.7 ft.)

While bearings do not check notes, the subtended angle checking ring count proves they were scribed approx. 100 yrs ago. I believe an error of 10 lks. was made in dist. to SE tree. At intersection of both record distances, neither bearing nor angle bet. them check.

Set - Brass Cap Mkd: "County Surveyor's Office 1964 T 30 SR 6 W
1/4 S 8"
S17

New BTs: 27" Doug. Fir S. 35° E. 25.8 ft. Mkd: "1/4 S 17 CS BT"
7" Incense Cedar N. 7 1/2° E. 30.1 ft. Mkd: "1/4 S 8 CS BT"
Brass Cap set by Markham for this corner bears S. 58° E 68.0 ft
Markham's cap set at position of corner set by Boyer when he was C.S.
Corner is on steep North slope. SEE COR # 98

Milo E. Godfrey, Dep. Surv.
Wm. Stoffel, Mike Darby, Mike Stone
July, 1964
C. S. File No. 53/40

Corner to Sections 7, 8, 17 & 18.

183

Found - Doug. Fir (now 38" diam) snag N. 40° W. 115.5 ft. Previously opened. Good scribing visible "SR 6 W S 6" - Ren. # 97

Doug. Fir (now 48" diam.) N. 84° W. 121.1 ft. (not S 89° W) previously opened. Good scribing "BT" visible on old blaze.

Doug. Fir stump 22". Previously opened S. 5° W (not S 35° E) 33.7 ft. Good scribing visible "7 BT"

No trace fd. of original NE tree. Distances given in field notes check gov't. notes, but bearings do not.

Set - Brass Cap at corner mkd: "County Surveyor's Office 1964
T 30 SR 6 W S 7 | S 8"
S18 | S17

Trees recently Mkd. for BTs by Cadastral Engineers:

23" I. Cedar S. 53° W 44.9 ft. Mkd: "T 30 SR 6 W S 18 BT"

23" Doug. Fir S. 55° E. 47.1 ft. Mkd: "T 30 SR 6 W S 17 BT"

13" Doug. Fir N. 33° E. 130.4 ft. Mkd: "T 30 SR 6 W. S 8 BT"

Wooden stake set by Cadastral Engineers for Temp. corner bears N. 81° E. 2.9 ft.

Brass cap, set by Markham for this same corner bears N. 43° W. 36.3 ft. SEE COR # 71

FD 1977
BLM ADMIN. SURVEY
SEE 615 FILE

Section Corner to Secs. 17 - 18 - 19 - 20.

Found - I. Rod recorded Ren. #181. Remove I. Rod & Set

Brass Cap Mkd: County Surveyor's Office, 1964 T 30 SR 6 W S18 | S17
S19 | S20

Markham's Brass Cap (Ren. No. 91) bears S. 80° W. 5.3 ft.

Existing & New BTs: 38" Pine N. 2 1/2° E. 92.4 ft. on slope of 18°.

16" Pine S. 83° W. 8.2 ft., healed over scar.

17" Pine S. 8° E. 10.9 ft. Mkd: T30S R6W S20 CS BT.

15" Pine N. 44° W. 76.5 ft. on slope 19° Mkd: T30SR6W S18CS BT.
Sept. 1964

RE-RENEWED SECTION CORNER NO. #254 184

185