

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 6 W. R.W.W.M.

HOKE-CHAPMAN CO., EUGENE, ORE. 97401

194

1/4 Corner to Section 30 only, T30-5W.

This corner set from survey; set at correct N-S distance by proportionate measurement:

Set - Brass Cap at Cor.Mkd: County Surveyor's Office 1969

R	T 30 S	R
6	1/4 S 30	5
W	1/4	W

New BT's: 26" W.Oak S. 43° E. 71.0 ft. mkd: 1/4 S30 CS BT.

9" Laurel S. 16° E. 93.2 ft. mkd: 1/4 S30 CS BT.

Note - Steel Fence Post set alongside Brass Cap.

This corner lies 99.45 ft. S. of 1/4 cor. sec. 25 only, T30-6W.

1/4 Corner to Section 25 only, T30-6W.

This corner set from survey; set at correct N-S distance by proportionate measurement.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1969

R	T 30 S	R
6	1/4 S 25	5
W	1/4	W

Note - 5' Steel Fence Post set along ad. B.C.

New BT's: 12" Oak S. 26° W. 127.4 ft. mkd: 1/4 S25 CS BT.

10" W.Oak S. 32° W. 262.6 ft. mkd: 1/4 S25 CS BT.

This corner lies 99.45 ft. north of 1/4 cor. Sec. 30, T30-5W.

195

196

Sec. Corner to Sections 24 and 25 only, T30-6W.

Set this corner from survey; at correct distance N-S by proportionate measurement.

Set - Brass Cap at Sec.Cor.Mkd: County Surveyor's Office 1969

R	T 30 S	R
6	S 24	5
W	S 25	W

Bearing Objects: No trees in proper sections available within reason.

Two 3/4" Iron Rods West 15.0 ft. & 20.0 ft.

Steel Fence Post South 53.38 ft.

Steel Fence Post south at Sec.Cor. 19 & 30, T30-5W.

This corner lies 106.77 ft. north of Secs. 19 & 30, T30-5W.

197

Section Corner to Sections 19 & 30 only, T30-5W.

This corner set from survey; set at correct distance N-S by proportionate measurement.

Set - Brass Cap at Cor Mkd: County Surveyor's Office 1969

R	T 30 S	R
6	S 25 S 19	5
W	S 30	W

Bearing Objects: No trees reasonable for BT's.

Two 3/4" Iron Rods East 15.0 ft. and 20.0 ft.

Fence Post North 53.38 ft.

Fence Post North at Sec.Cor. to Secs. 24 & 25 only, T30-6W.

Note - This corner lies 106.77 ft. S. of Sec. Cor. 24 & 25 only.

198

1/4 Corner to Sections 7 and 18.

Found - 1964 Cadastral Brass Cap at corner, firmly set and properly marked.

Orig. 42" D.Fir N. 15° W. 11.2 ft., alive in good condition, "1/4 S4" scribe.

1964 Cadastral B.T., face down.

New BT: 14" D.Fir S. 38° W. 51.8 ft. mkd: "1/4 S18 CS BT".

This corner lies on steep N.W. slope approx. 125 ft. south of creek, course westerly, in old growth timber.

3/18/69 199

S. W. Corner D. L. C. No. 49.

Found - 1963 County Surveyor Brass Cap, properly marked., Ren.#150.

6", now 9" B. OAK, N. 28 1/2° E. 28.6 ft., scribe visible.

16", now 16" W. Oak, N. 13° W. 80.0 ft., shows scar.

(This tree to be removed)

Also found 1" I. Pins at corner.

Set - 5/8" I. Rod in fence line running East & West, north 12.0 ft.

Note - No trees available for BT's. within reason.

N. E. BT to remain.

5/7/69

JAMES W. BYRON, CO. SURV.  
John M. Powell & Crew  
Jan. 23, 1969  
C.S. File No. 54/77

Vernon "Ray" Tracy  
Frank Jones  
C.S. 53/40

RE-RENEWED SEE CORNER NO. # 220  
RE-RENEWED SEE CORNER NO. # 219  
RE-RENEWED SEE CORNER NO. # 258  
RE-RENEWED SEE CORNER NO. # 259

Fd. O.R. by: J. H. MARKHAM, Jr. May 24, 1982  
Sec. M 92-33

FD. 1977  
BLM ADMIN. SURVEY  
SEE GIS FILE