

Douglas County Surveyor's Record of  
Government Corners Renewed

30 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

Section corner for Secs. 5 and 4 only. 217  
 Found - 1958 Cadastral brass cap properly mkd., laying on the ground.  
 I reset - Same brass cap in its original position, from which:  
 44" D.Fir, bears S.66°E., 28.4 ft. with a burned blaze,  
 previously opened.  
 36" D.Fir snag, bears S.7°W., 16.5 ft. with a burned blaze  
 previously opened.  
 18" now 20" Red cedar, bears S.16¼°E., 71.3 ft. scribing  
 T30S R6W S4 BT plainly visible.  
 43" D.Fir, now a stump, bears S.39½°W., 62.0 ft.  
 New BT - 12" Grand fir, bears N.48°W., 35.2 ft. scribed T29S R6W  
 S32 CS BT.  
 Note - Upon resetting brass cap, I find a 1½" truck axle with 8"  
 diameter wheel bolt flange attached, driven flush with the  
 ground, bearing north 0.8 ft. from the corner point.  
 Corner lies approx. 80 ft. west of a dirt road.

Gary Langlitz, Surveyors office  
 Peter Earle  
 Feb. 21, 1974  
 C.S. 56/43

1/4 Corner for Sections 2 and 11. 2/21/74  
 Set - 5/8" x 30" Iron Rod. 218  
 Old cor. not in evidence but new cor. compares with  
 topography from old notes  
 Set - Mound of rocks around rod from which:  
 New BT's - 12" Cedar, bears N.35 1/2°W., 32.5 ft. scribed  
 1/4S 2 T30S R6W BT 750  
 8" Incense Cedar, bears S.46 1/4°E., 110.4 ft.  
 scribed 1/4 S11 T30S R6W BT 750.

Herbert Northcraft  
 for C & D Lbr.  
 May 2, 1974  
 M 54 - 13

1/4 Corner for Sec. 25 only. East side.  
 Found - 1969 Doug. Co. Brass cap in good condition. Ren. #195  
 Steel fence post set by corner. 5/2/74  
 12" Oak, bears S.26°W., 127.4 ft. Tree is alive and shows healed  
 blaze. 219  
 A 10" W. Oak, bears S.82°W., 262.6 ft. Tree is alive and shows  
 healed blaze.  
 At the request of landowner we remove fence post and lower brass cap flush  
 with ground so as not to injure or cause injury to his livestock.  
 We stamp "Reset 1976" on DCSO 1969 Brass cap.

A. Victor Cangie, Doug. Co. Surveyors Office  
 Jim Cook  
 August 24, 1976  
 C.S. 59/18

1/4 Corner for Sec. 30 only, West side, T30-5 8/24/76  
 Found - Damaged 1969 Doug. Co. Brass cap. Ren. #194 220  
 A 26" W. Oak, bears S.43°E., 71.0 ft. with partially healed  
 blaze, alive & showing scribing.  
 A 9" Laurel, bears S.16°E., 93.2 ft. alive & showing scribing.  
 Also had partially healed blaze.  
 A steel fence post was set by corner.  
 Set - At the request of the landowner we remove fence post and set  
 a new cap stamped: Douglas Co. Surveyor  
 T 30 S 1/4  
 Reset 1976  
 flush with ground so as not to cause injury to landowners livestock.

Howard Johnstone  
 For: Roseburg Lumber  
 June 6, 1977  
 M 65 - 27

1/4 Corner for Sec. 6 and Sec. 1 of T.30-7 8/24/76  
 Set - 5/8" x 34" I. Rod and alum cap. 221  
 BT's - 9" Fir bears N.14°W., 9.8 ft.  
 6" Fir bears N.63°E., 18.5 ft.

Center 1/4 Corner for Sec. 6 6/6/77  
 Set - 5/8" x 34" Iron Rod and Alum cap. 222  
 BT's - 24" Pine bears S.80°E., 34.0 ft.  
 34" Fir bears S.64°W., 22.8 ft.

Howard Johnstone  
 For: Roseburg Lumber  
 June 6, 1977  
 M 65 - 27

JAN 78