

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 T. S. R 6 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

223

Section Corner for Sections 30 and 31 only, T30-5

- Found - A 1" x 44" I.P. set 32" in the ground
 A 15" Orig. now 42" remains of stump at ground level bears
 N.44 1/2°E., 62.2 ft. (Rec. N.42°E., 64.0 ft.)
 A stump hole bears approx S.80°E., 55.0 ft. (Rec. 56.1 ft.)
 A 6" now 18" B. Oak is down, orig. position approx. bears
 N.7°W., 31.0 ft. I chop open well healed blaze to find
 scribing has been chopped out.
 A 5" now 15" B. Oak bears S.88°W., 42.6 ft. @22°=39.5 ft. (Rec.
 S.85°W., 40.3 ft.) with a badly rotted blaze apparently chopped
 out.
 A 10" now 20" Fir stump 5 ft. high, bears N.31°E., (Rec. N.29°E.)
 61.4 ft. with visible scribing "S30 CC" in a partly healed
 double blaze.
 A 16" now 18" Fir stump bears S.72°22'E., 13.8 ft. with a rotte
 out blaze. Ren. #144
 A 16" now 18" D. Fir bears S.3 1/2°E., (Rec. S.6°E.) 24.2 ft.
 with a double well healed blaze.

Set - A 1" x 36" I.P. with a brass cap set at ground level and marked
 "Douglas County Surveyor" T 30 S

R	S 36	S 30	R
6		S 31	5
W			W
			1978

- New BT's - A 6" D. Fir bears N.41°E., 20.1 ft. I double blaze and scribe
 "T30S R5W S30 CS BT"
 A 7" D. Fir bears S.16°E., 6.7 ft. I double blaze and scribe
 "T30S R5W S31 CS BT"

Corner is 6 ft. East of a N-S wire fence, 125 ft. East of a dirt road
 West of small creek.

4/13/78

N.E. Corner for D.L.C. #47 in Sec. 13.

Found - As recorded in C.S. File 41/193, a stone measuring 4" x 6"
 with chiseled "X" on top with 3/4" I.P. on northerly side, both
 monuments below ground.

1" I.P. with brass cap attached marked "County Surveyors Office"
 T30S N.E. D.L.C. #47 R6W 1964 Ren. #178 #225
 Monument is 1 ft. above ground.

- A power pole #C-8077 bears S.43 3/4°E., 61.0 (Rec. S.45°E.)
 A fence running North & South bears East 47/5 ft.

New Accessory:

The Southeast corner of a house foundation bears N.38°W., 33.6 ft.
 Corner location as described in Ren. #178.

6/27/78

NE corner for DLC #47 (located in Sec. 13) BY ROBERT C.S. 63/36 225

Found - As recorded in Ren. #224, brass cap monument has been bent over
 at ground level.

Corner accessories as recorded in Ren. #224 with one note - the
 corner of the house as referred to bearing N.38°W., 33.6 ft.,
 is now the south southeast corner, as an addition is being
 placed on the east side of the house.

As the brass cap mon. has been bent over at ground level we straighten
 bent pipe and reset at same location with brass cap 3 ins. above ground.
 In addition to finding the stone and pipe as recorded in Ren. #224 which
 we replaced at proper location (the stone below ground the pipe flush with
 brass cap) also found water line pipe running east and west which is along
 the north edge of the corner mon. Water line is approx. 20 ins. below
 ground surface.

10/9/78

226

Section corner for Sections 1 and 12 only.

Found - A 3/4" I. rod buried 18" under ground. Ren. #140
 An 8" W. Oak now 12" with well healed double blaze bears S.59°W.,
 143.6 ft.

A 12" B. Oak now 14" with partially healed double blaze bears
 N.65°W., 106.8 ft.

A 3/4" I. Rod 18" above ground, 1.5 ft. north of RR r/w fence
 bears N.65°W., 49.6 ft. We drive rod 10" farther into ground.

New Accessories:

A 1 1/2" x 1 1/2" x 48" angle iron post set 24" in ground bears

CONT. NEXT PAGE

R. B. Kimberling
 F.C. Silagy
 P.L. Earle
 Doug. Co. Surveyors
 Office
 April 13, 1978
 C.S. 59/46

Larry E. Monrean
 F. C. Silagy
 Doug. County Sur-
 veyors Office
 June 27, 1978
 C.S. 60/11

Larry E. Monrean
 Karen Reed
 P.L. Earle
 Doug. Co. Survey-
 ors Office
 Oct. 9, 1978
 C.S. 60/17

L.E. Monrean
 Doug. Co. Surveyors
 Office
 K. Reed; P. Earle
 T. Plouff.
 Oct. 2 & 4, 1979
 C.S. 60/34

Accessories for
 6/84 - Co.
 Surveyors
 Office
 C.S. 22/18

1-79