

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T. 30 S. T. S. R. 6 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21821

Howard Johnstone  
LS # 498  
September 26, 1989  
M109 - 2

1/4 Corner for Sections 21 and 22.  
Found - A 1963 County BCIP. See Ren#159 **245**  
14" Fir snag bears S20°E 26.0 ft.  
8" Fir down bears S26°W, 11.2 ft.  
New BT's A 12" Madrone bears East 29.0 ft.  
12" Cedar bears N45°E 49.8 ft.

Howard Johnstone  
Roseburg Forest  
Products  
Jan. 23, 1990  
C.S. 63/104

Section Corner for Secs. 5 and 6 only **246**  
Found - 1958 Cadastral iron pipe with brass cap.  
48" Fir, N.53°W., 7.9 ft. low stump "no record". Ren. #132  
18" Fir, S.43 3/4°E. 67.3 ft. snag down 1958 Cad.  
12" G. fir, S.78 1/2°E., 37.0 ft. High stump and pushed over.19 80  
28" Fir S.23°W., 62.7 ft. high stump healed face. 1958 Cad.  
34" Fir, S.43 1/4°W., 19.1 ft. windfall, scar visible  
logs cut. 1905 Cad.  
New BT - 16" White fir, N.61°W., 65.0 ft. scribed "T29S R6W S31 BT".  
7" D. fir S.70°W., 56.2 ft. scribed T30S R6W S6 BT.  
Corner lies in NW corner of 1989-90 clear cut unit about 100 ft. south  
of road.

Mark Heimburger  
LS # 2287  
For: Barbara McCullough  
March 1990  
M 109 - 64

1/4 Corner Sections 32 & 33. Condition Report Only See Ren #103 **247**  
Found - 1" Iron pipe.  
BT's 24" pine bears N 46°W., 6.5 ft.  
28" pine bears N 77 1/2°E., 23.5 ft.

Douglas County Surveyors Office  
Randall Smith, Deputy  
Stephen Flause; Terrie Franssen  
April, 24, 1991  
C.S. 64/13

SW Corner for DLC #49 **248**  
Found - A 1" I.D. iron pipe (Ren. #58) and a 1 1/4" O.D. I.P. (Ren. #199)  
with brass cap cut off by field cutting. Both I.Ps bent  
down to ground. IPs are next to each other, plumb position of  
1 1/2" O.D. I.Pipe checks well with accessories.  
6" now 20" dia. dead fallen on face B.Oak bears N.28 1/2°E.,  
28.6 ft. (agrees w/rec.) Ren. No. 150  
5/8" I.R. bears N.1°W., 12.0 ft. (Rec. North 12.0 ft.)  
fence line has moved. Ren. No. 199  
Set - Position of 1 1/2" O.D. I.P. is referenced. A 2 3/8" dia. DCSO  
brass cap on a 1 1/4" O.D. x 32" long I.P. is set at referenced  
position. DCSO BC/IP is set 5" below ground with 1" I.D.  
x 34" long I.P. and 1 1/2" O.D. x 26" long I.P. set along north  
edge of BC/IP 5" below ground. Cap mkd. "Douglas County  
Surveyors T30S

SW	DLC	R
Cor	49	6
		W
	1991	

New Accessories & Office  
New BT - 24" dia. B.Oak double blazed and scribed "SW DLC 49 CS BT" bears  
S.77°W., 103.5 ft.  
5/8" I.R. with DCSO alum cap stamped "BO 2" protrudes 8" above  
ground in an easterly fence line, bears N.1°W., 22.8 ft.  
5/8" I.R. with DCSO alum. cap stamped "BO 1" protrudes 10"  
above ground in a southerly fence line bears S.31°W., 43.9'  
Corner is in an open field, a fourway fence corner bears N.32°W., 25 ft  
4/24/91

Section Corner for Secs. 27, 28, 33 and 34 **249**  
Found - A 2 1/2" dia. DCSO brass cap on an 1 1/2" O.D. x 36" long iron pipe.  
tipped over, flanges still in ground, good for position. R.#164  
12" now 25" dia. W.Oak with a fully healed double blaze, bears  
N.19°W., 92.6 ft. Ren. No. 10  
8" now 14" dia. Ash with a prev. opened blaze, illegible scribe  
marks visible, bears N.21°E., 62.0 ft. Ren. No. 10  
8" now 13" dia. 8" high broken Ash stump, no blazes or scribing  
visible, bears S.24 1/2°W., 264.0 ft. Ren. No. 10  
No other BTs found.  
Set - Position of flanges referenced, BC/IP removed and straightned  
bC/IP returned to referenced position, now protrudes 2" above  
ground. Marks "RESET 1991" are added to brass cap.  
New BTs - 18" dia. B.Oak double blazed and scribed "T30S R6W S28 CS BT" on  
northeasterly trunk, bears N.57 1/2°W., 110.3 ft. to center of  
scribed trunk at base.