

Douglas County Surveyor's Record of
Government Corners Renewed

T 30

T. S. R 6

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91891

252

Section Corner for Secs 1, 2, 11 and 12
(CORNER REPORT ONLY)

- Found - 1" I D. iron pipe protrudes 2" above ground. I.P. is surrounded by a 3 ft. dia. ring of stones. Ren. No. 17
24" now 26" dia. down and dead pine with an opened double blaze, scribing visible "S BT", root hole bears S.85°E., 77.2 ft. (agrees w/ Ren No 17) Source Unknown.
24" now 33" dia. pine with a previously opened blaze, illegible scribe mark visible, bears N 54½°E, 61.4 ft (agrees with recent BLM survey BT tags). Source unknown.
10" now 21" dia. D. fir with a recent rescribed single blaze, scribing visible "T30S R6W S11 BT" bears S.2°W., 31.0 ft. (agrees with recent BLM survey BT tags) Ren No 17
14" now 21" dia. D. fir with a fully healed double blaze, bears N.75°W., 25.7 ft. (agrees with Ren. No. 171) Ren. #17
14" now 19" dia. D. fir with a fully healed single blaze bears S.85°E., 17.6 ft. (agrees with Ren. No. 171) Ren. No. 171
16" now 16" dia. D. fir with a fully healed double blaze bears N.41°E., 23.8 ft. (agrees w/rec.) Ren. No. 171

Iron pipe is 48 ft. east of a south running creek.
(See C.S. file 64/15 for BLM problems and notes)

5/23/91

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Terrie Franssen
May 23, 1991
C.S. 64/15

253

Section Corner for Secs 16, 17, 20 and 21

- Found - A 2½" dia brass cap on a 1½" O.D. iron pipe protruding 3" above ground (Markham, 1957 - Ren. No 95)
Iron train rail protrudes 4" above ground bears S8°E., 1.6 ft. (Boyer, 1942 - Ren. No. 31)
36" now 33" dia. 1½ ft. high pine stump with a burnt face, no scribing visible bears S.11½°W., 22.2 ft. (agrees with record first noted in 1957 - source unknown)
18" now 21" DBH Pine with a fully healed single blaze bears S.61°E., 81.7 ft. (Rec. S.61°E., 83.0 ft. dist. is a slope measurement) Ren. No. 95
8" now 28" DBH J. Pine with a fully healed single blaze bears S.78°E., 64.0 ft. (agrees with record) (1890 mineral survey)
15" now 24" dia. fallen Pine with an opened double blaze illegible scribing visible in upper blaze and "BT" found in lower blaze, evidence of roots bear S.25°E., 171.6 ft. (agrees with record) Orig. BT.
New BTs - 10" DBH D. Fir, double blazed and scribed "T30S R6W S21 CS BT" bears S.52 3/4°E., 9.6 ft.
19" DBH Ponderosa Pine double blazed and scribed "T30S R6W S16 CS BT" bears N.9½°E., 125.3 ft.
14" DBH I. Cedar double blazed and scribed 'T30S R6W S17 CS BT" bears N.26½°W., 119.7 ft.

5/7/91

254

CORNER REPORT ONLY

Section Corner for Secs. 17, 18, 19 and 20

- Found - A 1964 DCSO brass cap on a 1½" O.D. Iron pipe protruding 4" above ground, & properly marked. Ren. #184
2½" dia. B/C from Ren. No. 91 (Markham) is flush with ground bears S.80°W., 5.3ft. from 1964 Co. Cap.
16" now 21" dia. Pine with a fully healed double blaze bears N.82°W., 8.2 ft. (Rec. S.83°W., 8.2 ft.)
14" now 15" dia. Pine with 5 ft. of fill around base of tree No blazes visible, bears S.8°E., 10.9 ft.
15" now 24" dia. Pine with a fully healed double blaze bears N.44°W., 70.5 ft. (Rec. N.44°W., 76.5 ft.)
38" Pine bearing N.23½°E., 92.4 ft. is gone.
18" now 22" dia. Pine with a fully healed double blaze bears N.88½°W., 34.4 ft. (Rec. N.86½°W., 29.7 ft.)
24" now down and rotted Pine with stump of indeterminable size No blazes or scribing visible bears N.22 3/4°E., 88.8 ft. (Rec. N.27½°E., 92.4 ft.)

No new accessories.

5/7/91

Douglas County
Surveyors Office
Randall Smith
Stephen J. Flause
Terrie Franssen
May 7, 1991
C.S. 64/15