

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

Renew $\frac{1}{4}$ Corner $\frac{1}{4}$

S31	T29 $\frac{1}{2}$ S R7W
S 6	T30 S R7W

33

Found - Brass Cap set in 1924 & BT's. as follows:
14" Chinquapin S.15°E. 37.3 ft. (windfall)
22" Fir N.4°W. 21.8 ft. (stump)
(Both trees show good scars)
New BT's: 17" W. Fir S.32°E. 32.6 ft. scribed $\frac{1}{4}$ S6 CS BT.
17" Chinquapin N.34°W. 11.3 ft. scribed $\frac{1}{4}$ S31 CS BT.

RE-RENEWED, SEE CORNER NO. #140

Section Corner

S32	S33	T29 $\frac{1}{2}$ S R7W
S 5	S 4	T30 S

34

Found - All four 1924 BT's. N.E. BT., now down.
Corner Stone, not found. Set PK nail & chisled 3"+ on
exposed flat sandstone rock. We also
chisled CS in Rock near Cross.
New BT: 19" Fir bears N.65°E. 21.7 ft. scribed S33 T29 $\frac{1}{2}$ S R7W CS BT.

RE-RENEWED, SEE CORNER NO. #128

Renew Section Corner

S31	S32	T29 $\frac{1}{2}$ S R7W
S 6	S 5	T30 S

35

Found - 24" x 16" x 12" Stone at corner in mound of stones.
(5 notches on E. Face, 1 on W. face.
14", now 20" Fir N.42°E. 9.2 ft. (re-scribed)
T29 $\frac{1}{2}$ S R7W CS BT.
12" Live Oak S.46,E. 7.9 ft. (rotted out)
22" Fir S.45°W. 50.2 ft. (O.K.)
46" Fir N.44°W. 37.0 ft. (O.K.)
New BT: 5" Fir S.11 $\frac{1}{2}$ °E. 30.0 ft. scribed S5 CS BT.

Renew

S32	T29 $\frac{1}{2}$ S R7W
S 5	T30 S R7W

36

Found - Conglomerate Stone 5" x 12" x 6" above ground,
($\frac{1}{2}$ on N. side, as recorded.)
8" Fir, now 14" S.12°E. 9.9 ft. (O.K.)
32" Pine, now 36" N.34°E. 138.6 ft.
Set - Brass Cap alongside Rock at Corner Mkd: T29 $\frac{1}{2}$ S R7W
County Surveyor's $\frac{1}{4}$

S32
S 5

Office, 1962
T 30 S
New BT: 8" Fir N.63°W. 13.0 ft. scribed $\frac{1}{4}$ S32 CS BT.

Section Corner to T29 $\frac{1}{2}$ S

S34	S35	T29 $\frac{1}{2}$ S R7W
S 3	S 2	T30 S R7W

37

Found - Brass Cap at Corner & all BT's. except N.E. BT.
New BT: 6" R. Fir bears N.39°E. 25.0 ft. scribed S35 CS BT.
ED. O.K. 10/20 H. JOHNSTONE

$\frac{1}{4}$ Corner to

S34	T29 $\frac{1}{2}$ S R7W
S 3	T30 S

38

Found - Brass Cap at Corner & N.W. BT. S.E. BT., now stump.
New BT: 14" R. Fir bears S.43°E. 41.6 ft. scribed $\frac{1}{4}$ S 3 CS BT.
ED. O.K. 10/20 H. JOHNSTONE

Section Corner to

S33	S34	T29 $\frac{1}{2}$ S R7W
S 4	S 3	T30 S

39

Found - Brass Cap at Cor. S.E. BT., now stump Hole.
S.W. BT., now dead. N.E. BT. down. N.W. BT. poor condition.
New BT's: 9" W. Fir bears S.3°E. 10.8 ft. scribed S3 T30S R7W CS BT.
6" Fir bears S.70°W. 19.0 ft. scribed S4 CS BT.
11" Cedar bears N.72°W. 18.7 ft. scribed S33 T29 $\frac{1}{2}$ S R7W CS BT.
23" Pine bears N.19°E. 25.1 ft. scribed S34 T29 $\frac{1}{2}$ S R7W CS BT.

James W. Eyrton, Deputy County Surveyor
Dale McFarland and John Powell
June 21 - 25, 1962
C. S. File No. 49/139