

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

68
 $\frac{1}{4}$ Corner to Sec. 6, T30-7W. & Sec. 1, T30-8W.
 Found - Orig. 36", now 56" Fir S.40°E. 5.3 ft., shows good bark scribing, "BT".
 Orig. S. W. Bearing Tree, not found.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
 $\frac{1}{4}$ R8W S 1/S 6 R7W T30S
 New BT's: Rescribe, now 56" Fir S.40°E. 6.8 ft. bark scribe $\frac{1}{4}$ S6 CS BT.
 14" W.Fir bears N.53°W. scribed $\frac{1}{4}$ S 1 CS BT.
 Note - Corner about 75 ft. North of small stream & 30 ft. West of Log. Road.

69
 Sec. Cor. to Secs 6 & 7, T30-7W. & Secs. 1 & 12, T30-8W.
 Found - All Orig. BT's. Orig. 15", Pine S.24°E. 36.3 ft., shows good scrbing.
 Orig. 24", now 32" Cedar N.64°E. 34.3 ft., shows good scribing.
 N. W. BT., now remains of stump. S.E. BT., now down.
 Note - Corner is at foot of 10 ft. high bluff.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

R8W	S 1	S 6	R7W
	S 12	S 7	T30S

 New BT's: 8" R.Fir bears S.26°E. 66.0 ft. scribed S7 T30S R7W CS BT.
 14" R.Fir bears N.72°W. 55.6 ft. scribed S1 T30S R8W CS BT.

70
 $\frac{1}{4}$ Corner to Sections 24 and 25.
 Found - 1" I.Pipe at Corner & both BT's. as recorded Ren. Cor. No. 4.
 N. E. Bearing Tree, now stump.
 New BT: 18" Laurel bears North 35.7 ft. scribed $\frac{1}{4}$ S24 CS BT.

71
 Section Corner to Sections 25 - 26 - 35 - 36. *FD. OK BY SMALLEY 7/92 M 112-52*
 Found - Mound of Stone and all BT's. as recorded Ren. No. 15.,
 Except 6" Live Oak bears S.3°W. 16.4 ft., not S.11 $\frac{1}{2}$ °W. 16.4 ft.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

S 26	S 25	T30S R7W
S 35	S 36	

72
 $\frac{1}{4}$ Corner to Sections 25 and 36. *FD. OK BY SMALLEY 7/92 M 112-52*
 Found - Both BT's. & I. Rod as recorded in Ren. Cor. #14.
 New BT: 6" R.Fir bears N.65°W. 19.2 ft. scribed $\frac{1}{4}$ S25 CS BT. # 143
 Note - Logging Road bears West 100 feet.

73
 Section Corner

	T30S	
S 36	S 31	
R8W	S 1	S 6 R7W
	T31S	

 Found - Brass Cap at Corner and all Bearing Trees (GLO Brass Cap, 1918)
 S. W. Bearing Tree, now rotted stump.
 New BT: 6" R.Fir bears S.29°W. 4.5 ft. scribed S1 T31S R8W CS BT.

74
 $\frac{1}{4}$ Corner to Sec. 31, T30-7W. & Sec. 36, T30-8W.
 Found - GLO Brass Cap at Corner 66 ft. south of Table Creek.
 Also find now 18" Fir S.86 $\frac{1}{2}$ °W. 23.1 ft., shows scars.
 Now 20" Yewood S.31°E. 33.0 ft., all as recorded 1918 GLO notes.
 New BT: 22" Fir bears N.71°E. 15.0 ft. scribed $\frac{1}{4}$ S31 CS BT.

75
 $\frac{1}{4}$ Corner to Sections 1 and 12.
 Found - Both Orig. BT's: 72" D.Fir N.50°E. 15.8 ft., shows bark scribe.
 24", now 30" B.Oak S.40°W. ? 18.5 ft., shows good scar. Didn't open.
 Set - Brass Cap at intersection of dist. & bear. to Fir.
 Bearing to Oak is S.45°W. Brass Cap Mkd: County Surveyor's Office, 1964

T 30 S R 7 W	S 1	
	S 12	

 New BT's: 13" D.Fir N.20°E. 41.8 ft. Mkd: $\frac{1}{4}$ S1 CS BT.
 16" D.Fir S.2 $\frac{1}{2}$ °E. 31.6 ft. Mkd: $\frac{1}{4}$ S12 CS BT.

FD. B.C. 4
 BTs 1/72
 BLN ADMIN.
 SURVEY - SEE
 Q15 FILE

James W. Byron, Deputy County Surveyor
 Mike Darby and Jim Halterman
 February 1964
 C. S. File No. 53/40

Vernon R. Tracy
 Mike Stone & J. Barnett
 Sept. 3, 1964
 C. S. File No. 53/40

RENEWED, SEE CORNER NO. # 143

RENEWED, SEE CORNER NO. # 149