

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21891

C.
S.
File
No. 53/40

(continued)

New BT's: 22" D.Fir S. 3°E. 11.7 ft. Mkd: T30S R7W S28 CS BT.
7" D.Fir N.23°E. 5.9 ft. Mkd: T30S R7W S21 CS BT.
11" D.Fir N.45°W. 41.5 ft. Mkd: T30S R7W S20 CS BT.
26" D.Fir S.81°W. 26.9 ft. Mkd: T30S R7W S29 CS BT.

Note - This corner lies 27.0 ft. E. of creek, flowing S.20°E.

May 21, 1965

1/4 Corner to Sections 15 and 22.

Found - Orig. 30", now 35" Laurel S.48°E. 41.6 ft. shows "BT" on open blze.
Orig. 30", now 28" Laurel N.70°W. 38.9 ft., S.B. 36.3 ft.,
shows fragmentary reverse scribe mark.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965 T30S R7W S 15
S 22

New BT's: 8" D.Fir N.26°E. 80.5 ft. Mkd: 1/4 S15 CS BT.
9" D.Fir S.45°W. 14.5 ft. Mkd: 1/4 S22 CS BT.

Section Corner to Secs. 8 - 9 - 16 - 17.

Found - Rock as called for broken in several pieces with 4 notches on the largest piece.

Orig. 20", now 38" Fir N.71°E. 47.5 ft., shows "T3S R W 9 BT" in poor bark scribe.

Orig. 22", now 39" Fir S.15°E. 4.6 ft., shows "T30SR7W S16 BT" in bark scribe, good condition.

Orig. 20", now 38" Fir Stump N.18°W. 39.6 ft., burned, shows no scar, old axe mark in bark.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965 T30S R7W S 8 S 9
S 17 S 16
Set Brass Cap in Mound of Stone.

New BT: 14" Laurel S.79°W. 24.4 ft. Mkd: T30S R7W S17 CS BT.

Note - No other trees available as corner falls in logged off area.

1/4 Corner to Sections 3 and 10.

Found - Orig. 36", now 41" Fir N.42°E. 16.5 ft., shows "1/4 S B" bark scribe, alive & in good condition.

Orig. 16" Fir S.26°E. 33.7 ft., down & out of position, fd. old axe mark & fragmentary scribe of "B".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965 1/4 S 3
S 10 T30S R7W

New BT's: 10" Yew S. 1°E. 23.2 ft. Mkd: 1/4 S10 CS BT.

13" Hemlock N.23°E. 22.0 ft. Mkd: 1/4 S 3 CS BT.

Note - This corner lies on flat on E. side of Thompson Creek approx. 30.0 ft. East of Creek.

FD. O.K. 10/20 H. JOHNSTONE

Section Corner to Secs. 31 & 32 only, T30-7W.

Found - GLO Brass Cap, 1918, & BT's. as follows:

12", now 14" Live Oak N.32°E. 22.4 ft., scar is unhealed, center rotted out.

12", now 26" Fir N.70°W. 7.9 ft., show very good scar, alive & in good condition.

New BT: 26" D.Fir N.48°E. 38.1 ft. Mkd: T30S R7W S32 CS BT.

Note - This corner lies on very steep E. slope broken with bluffs & Rock outcrops approx. W. of Creek, flowing South.

Closing Corner Sections 6 and 5, T31-7W.

Found - GLO Brass Cap, 1918 & BT's as follows:

14", now 18" Fir S.62°45'E. 66.7 ft., shows very good scar. Tree alive & good condition.

6", now 8" B.Oak S.21°15'W. 29.0 ft., shows good scar, top broken out, tree appear to be dying.

New BT: 16" D.Fir S.49°W. 7.4 ft. Mkd: T31S R7W S 6 CS BT.

Note - This corner lies on ridge top. S.E. BT. is on edge of bluffs, running N.E. & S.W., also approx. 103 ft. W. of "AP" corner.

91 Cont.

92

93

94

95

96

Vernon R. Tracy
Mike Darby
May - June 1965
C. S. File No. 53/40