

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T.S. R. 7 W. R.W.W.M.

"A P" Corner T31-7W. & T30-7W, betwn. C.C. & Section Corner.  
Found - GLO Brass Cap Mkd: AP & BT's. as follows:

97

1918  
18", now 24" Fir S.37°W. 20.5 ft., shows very good scar  
& in good condition.

5", now 9" Y. Pine N.1°W. 9.2 ft., shows scribe on unhealed  
scar. Tree is now dead due to porcupine damage.

New BT: 8" D.Fir N.5°E. 12.3 ft. Mkd: AP CS BT (5 ft. off ground).

Note - This corner lies approx. 103.0 ft. E. of corner of S 6/S 5  
on south boundary of Section 31, T30-7W.

"AP" Brass Cap is set in rock mound at foot of overhanging  
rock bluff approx. 30.0 ft. high.

June 23, 1965

Vernon R.  
Tracy  
&  
Crew  
June, 1965  
C.S.  
File  
No. 53/40

1/2 Section Corner to Sections 29 and 28.

98

Found - Stone 12x11x5", badly chipped, no marks. Recorded to be  
12x12x10".

Orig. 10", now 11" Laurel N.70°E. 14.5 ft., turned out  
& dead, upper scar badly rotted, lower scar healed  
over. Open & find "BT" & axe notch.

Only a hole where other BT. should have been.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965  
T30S 1/2 S 29/S 28 R7W.

New BT's: 6" Hemlock N.22°E. 5.5 ft. Mkd; 1/2 S28 CS BT.

14" B. Fir N.68°W. 17.0 ft. Mkd: 1/2 S29 CS BT.

Note - Corner lies 50.0 ft. West of top of bluff 75.0 ft. high.

1/2 Section Corner to Sections 30 and 31.

99

Found - GLO Brass Cap at Corner, 1918.

Orig. 50", now 56" Y. Pine N.10°E. 118.8 ft., unhealed scar  
shows "S30 BT". Tree appears to be dying.

Orig. 18", now 23" Live Oak S.54°E. 117.5 ft., shows good  
scar.

Due to Pine Tree condition & dense brush, we mark New BT:

New BT's: 11" D.Fir S.11°E. 11.4 ft. Mkd: 1/2 S31 CS BT.

14" Y. Pine N.17°W. 10.3 ft. Mkd: 1/2 S30 CSBT.

Note - This corner lies on east slope of rolling bench approximately  
100.0 ft. West of small, dry creek bed.

Section Corner to Secs. 32 & 33 only.

100

Found - GLO Brass Cap in Mound of Stones.

Orig. 6", now 7" W.Oak N.87°E. 130.0 ft., rotted, no scribe fd.

Orig. 30", now 30" Pine N.59°W. 75.2 ft., now snag, shows  
"T30SR7W S32 BT".

New BT: 10" B.Oak N.25°E. 128.6 ft. Mkd: T30S R7W S33 CS BT.

Note - This corner lies on top of bluffs approximately 250 ft.  
East of W. C. to Sections 4 & 5, T31-7W.

South 1/2 Corner Section 32 only, T30-7W.

101

Found - GLO Brass Cap, 1918.

Orig. 16", now 16" B.Oak N. 9°W. 35.0 ft., down & dead  
& rotted, shows "S32 B" scribe.

Orig. 24", now 36" Y. Pine N.11°E. 53.5 ft., shows scar,  
tree alive, we do not open.

New BT: 9" D.Fir N.46 1/2°W. 11.8 ft. Mkd: 1/2 S32 CS BT.

Note - This corner lies 162.4 ft. E. of N. 1/2 of Sec. 5, T31-7W.

North 1/2 Corner Section 5, T31-7W.

102

Found - GLO Brass Cap, 1918.

Orig. 7", now 9" B.Oak S.38°E. 5.9 ft., open & find "S"  
scribe. Tree is dying.

Orig. 24", now 24" B.Oak S.66°W. 26.4 ft., dying, shows scar.

New BT's: 12" D.Fir S.24°E. 20.6 ft. Mkd: 1/2 S5 CS BT.

13" B.Oak S. 5°W. 26.2 ft. Mkd: 1/2 S5 CS BT.

Note - This corner lies 162.4 ft. W. of S. 1/2 Cor. Sec. 32, T30-7W.

RE-RENEWED, SEE CORNER NO. #131  
RE-RENEWED, SEE CORNER NO. #136  
RE-RENEWED, SEE CORNER NO. #135

Vernon "Ray" Tracy  
Mike Darby and Terry Connell  
July 1965  
C. S. File No. 53/40