

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 8 R. W. W. M.

1

SECTION CORNER BETWEEN SECTIONS 6 and 7.
Chained between S.E. corner and S.W. corner of section 6. Found remains of original post at 2658.3 ft. W. of S.E. corner and from this point found a stump of an 84" Fir and rotten remains of a Fir stump standing up about 18" above ground. The 84" Fir stump bore $3.46^{\circ}W.$, 12.3ft. and the Fir (15"±) stump $N.52^{\circ}E.$, 12.0' indicating that this must have been the corner and these trees the original bearing trees. The bark of the big stump was mutilated so much that any bark blazes would have been destroyed. The stump showed tree to be cut sometime in 1943 or 1944. Chained W. 2832.9' to S.W. corner of section from this corner. Ran north from corner and found a blaze on a fir on both N. and S. faces about 350 or 400 ft. North and cut in and found it to have been cut or marked about 57 years ago. Found another blaze about 250 ft. further North. Set a new B.T.
A 60" Fir Stump $N.38^{\circ}E.$, 27.3 ft. marked in wood
S.6 C.S.B.T. (dist. to face of tree)
Used O.B.T. for other B.T. $3.46^{\circ}W.$, 12.3 ft. remarked on wood of tree.
Set 6 x 6 x 8" S. S. Rock for corner, cross on top.

A. Boyer C. S.
Witnesses
Joe Morgan
Howard Church
Lester Calder
"Don"
November 29, 1944.
April 1949
C.S. 40/192

SEC. COR. BET. 3-4 North TP. Line
Found O. B. T. S $52^{\circ} E$ 10.6 with scribe in bark.
Set 3" Yew post for Cor.
12" Fir S $13^{\circ} 30'$ W 23.7ft. mkd. B T S 4 T 20 S R 8 W 1581.

2

Section corner to secs. 12 & 13, (T 30 S, R 8 W) and secs. 7 & 18, (T30S, R7W).
Set a 1/2 inch iron rod from which bears:
A Fir, 26 inches, $N.56^{\circ}E.$, 14.5 feet - O. B. T.
A Fir, 10 inches, $S.75^{\circ}W.$, 25.6 feet - marked S 13, T30S, R8W., W. M.
A Fir, 14 inches, $N.59^{\circ}W.$, 29.0 feet - marked S 12, T30S, R8W., W. M.
A Pine, 8 inches, $S.25^{\circ}E.$, 41.6 feet - marked S 18, T30S, R7W., W. M.
March 11, 1955.

R. H. Gee
March, 1955.
C. S. File No. 41/385.

*Fd I.R. & 8/17/72
84m 100m
See 6/25*

Section corner to Sections 23, 24, 25 and 26.
Found Yew B. T. which is down. Reset corner from this B. T.
Set a 4 inch X 4 inch X 4 foot cedar post from which bears:
A Fir stump, 22 inches, $N.79^{\circ}W.$, 34.0 feet, marked S 23, T 30 S., R 8 W., W. M.
A Fir stump, 20 inches, $S.73^{\circ}W.$, 54.5 feet, marked S 26, T 30 S, R 8 W., W. M.
A Fir, 36 inches, $S.21^{\circ}E.$, 110.0 feet, marked S 25, T 30 S, R 8 W., W. M. A metal tag was placed on this tree.
A Fir 28 inches, $N.71^{\circ}10'E.$, 43.7 feet marked S 24, T 30 S, R 8 W., W. M.
The bark was removed from the stumps. Area in Sections 23, 24 and 26 have been logged. 8-14-58 - STEEL FENCE POST HAS BEEN PLACED AT CORNER - C.S. FILE No. 49/108

RE-NEWED CORNER NO. #114

4

1/2 sec. corner to secs. 27 - 34.
Set 3" x 3" x 36" D. Fir Stake from 1 O. B. T. (snag) (S.E. B.T. 12" D. F.)
Blaze and Scribe new B. T.s:
14" D. Fir, $N.56^{\circ}E.$, 35.0 feet, mkd. 1/2 S 27 - RE2741 B.T.
16" Sug. Pine, $S.54^{\circ}E.$, 11.8 feet, 1/4 S 34, RE2741 B. T.
June 24, 1955.

A. E. Evans
Work for Martin Box Co.
C. S. File No. 42/21.

Section corner to secs. 26, 27, 34 and 35.
Set a 4" x 4" x 36" Cedar Stake.
Blaze and scribe 4 B. T.s:
A 46" D. Fir, $N.84^{\circ}E.$, 75.1 feet mkd. T 30 - R 8, S 26 - RE 2741 - BT.
A 30" D. Fir, $N.43^{\circ}W.$, 19.5 feet mkd. T 30 - R 8, S 27 - RE 2741 - BT.
A 24" D. Fir, $S.19^{\circ}W.$, 19.6 feet mkd. T 30 - R 8, S 34 - RE 2741 - BT.
A 33" D. Fir, $S.42^{\circ}E.$, 80.7 feet mkd. T 30 - R 8, S 34, - RE 2741 - BT.

5

June 6, 1955.