

Douglas County Surveyor's Record of  
Government Corners Renewed

30 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 22, 23, 26, & 27. 17  
 Found - Fir Tree, now 33" N.26°W. 16.5 ft. This tree was bark scribed. Could see scribing "S R8W S2 BT". Rescribe this Tree in bark "T30S R8W S22 CS BT."  
 Fir Tree, now 21" diam. N.63°E. 24.4 ft. Upper scar has been opened, nearly grown over, but can see portions of scribing. Did not rescribe.  
 Fir Snag, now 18" diam. S.57°E. 13.9 ft. Upper Scar has been opened & scribing "8W S26" is visible.  
 Fir, down & dead, 5" diam., S.61°W. 14.5 ft. Both scars are open & show almost no growth since being blazed, scribing, "R8W S27 BT" is still visible.  
 At Corner Set Iron Pipe with Brass Cap Mkd: "County Surveyor's Office, 1958 T30S R8W  $\frac{S22}{S27} \frac{S23}{S26}$ "  
 Blaze & Scribe: 20" Doug. Fir S.32°E. 40 ft. T30S R8W S26 CS BT.  
 18" Doug. Fir S.57°W. 31.8 ft. T30S R8W S27 CS BT.

James W. Byron, Deputy  
Milo Godfrey  
S. A. Blilow  
Sept 3, 1958  
C. S. File No. 49/108

Closing Corner to Sections 5 & 6, T30S R8W, & Sec. 32, T29S R8W. 18  
 Found - Orig. 14", now 26" Hemlock N.21°E. 21.1 ft., previously opened face shows good scribing "S32 T29S R8W".  
 Orig. 36", now 46" R.Fir S.30°W. 25.1 ft., shows good bark scribing.  
 Remains of Cedar Stump that checks bearing & distance for Orig. S.E. BT.  
 Set Brass Cap at Corner Mkd:  $\frac{CC}{S} \frac{S32}{S6} \frac{T29S}{S5} \frac{R8W}{T30S}$  County Surveyor's Office, 1958  
 New BT's: 7" Hemlock bears S.26½°E. 33.1 ft. scribed T30S S5 R8W CC CS BT.  
 4" Cedar bears S.11°W. 43.1 ft. scribed S6 CS BT.

James W. Byron, Deputy County Surveyor  
Chairmen: Milo Godfrey  
S. A. Blilow  
October, 1958  
C. S. File No. 49/100

Corner to Section 6, T30S R8W, & Sections 31 & 32, T29S R8W. 19  
 Found - Orig. 15", now dead, 24" Hemlock N.33°E. 17.2 ft. I open & find good scribing "BT".  
 Orig. 30", now 30" partly rotted Fir Snag S.50°E. 2.0 ft. I find Stump Holes that check bearing & distance for S.W. & N. W. BT's.  
 Drove ¾" x 30" Rod at Corner.  
 New BT's: 12" Hemlock bears N.2°W. 79.0 ft. scribed S31 T29S R8W CS BT.  
 16" Hemlock bears S.61°W. 38.5 ft. scribed S6 T30S R8W CS BT.  
 Note: Sketch in file shows exact location of Corner.

Corner to Section 6, T30S R8W, and Section 31, T29S R8W. 20  
 Found - Orig. 15", now 24" Stump previously opened, shows good scribing "BT".  
 Stump Hole that checks bearing & distance for Orig. S.W. BT.  
 Set Brass Cap at Corner Mkd:  $\frac{1}{4} \frac{S31}{S6} \frac{T29S}{T30S} \frac{R8W}{R8W}$  County Surveyor's Office, 1958  
 New BT's: 15" R.Fir bears N.37°E. 39.3 ft. scribed S31 ¼ CS BT.  
 22" R.Fir bears S.22°E. 47.3 ft. scribed ¼ S6 CS BT.

FD 1976 BLM  
SEE GIS FILE

Section Corner to Sections 4 & 5, T30S R8W, & Secs. 32 & 33, T.29S. R8W. 21  
 Found - Scribed Stake Set by Boyer, 1939. c.s. 16/25  
 Orig. Cedar, now 32", this had been chopped open to expose scribing "T30 R8W S5" can be plainly read.  
 Orig. Laurel, now 24", bears N.46°W (instead of N.50°W) 19.9 ft. Center has entirely rotted away, but was rescribed by Boyer, scribing "S32 29S R8W CS & T" can be plainly read.  
 No trace found of other 2 Orig. BT's.  
 30" Fir N.4½°E. 25 ft. bark scribed "S33 T29S R8W CS BT"  
 60" Fir S.9°E. 50 ft. (on slope) bark scribed "S4 30/8 CS BT."  
 All distances measured from face of blaze.  
 Set Iron Pipe at corner with Brass Cap Mkd: "County Surveyor's Office, 1958  $\frac{T29S}{S32} \frac{R8W}{S33} \frac{R8W}{S5} \frac{R8W}{S4}$ "  
 Blaze & Scribe 7" White Fir N.36°W. 39.6 ft. Mkd. "T29S R8W S32 CS BT".

James W. Byron  
Milo Godfrey  
S. A. Blilow  
October 29, 1958  
C. S. File No. 49/100

c.s. 16/25