

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

John M. Powell
& Crew
C.S. File No
53/67

801
1/4 Corner to Sec. 36, T30-8W. and Sec. 1, T31S. R8W. 97
Found = 4 X 4 Post at 1/4 Corner, See Ren. #7.
6", now 8" W. Fir, N.31°E. (Rec. N36E) 21.8 ft., open for scribe "BT".
16", now 19" D. Fir, S.24°W. 18.1 ft., no scribe visible on face.
I do not find original pines, as notes. Do find Pine Stob S.25°E. 14.9 ft.,
(Record 11.9 ft.) This stob badly burnt & decayed.
No trace of N.E. Bearing Tree., burn in area very old, doubt orig. evdn
Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 8 W (ever found
Office 1/4 S 36
1971 S 1
T 31 S

Reblaze & Rescribe: 19" D. Fir S.24°W. 18.1 ft. scribed "1/4 S 1 CS BT".
3/31/71

JAN. 1972

John
Powell
&
Crew
C.S. File
53/67

1/4 Corner to Sections 21 and 28. 98
Found - 12", now 22" D. Fir, N. 20° E. 17.8 ft., faint
bark scribe visible "1/4 "T".
5", now 11" Chinquapin, S. 62° W. 5.3 ft.,
opened for reverse scribe.
Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R8W
Office 1/4 S 21
1972 S 28

New BT's: 11" W. Fir S.13° E. 27.3 ft. scribed "1/4S28 CS BT".
8" W. Fir N. 2° W. 27.4 ft. scribed "1/4S21 CS BT".
6/1/72

Fd BC # 3
BTS. 1976
BLM ADMIN
SURVEY
SEE GTS
FILE

James W.
Byron, Dep.
S.A. Bilow
C.S. File
No.
49/100

801
Sec. Cor. to Secs. 1 & 12, T30-9 & Secs. 6 & 7, T30-8. 99
Found - All 4 Orig. BT's. check bear. & dist.
24", now 36" Fir Snag, S.55°W. 29.7 ft., good bark scribing.
9", now 26" W. Fir S.45°E. 36.3 ft., good bark scribing
above & good scar below.
24", now 40" Fir Stump, shows good scar near base.
24", now 36" Fir, N.53°E. 16.5 ft., now down.
Set-Brass Cap at Cor. Mkd: County Surveyor's R9W T30S R8W
Office S 1 | S 6
1958 S 12 | S 7

New BT's: 9" W. Fir S. 8°W. 38.0 ft. scribed S12 T30S R9W CS BT.
8" W. Fir S.67°E. 15.5 ft. scribed S7 T30S R8W CS BT.
8" W. Fir N. 27-1/4°E. 27.3 ft. scribed S6 T30S R8W CS BT.
16" W. Fir N.36°W. 45.0 ft. scribed S1 T30S R9W CS BT.
N 25 1/2° E Per CS 49/100 July 9, 1958

John M.
Powell
& Crew
C.S. File
No. 54/38

801
South 1/4 Corner Section 36, T29-8W. 100
Found - C.S. Brass Cap set in 1967, out of position,
due to logging, See Ren. #83.
6", now 7" W. Fir, N.4°E. 31.2 ft., shows good scar.
15" Cedar, now high stump, S.11°E. 20.2 ft. scribe vis.
Reset Brass Cap at 1/4 Corner.
New BT: 11" Cedar N.89°E. 112.2 ft. scribed "1/4 S36 CS BT".
7/5/72

JAN 1972

Moore Mill & Lumber
By Shaner Engineering
M 49 - 16
March 19, 1973

801
1/4 Corner Sections 17 & 18. 101
No original evidence found
Set - Brass Cap mkd. T30S, R8W, WM, 1/4 S S18, S17, 1973.
New BT's - 22" D. Fir, scribed "1/4 S17 BT.", bears N.14°E., 8.8 ft.
14" D. Fir, scribed "1/4 S18 BT.", bears N.29 1/2°W., 6.3 ft.
Note - A well marked North-South property line runs 7.0 ft. West
of this corner.

Center 1/4 Corner Section 18. 102
Set - Brass cap mkd. Sec. 18, T30S, R8W, WM C 1/4, 1973.
New BT's - 8" D. Fir, scribed "C 1/4 S18 BT", bears N.85°W., 4.0 ft.
10" D. Fir, scribed "C 1/4 S18 BT", bears S.75°E., 9.2 ft.
3/19/73

~~1/4 Corner Sections 13 & 18.
Found - 1" iron pipe set by Johnstone. Ren. No. 31.
10" Orig. W. Oak, now down and rotted, bears S.35°W., 45.5 ft.
12" Orig. W. Oak, now down and rotted, bears N.42°E., 23.8 ft.
16" D. Fir, bears S.43°W., 39.6 ft. (Record 40.0 ft.)~~