

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30 T. S. R 8 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

128

1/4 Corner for Sections 35 and 36.

Found - Orig. stone marked "1/4 on west side. Since bearing and dist. to remaining orig. BT did not fit well & because the dirt under the stone was covered with leaves and needles which were not even rotted, I decided the stone was not in its orig. position. The proper position of the corner bears N.8°E 5.0 ft. from the found position of the stone.  
Fd. orig. 5" now 30" Pine which had recently been cut into showing scribe marks: S visible. This tree barber chaired sometime after it was cut into, leaving a 12'-15' stump. Tree bears East 25.1 ft. from found position of stone instead of S.80°E., 23.8 ft. (Record)  
Set - At record bearing and distance from orig. BT (N.80°W., 23.8 ft.) I set a 2 1/2" x 30" I.P. with brass cap stamped: Douglas County Surveyor 1981 T30S R8W 1/4 S35 S36, 26" into the ground and place orig. stone along side.  
New BT's- 20" Pine scribed 1/4 S36 CS BT in double blaze bears S.29°E., 11.5 ft.  
20" Pine scribed 1/4 S35 CS BT in double blaze bears N.68°W., 7.3 ft. All three trees have DCSO BT tags.  
Note: The found stone had a visible line on it showing where it had been buried in the ground years back.

Gregory Quibell  
Deputy, Doug. Co.  
Surveyors Office  
Witness:  
D. Stewart  
Feb. 19, 19

2/19/81

129

1/4 Corner for Sections 22 & 23.

Found - 1965 Brass Cap, properly marked & firmly set 12" above the ground. Ren.# 72.  
26" Chinquapin (orig. 12"), now dead, bears N.56°W., 29.7-ft. to face. Tree has rotted blaze; no scribing visible.  
Orig. 20" Fir, now very badly decayed & buried under several down trees; unable to get good bearings & dist.  
10" Fir (orig. 9"), bears S.35 1/2 °E., 58.4-ft., Ren.# 117. with scribe marks 1/4 S23 CS BT visible in open double blaze...this tree will be removed by road construction on 7-10-81.  
11" Fir (orig. 9"), bears S.42°W., 88.1-ft., with scribed 1/4 S22 CS BT visible in open double blaze. Ren.# 117.  
14" Fir down and rotten (stump hole bears East, 12.5-ft.) scribed 1/4 S23 CS BT visible in open double blaze. Ren.#72.  
12" Fir down & rotted (stump hole bears S.68°W., 14.3-ft.) with healed over double blaze visible. Ren. # 72.  
New BT's - 20" Cedar bears N.78°E., 99.4-ft., scribed 1/4 S23 CS BT in double blaze.  
11" Fir bears N.82°W., 18.4-ft., scribed 1/4 S22 CS BT in double blaze.

Gregory Quibell  
Deputy, Doug. Co.  
Surveyors Office  
Witness:  
Debbie Stewart  
July 9, 1981  
C.S. 61 / 27  
Declination:  
19°E

FD OK - 9/96 - Debrout - M125-51 7/9/81

130

Center 1/4 Corner of Sec. 36.

Set - 5/8" x 36" I.R., & Aluminum Cap, marked: LS 498.  
New BTs- 7" Fir bears N.72°E., 15.1-ft.  
8" Fir bears S.85°W., 25.4-ft. 12/18/81

Howard Johnstone  
For: Rsbg.Lmbr  
December 18, 1  
M 89-79

131

1/4 Corner for Secs. 27, & 26.

Found N O evidence of the orig. corner.  
Set - 5/8" x 36" I.R. & alum. cap at midpoint, mkd: LS 498.  
New BTs- 6" fir bears S.40°E., 13.5-ft. (scribed).  
12" fir bears N.49°W., 45.4-ft. (scribed). 6/30/82

Howard Johnstone  
LS 498

1/4 Corner for Secs. 26, & 35.

Fd. - 36" fir stub with cruiser marks & remnants of tag. Did not find scribing - dirt has been pushed against tree from fire trail through corner. Other BT falls in fire trail, and is gone. Location is consistent with our records of R.H. Gee's 1949 survey when both BTs were found.  
Set - 5/8" x 36" I.R. & alum cap S.37°E., 13.9-ft. from fir stub (OBT) cap mkd: LS 498).  
New BTs- 6" fir bears S.34°E., 2.8-ft. (scribed)  
5" fir bears N.17°E., 15.1-ft. (scribed). 6/30/82

For: Rsbg.Lmbr.Co.  
June 30, 1982  
M 92 - 52

FDOK  
DEdwards  
2/2005 CS65/55-1  
set 6" steel post  
2' West

#151