

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30 T. S. R 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

138

1/4 Corner for Section 13: and Section 18 of T.30-7  
 Found - A 1962 DCSO 2 1/2" dia. brass cap on a 1 1/4" O.D. iron pipe, protrudes 14" above ground. Cap is erroneously stamped with reverse ranges. Ren. #33  
 11" now 24" dia. D. fir with a previously opened blaze scribing visible "4S" bears S.44°E., 15.8 ft. (agrees with record) Original BT.  
 10" now 13" dia. madrone snag, no blazes or marks, is tagged with a yellow PLM tag (15.2 fto dist., N.26°E., T30S R8W S13 posted by CS 7/62) We open tree in two places, no blazes or scribing found. A cat road running NW-SE is along westerly side of tree. This tree has been recorded as an orig. BT in previous records. We have some doubt about it being original, tree bears S.23°W., 15.2 ft.  
 7" now 7" dia. D. fir with a partially healed single blaze scribing visible "1/4 S13 BT" bears N.77 3/4°W., 4.6 ft. (rec. N.80°W., 4.3 ft.) 1987 BLM D. resurvey BT.  
 Set - Erroneously stamped ranges are stamped out and correct marks are added to brass cap. Cap now reads: COUNTY SURVEYORS OFFICE  
 R T 30 S R  
 8 S13 | S 18 7  
 W 1/4 1962 W  
 New BTs - 9" dia. D. fir double blazed and scribed "1/4 S13 CS BT" bears N.33°W., 12.0 ft.  
 7" dia. D. fir double blazed and scribed "1/4 S18 CS BT" bears N.52 1/2°E., 4.4 ft.  
 Corner lies at the edge of a NE-SW cut line.

2/2/90

139

Condition Report Only  
 Sec. cor. 21, 22, 27 & 28 previous ren.# 57  
 Mon. Fd.- 1" iron pipe by Tracy in 1965 firmly set projecting 7" above the ground with a 2 1/2" brass cap.  
 Bt's Fd.- 10" rotted fir stump, bears N.33°E.  
 22" D.Fir, bears S.25°W. 18' with a healed blaze.  
 Root Hole, bears N. 11°W. 11.9' with uprooted 33" Fir alongside.  
 Root Hole, bears S.25°E. 16.6' with an uprooted 18" D.Fir stump alongside with scribe marks visible.  
 Root hole, bears S.13°E., 35.6' with a rotted 7" Cedar alongside.  
 Root hole, bears S.82 1/2°E., 37.3' with a partially uprooted 10" fir stump laying upside down and alongside.  
 Root hole, bears N.36 1/2°W., 30.4' with an uprooted 30" D.Fir alongside with scribe marks "T30S R8W S21 BT" visible.

RENEWED, SEE CORNER NO. #141

140

Center 1/4 Cor. Sec. 22  
 Mon. Set- 5/8"X30" iron rod 26" in the ground with plastic cap "BTS Eng-Surv".  
 New Accessories -  
 12" D.Fir, bears S.28°E., 10.2', scribed "C 1/4 S22 BT".  
 8" D.Fir, bears N.73°W., 11.3', scribed "C 1/4 S22 BT".  
 5/8"X30" Iron rod w/ plastic cap "BTS Eng-Surv.", bears N.28°W., 20'.  
 5/8"X30" Iron rod w/ plastic cap "BTS Eng-Surve.", bears S.73°E., 20'.

Douglas County  
 Surveyors Office  
 Randall Smith  
 Steven Flause  
 Feb. 2, 1990  
 C.S. 64/5

Kristian DeGroot  
 Sept. 1996  
 M 125-51