

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 9 R. W. W. M.

1/4 Section Corner to Sections 2 & 11.

Found - Orig. 20", now 24" Cedar Snag N.5°W. 27.7 ft., exposed scribing "1/4".

Also find root section of Cedar that checks bearing & distance for Orig. South BT.

Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S 2 T30S R9W County Surveyor's Office, 1958

New BT's: 20" Cedar bears N.46°W. 13.2 ft. scribed $\frac{1}{4}$ S 2 CS BT.

12" R.Fir bears S.10°E. 14.0 ft. scribed $\frac{1}{4}$ S11 CS BT.

Ed. OK. 1/12/74 B. Shaner M 49 - 51

J. Byron
S. Below
July 9, 1958
C.S. File No. 49/100

RENEWED, SEE CORNER NO. 185
WILL
See Also same day, MME(s.) M-7

Township Corner T30S-T29S, R9W-R8W.

Found - S. Pine Tree, now 45", at Twp. Corner.

S. Pine, now 45" N.80°E. 3.3 ft.

D. Fir, now 25" diam. S.88°W. 18.5 ft. Cut into this tree to expose part of upper blaze. Find good scribing "W" & "S 36".

Fir Stump, now 40" diam. N.50°W. 48.2 ft. Opened lower scar but found only charred face.

Remains of badly rotted Laurel Stump S.10°E. 46.2 ft.

Set Brass Cap 10 ft. North of true Corner for Witness Corner Mkd:

T29S
R9W $\frac{S36}{S11}$ | $\frac{S31}{S6}$ R8W "County Surveyor's Office, 1958
W. C. Corner 10 ft. S.

Blaze &

Scribe: 16" D.Fir S.49 $\frac{1}{2}$ °W. 27.5 ft. mkd; "T30S R9W W.C. S 1 CS BT".

24" D.Fir N.60° W. 32.6 ft. mkd; "T29S R9W W.C. S36 CS BT".

45" S.Pine(N.E. BT. for True Cor.) S.25°E. 10.0 ft.

Mkd: "T30S R8W W.C. S 6 CS BT".

19"W. Fir N.73°E. 33.4 ft. mkd: "T29S R8W W.C. S31 CS BT".

Ed. OK By RAMBO 7/03 M 142-69

Section Corner to Sections 11, 12, 13, & 14.

Found - Incense Cedar, now 26" diam., N.45°E. 1.3 ft. Chopped out lower blaze & found scribed "BT" in perfect condition.

Ring count proves it to be original scribing. **FD OK on 2002**

Shattered Remnants of a Fir Stump(Approx. 30" diam.) bears S.40°W. 6 ft. **Bill Resorby 21071**

No Trace of other two bearing trees could be found.

Set Brass Cap at Corner Mkd: $\frac{S11}{S14}$ | $\frac{S12}{S13}$ T30S R9W County Surveyor's Office, 1958

Blazed & Scribed new BT's as follows:

25" Incense Cedar, S.39°W. 43.2 ft. "T30S R9W S14 CS BT"

23" Incense Cedar, S. 6°E. 31.9 ft. "T30S R9W S13 CS BT."

16" W. Fir N.13 $\frac{1}{2}$ °W.33.5 ft. "T30S R9W S11 CS BT."

10
FD OK 6/88 H. JOHNSTONE M 106-51
FD OK G Smith 10/2006 M 151-57
James W. Byron, Deputy County Surveyor
M. Godfrey
S. Below
July 17, 18, 1958
C.S. File No. 49/100
SW Stump & W.C. (S)

Section Corner to Sections 1, 2, 11, & 12.

Found - Hub with Tack at Corner

Dead Cedar, now 14" diam. S.25°W. 6.6 ft. This has been chopped open & scribing "30S R9W 2" visible. Chopped out lower scar & found face had rotted before growing over.

Tree has grown so slowly that rings are too fine to count.

White Fir Snag, now 25" diam. N.85°W. 13.9 ft. Bark

Scribing "T30 R9W S2" visible. Portions of letters widely separated showing considerable growth since being scribed.

Rotted Remnants of Large Fir Stump N.5°E. 13.2 ft.

Stump Hole to S.W. which fits bearing & dist. for old BT. in Sec. 11.

Set Brass Cap at Corner Mkd: $\frac{S2}{S11}$ | $\frac{S1}{S12}$ T30S R9W County Surveyor's Office, 1958

New BT's: 14" D.Fir S.88 $\frac{1}{2}$ °W 23.1 ft. scribed "T30S R9W S11 CS BT"

11" I.Cedar S.66°E. 32.5 ft. " "T30S R9W S12 CS BT".

44" D.Fir N.85°E. 18 ft. scribed "T30S R9W S 1 CS BT".

5" I.Cedar N.14°W. 31.5 ft. " "S2 CS BT".

RENEWED, SEE CORNER NO. 38

11