

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T.S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

Section Corner to Sections 14 - 15 - 22 - 23.

32

Found - Orig. 36", now 40" Down Fir S.65°W. 15.8 ft., shows good bark scribing on section cut from tree.

Orig. 6", now 22" W. Fir N.60°W. 13.9 ft., shows bark scribing. No other Orig. Bearing Trees found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963

CHECKED
FOUND O.K.

New BT's: 7" W. Fir bears N.63°E. 21.4 ft. scribed S14 T30S R9W CS BT.

14" Hemlock bears ~~EAST~~ ^{EAST} 39.0 ft. scribed S23 T30S R9W CS BT.

Rescribed 22" W. Fir N.60°W. 14.8 ft. scribed S15 T30S R9W CS BT.

11" W. Fir bears S.18°W. 66.1 ft. scribed T30S R9W S22 CS BT.

James W. Byron
& Crew
June 19,
1963
C.S. File
No. 49/100

Corner of Secs. 31 and 32, T30-9W. & Secs. 5 and 6, T31-9W.

33

Found - Original Stone at Corner.

Orig. Fir, 30", N.44°E. and the Fir, 30", S.22°E. are both snags.

Orig. Fir, 34", S.21½°W. is now a short stub, badly decayed.

No evidence of the Original 8" Fir.

I drive a 1½" Pipe at the South Side of the Orig. Stone & Scribe:

8" Doug. Fir S.60°W., 34.4 feet., "S6 B.T. 473".

10" Oak S.5½°E., 20.4 feet., "S 5 B.T."

Forest LaFlamme
For Georgie Pacific Corp.
August 12, 1963
C. S. File No. 51/265

North ¼ Corner of Section 6, T31S. R9W.

34

Found - Orig. Stone with the chisel marks faintly showing.

Orig. Fir, 15", S.40½°E. is now 30" in diam. & is plainly scribed.

Orig. Hemlock B.T. is gone. I scribe:

White Cedar, 9", N.22°W., 26.3 feet, "¼ S31 B.T."

¼ Corner to Sections 25 and 26.

35

Found - 24" Fir, now 38", N.19°W. 21.1 ft., bark scribe visible, Tree blown down.

New Bearing Trees:

11" W. Fir S.14°W. 78.6 feet.

8" W. Fir S.75°E. 70.5 feet.

Note - Corner falls in west edge of 12 Mile Creek so no Pipe was set.

Howard W.
Johnstone
For Rsbrg. Lumber
May 28, 1964
C. S. File No.
51/163

¼ Corner to Sections 2 and 3.

36

Found - 1" x 30" I. Pipe called for in Ren. No. 21.

8" Cedar N.23°W. 13.0 ft.

12" Fir is down.

New BT's: 20" D. Fir S.28°E. 66.6 ft. Mkd: ½ S 2 CS BT.

Note - This corner lies about 6.0 ft. S. W. of old logging spur.

¼ Corner to Sections 9 and 16.

37

Found - Both Orig. BT's.: W. Oak, now snag, 16" diam. S.27°E.

19.8 ft., no scribe left on rotted face.

D. Fir (Alive & burned) 21" diam. (called for 24" Orig.)

N.40°W. 13.2 feet.

Ren. No. 4 - Epstein's 1931 BT's., both down & rotting, no sign of Rock.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

New BT's: 14" B. Oak S.21°E. 35.0 ft. Mkd: ¼ S16 CS BT.

11" D. Fir N.51°E. 28.3 ft. Mkd: ¼ S9 CS BT.

Vernon R. Tracy
Mike Darby
July 27-31, 1964
C. S. File No. 53/53

Section Corner to Sections 1 - 2 - 11 - 12.

38

Found - Brass Cap & I.P. in good condition. See Ren. No. 11

All Orig. BT's. completely destroyed by fire, renewal BT's. marked in 1958, dead & scribe burned off all except,

44" D. Fir N.85°E. 18.0 ft. and 5" Cedar N.14°W. 31.5 ft.

New BT: 9" Cedar N.37½°W. 184.7 ft. Mkd: T30S R9W S 2 CS BT.

Note - This corner lies on S. W. slope approx. 100.0 ft. above small creek.