

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

Section Corner to Sections 13 - 14 - 23 - 24. 101

Found - 1" Iron Pipe, ~~under~~ 28" of earth still standing upright.
Set Brass Cap directly over Iron Pipe, See Ren. #19.

25" D. Fir, now stump, N. 52°W. 38.4 ft., shows BT. scar and parts of bark scribe.

23" Cedar, now 23", N. 71°E. 15.8 ft., shows scar (slight)

16" W. Fir, now stub, S. 73°E. 46.8 ft., scribe visible.

6" W. Fir, now 7", S. 15°W. 47.3 ft., scribe visible "R9W".

Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 9 W
Office S 14 | S 13
1970 S 23 | S 24

New BT's: 11" D. Fir N. 44°W. 53.0 ft. scribed T30S R9W S14 CS BT.

8" W. Fir S. 75°E. 51.4 ft. scribed T30S R9W S24 CS BT.

9/10/70

1/4 Corner, Secs. 35 and 36. 102

Found - 1964 D.C.S. Brass cap in place.

Stump of orig. BT only. Ren. No. 49

Both Ren. BT's gone due to logging.

New BT's - 8" W. Fir, S. 10°E., 23.6 ft. mkd. "1/4 S35 CS BT"

8" W. Fir, S. 33°W., 56.1 ft. mkd. "1/4 S35 CS BT."

Note - This cor. lies on south slope approx. 125.0 ft. north of creek bottom. Creek course east.

7/24/73

1/4 Cor. Secs. 14 and 13. 103

Found - 1964 D.C.S. Brass cap in place. Ren. No. 52

20" Cedar, N. 73°E., 116.0 ft. Alive, good cond. scribe visible on unhealed blaze

BT to northwest was destroyed by logging.

New BT - 6" D. Fir, N. 20°W., 20.3 ft. mkd. "1/4 S14 CS BT."

7/19/73

1/4 Corner, Secs. 3 and 2. 104

Found - No trace of I.P. or Brass cap. Ren. No. 96

30" Fir stump, N. 34°W., 29.4 ft. RR spike driven in top.

28" Fir, stump, N. 7°E., 32.0 ft. RR spike driven in top.

Set - Brass cap mkd. County Surveyors T 30 S R 9 W #105
Office S 14 | S 13
1973 S 23 | S 24

Note - This cor. lies 4.0 ft. west of cat fire road. This area appears to have been burned again.

7/26/73

1/4 Corner for Secs. 3 and 2. 105

Found - 1973 County Surveyor's Brass Cap. Ren. No. 104

30" D. Fir burned stump BT, bears N. 34°W., 29.4 ft. RR spike driven into top of stump through burnt BT tag.

28" D. Fir, burned stump, bears N. 7°E., 32.0 ft. RR spike driven into top of stump through burnt BT tag.

10" D. Fir, scribes vis. tree now down, bears S. 75°E., 27.0 ft.

New BT's - 10" Cedar, scribed "1/4 S2 BT", bears N. 40 1/2°E., 87.5 ft.

12" Cedar, scribed "1/4 S3 BT" bears N. 88 1/2° W., 122.6 ft.

Center 1/4, Section 2. 106

Set - Brass cap mkd. T30S, R9W, WM C1/4 S2 1974

BT's - 6" D. Fir, scribed "C1/4 S2 BT", bears N. 40°E., 19.8 ft.

6" D. Fir, scribed "C1/4 S2 BT", bears S. 79°E., 34.6 ft.

John M. Powell
Penley & Heritage
C. S. File No.
53/53

MARCH 71

Vernon "Ray" Tracy, Surveyors Office
Jack Heritage
C.S. File 56/34
July, 1973

Shaner Engineering
for Moore Mill and Lumber Co. Bandon, OR
January 12, 1974
49 - 51

Fd. 800
9/12 Blm Admnd.
Survey 96
GTS File

RE-RENEWED, SEE CORNER NO. 169

RE-RENEWED, SEE CORNER NO. 184

RE-RENEWED, SEE CORNER NO. #105

RE-RENEWED, SEE CORNER NO. #146

Fd. ok 4/88
H. J. J. J. J.
#106-52