

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 S T.S. R 9 W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Shaner Engineering
for Moore Mill and Lumber, Bandon, OR
January 12, 1974
M 49 - 51

1/4 Corner for Secs. 1 and 2.
Set - Brass cap mkd. T30S R9W WM 1/4 S2 S1 1974.
BT's - 24" Cedar stump, scribed "1/4 S2 BT", bears N.13°W.,
66.7 ft.
36" D. Fir stump, scribed "1/4 S1 BT", bears S18°E. 94.0 ft.
Note - This corner is on a slide area and may move. The corner
also lies on an old road. No orig. evidence found.

RE-NEWED. SEE CORNER NO. 107

107

Section corner for 3, 2, 10 and 11.
Found - 30" Cedar, orig., down and burned with old face. Bears
S.12°E., 77.2 ft.
Stump hole for 30" Fir, orig., bears S.35°W., 124.7 ft.
Set - Brass cap mkd. T30S R9W WM S3, S2, S10, S11 1974.
Note - Corner area has been heavily burned several times, no
trees are within limits so I scribed an "X" on rocks
as follows:
X on 5' x 5' x 5' rock, bears S.54°W., 7.6 ft. to the X.
X on 4' x 4' x 3' rock, bears N.47°W., 6.3 ft. to the X.
X on 4' x 4' x 6' rock, bears N.16°E., 36.7 ft.
to the X.
X on 5' x 5' x 8' rock, bears S.58°E., 11.0 ft.
to the X.

108

Jan. 12, 1974

1/4 Cor. for Sections 7 and 18.
Found - 30" Fir stump, orig. BT, old face badly burned
bears N.15°E., 32.7 ft.
18" fir snag, orig. BT, scribe "T" vis. bears
S.87 3/4°W., 14.7 ft.
14" fir, marked as a corner tree, now gone.
New BT's - 10" cedar, scribed "1/4 S7 BT", bears N.22 1/2°W.,
18.8 ft.
10" D. Fir, scribed "1/4 S18 BT" bears S.3 1/2°W.,
44.2 ft.
Set - Brass cap mkd. T30S R9W, WM 1/4S S7, S18 1973.

FD BC OS BTs Thosteter
3/2008
MISS-26

109

Shaner Engineering
for Moore Mill and Lumber Co.
Bandon, Oregon
M 49 - 54
Feb. 4, 1974

Center 1/4 Corner, Section 18.
Set - Brass cap mkd. T30S, R9W WM S18 C1/4S 1974 from which a
6" D. Fir, I scribed "C1/4 S18 BT" bears N.48°E.,
35.5 ft.
6" D. Fir, I scribed "C1/4 S18 BT", bears S.61°E.,
37.2 ft.

Re-renewed #192

110

2/4/74

Gary Langlitz
County
Surveyors
Office
P. Earle
CS 56/49
4/16/74

1/4 Corner for Secs. 32 and 33.
Found - A stone, split, 14"x8"x6", with a "1/4"
chiseled on the East face (orig. notes call
for stone to be marked on west face.)
14", now 24" Fir snag, bears N.18°W., 27.1 ft.
showing well healed blazed. I do not open.
No trace of original NE bearing tree.
Set - Brass cap at corner point mkd:
COUNTY SURVEYORS T 30 S R 9 W
OFFICE S 32 | S 33
1974 1/4

111

Reset stone alongside brass cap.
New BT's - 10" hemlock, bears S.39 1/2°W., 15.6 ft.
scribed "1/4 S32 CS BT"
8" D. fir, bears S.22°E., 22.2 ft. scribed
"1/4 S33 CS BT"
Steel fence post alongside brass cap
Magnetic declination 20° east.

4/16/74