

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30 T. S. R 9 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21991

C O N T. - - - -

(Sec. Cor. 31,32; & 5,6 of T31-9)

126

A search is made for the original bearing trees. None are found.  
 Found - 1893 BT, a Fir, 30" now a 30" DBH 50 ft. tall D. Fir snag bears N.44°E., 42.9 ft. Tree has good evidence of burling around a rotted & burned blaze. No scribing visible.  
 1893 BT, A Fir snag, 30 ft. tall & 30" DBH, bears S.22 1/2°E., 43.2 ft. face measurement. No scribing or definite blaze marks are found but this tree agrees reasonable well with 1893 Fir, 30" bearing S.22°E., 42.9 ft.  
 1893 Fir, 34" now a rotted 30", 12" tall burned fir stump bears S.21 1/2°W., 32.3 ft. No blazes or scribe marks visible.  
 Northwest bearing tree, 1893, is searched for but not found.  
 Found - An 8" D. Fir, now a 12" DBH D. Fir bears S.60°W., 34.4 ft. Tree has a well healed single blaze. No scribing visible. #  
 A 10" Oak now a 12" DBH Chinquapin bear S.51°E., 20.4 ft. Tree has a partially healed single blaze with the scribing S5 BT visible. Ren. #33  
 Found monument position is accepted.  
 No other suitable bearing trees are available.  
 All found trees are tagged with DCSO bearing tree tags.

4/7/81

1/4 Corner for Section 32; and Sec. 5 of T.31-9

127

Found - 1967 County brass cap, properly marked, on a 1" I.P. firmly set & protruding 6" from ground. Ren. #95  
 1893 resurvey, a stone measuring 14"x10"x4" is deposited on top of ground & set on the east side of the B.C. Stone is marked 1/4 on its top side (rec. 1/4 on N. face).  
 A steel fence post protrudes 36" from the ground on the west side of the B.C. monument.  
 Possible remains of orig. southeast 18" Fir are found near record bearing & distance. No evidence of the other orig. bearing tree is found.  
 Found - 1893, A Fir 18" is now a burned D. Fir snag 18" DBH, approx. 35 ft tall bears S.34°E., 17.5 ft. face measurement (rec. S.33 3/4°E., 17.5 ft.) Tree has good evidence of burned blazes. No scribing visible.  
 1893, A Fir 30" now the remains of a large burned and rotted Fir stump bears N.14 1/4°W., 84.5 ft. No blazes or scribing apparent (rotted away.)  
 A D. Fir, 22" now a dead 26" DBH D. Fir bears S.10°W., 34.7 ft. (rec. S.12°W., 34.7 ft.) Tree has burned open blaze with no legible scribing. Ren. #94  
 A. D. Fir, 22" now a 38" DBH D. Fir dead, bears N.25°E., 13.5 ft. An opened blaze has the scribing 1/4 S32 visible. Ren. #94

Monument location is accepted as found.

New Accessories:

A boat spike in a 12" diam., 12" tall burlled fir stump bears N.06 3/4°W., 9.3 ft. Boat spike driven into the top of said stump is stamped BO 2.  
 A spike in a D. Fir stump 20" diam. and 21" tall bears S.59 1/2°W., 42.1 ft. Spike stamped BO 1.  
 A 8" DBH madrone bears N.16°W., 81.9 ft. and is bark scribed 1/4 S32 CS BT.

All accessories are tagged with DCSO BT tags.

4/7/81

Section corner for Secs. 3, 4, 9 and 10

Found - No evidence of original corner.  
 Set - 5/8" x 36" iron rod and aluminum cap marked "LS 498".  
 BTs - 3" willow, N.43°E., 2.8 ft.  
 4" fir, S.10°E., 35.5 ft.  
 4" fir, S.47°W., 17.7 ft.

No trees within reasonable distance in Sec. 4.

8/82

128

Stephen J. Flause, Deputy  
Douglas County Surveyors Office  
Witnesses: T. Plouff; K. Mosely  
April 7, 1981  
C.S. 61/19

RECORDED  
INDEXED  
4-10-82

Howard Johnstone  
For: Roseburg Lumber  
Aug. ,1982  
M 90 - 26