

Douglas County Surveyor's Record of
Government Corners Renewed

T 30

T. S.

R 9

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97551

Section corner for Secs. 1, 2, 11 and 12
CORNER REPORT ONLY

Found - 1958 County BCIP marked 2, 1, 12, 11
6" cedar, N.14°W., 31.5 ft. Now Down
16" cedar, N.37½°W., 184.7 ft. Healed
46" fir, N.85°E., 18.0 ft. Now stump, scribe visible.
12" cedar, S.66°E., 32.5 ft. Dead. Ren. #11

Ren. #38

143

Howard Johnstone
For: Roseburg
Resources
November, 1988
M 101 - 44

1/4 Corner for Sections 1 and 12

Set 5/8" x 36" iron rod and alum. cap marked 1/4 S1/S12
Scribed -24" fir, S.13°E., 19.8 ft. "1/4 S12 BT"
12" fir, N.2°E., 13.4 ft. "1/4 S1 BT"

144

177

1/4 Corner for Section 12; and Sec. 7 of T.30-8
CORNER REPORT ONLY (1988 BLM survey, not filed yet)

Found - 1988 CAD BCIP marked 1/4 S12/7
10" fir, N.12°W., 5.6 ft. scribe visible
12" fir, N.60°E., 20.8 ft. scribe visible.

145

11/18/88

1/4 Corner for Sections 2 and 3

Found - A 1973 DCSO 2½" dia. brass cap on a 1 3/8" O.D. iron pipe, leaning
1½ ft. south of plumb. Ren. No. 104

30" now 18" dia. 2 ft. high burnt and rotted D. fir stump, no boat
spike seen, bears N.34°W., 29.4 ft. (agrees w/rec. Ren. #96)

28" now 24" dia. 5 ft. high burnt and rotted D. fir stump, with
boat spike in top near center, boat spike bears N.7°E., 31.5 ft.
(Rec. N.7°E 32.0 ft.) Ren. #96

10" now 11" dia. tipped out to north, down and burnt cedar,
scribing visible "1/4 S BT" bears S.75°E., 27.0 ft. to remnants
of roots, (agrees with record, first noted in Ren. #105) source
unknown.

12" now 18" dia. cedar with a partially healed single blaze,
scribing visible "1/4 S3 BT" bears N.89½°W., 124.9 ft. (Rec.
N.88½°W., 122.6 ft.) Ren. No. 105

Northeast cedar BT from Ren. No. 105 is gone.

14" now broken, shattered, rotted remains of indeterminable size
near record bearing (N.70°E., 21.8 ft.) Possible orig. BT.

Set - Plumbed position of 1973 DCSO BC/IP is referenced, Iron pipe
measured 36" long. The stamping "RESET 1989" is added to brass
cap. BC/IP is returned to referenced position and now protrudes
6" above ground.

New BTs - 7" dia. D. fir double blazed and scribed "1/4 S3 CS BT" bears
S.7½°W., 35.9 ft.

7" dia. madrone bark scribed "1/4 S2 CS BT" bears S.59½°E.,
67.4 ft.

4" dia. D. fir double blazed and scribed "X BT" bears North, 43.1'

Corner lies along southwest edge of a dirt road.

12/11/89

147

Section corner for Secs. 31 & 32; and 6 & 5 of T.31-9

Found - 2½" dia. DCSO brass cap on 1½" o.d. I.P. protruding 18" above
ground. (Ren.#91). See Ren. # 126.

14" x 10" x 8" with 5 notches on east edge is found on top of
ground along west edge of DCSO BC/IP. (1893 Retracement Survey.)

1½" i.d. I.P. protruding 18" above ground found along SE edge of
DCSO BC/IP. (Ren. # 33)

Metal fence post along south edge of BC/IP

30" now 37" dia. 30 ft. high Douglas Fir snag w/previously
opened blazes, no scribing visible bears S.22°E., 44.5 ft.
(Rec. S.22°E., 43.2 ft., distance is a face measurement)

1893 BT

34" now decayed fir stump, no blazes or scribing visible, bears
S.21½°W., 32.3 ft. (agrees with record) 1893 BT

30" now 30" dia. 3 ft. high D. Fir stump with a fully healed
blaze bears N.44°E., 42.9 ft. (agrees w/Rec.) 1893 BT

8" now 14" dia. D. Fir with a fully healed blaze bears S.60°W.,
34.4 ft. (agrees w/Rec.) Ren. # 33

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Dec. 11, 1989
C.S. 64/3

Douglas County
Surveyors Office
Randall Smith
Ed Monrean
Sept. 21, 1992
C.S. 64/32