

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 T. S. R. 9 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

Mark Smalley
For; Roseburg Forest Pr.
M 119-18
Feb. 1994

154
1/4 Corner for Sections 30 & 31.
Found - 5/8" iron rod and original stone marked "1\4"
BTs - 18" Cedar, N.4 $\frac{1}{2}$ °W., 10.6 ft. rotten snag.
10" Fir, N.76°E., 3.2 ft. scribe visible.
50" fir, N.89 $\frac{1}{4}$ °W., 20.3 ft. scribe visible, original line tree.
notes call for it on line east of corner. Tree was faced and
scribed by GP survey.
Scribed-8" Fir, N.27°W., 9.7 ft. "1/4 BT"
8" Fir, S.41°W., 7.4 ft. "1/4 BT"

155
1/4 Cors. Sec. 3 & 4
Found - County Surveyors Brass Cap, 1.5' above ground. Ren. #26.
24" White Fir, bears N.75°57'E., 28.3'. Well healed scar w/tag.
29" Douglas Fir stump, bears N.21°03'E., 27.1'. Well healed scar
w/tag, no rec.
19" White Fir, bears N.27°05'W., 41.8'.
24" rotted stump w/tag along side bears N.26°53'E., 11.5'.
Corner lies on flat ground approx. 1 chain west of road & 1 $\frac{1}{2}$ chains east of
pond.

FD OK
D. Edwards
2-2005 M 147-17

156
Center 1/4 Sec. 4 Ren. #124
Set - 5/8"x30" rebar with 1 $\frac{1}{2}$ " aluminum cap which reads "LONE ROCK
TIMBER C 1/4 SEC 4" from Ron Stunztner's survey M 87-17
31" Douglas Fir, S.21°10'W., 6.9' to spike in face, we chopped out.
26" Cedar, bears N.89°57'E., (Rec. S89°E.) 37' to spike in face,
we chopped out.
30" Douglas Fir, bears N.42°W., 35.1' we scribe C 1/4 S4 BT & tag.
9" Hemlock, bears N.9°E., 43.3', we scribe C 1/4 S4 BT & tag.
Corner lies on a rolling benchy moderate westerly slope.

Ken Hoffine, L.S. #2291
For: Lone Rock Timber Co.
May 1994
M 119-30

157
Corner Secs. 3, 4, 9, & 10 Ren. #128
Found - 2" aluminum cap on a 5/8" iron rod
4" Willow bears N.43°E., 2.5', scribing visible w/tag.
12" Douglas Fir, bears S.42°W., (Rec. S.47°W.) 17.8', well healed
scar w/tag.
11" Douglas Fir, bears S.15 $\frac{1}{2}$ °E., (Rec. S.10°E. tag reads S.16°E.)
35.8', well healed scar w/tag.
Corner lies on a steep south-east slope approximately 200' at N.65°W., from
a road at a water pump chance. A metal fence post lies North 0.5' of the
corner.

158
1/4 Corner for Sections 27 & 28
Found -40" now 40" dia. 60 ft. high D.Fir snag with a previously opened
blaze on west side, scribing visible "48"-original corner tree.
-2 $\frac{1}{2}$ " dia. DCSO brass cap on a 1 $\frac{1}{4}$ " O.D. iron pipe protrudes 18"
above ground (1965) See renewal #71.
-Note: DCSO BC/IP set in error as orig BT noted in 1965 renewal
was the corner tree.
Accessories Found - (brg's & distances were taken to center of corner tree)
-40" now 36" dia. 20 ft. high burnt D.Fir snag no scribing visible,
bears S.3 $\frac{1}{2}$ °W., 77.9 ft. (rec. S.6°W., 77.9 ft.) orig. BT.
-36" now 36" dia. 15 ft. high D.Fir snag with scribing visible on
a opened blaze "1/4 S T" bears S.42 $\frac{1}{2}$ °E., 14.5 ft. (rec. S.54°E.,
15.8 ft. could be a slope measurement) orig. BT.
-1 $\frac{1}{4}$ " O.D. 17" high iron pipe with DCSO yellow plastic cap bears
N.56 $\frac{1}{2}$ °W., 16.9 ft. (rec. S.54°E., 15.8 ft. would be a distance
and brg. from I.P. to blaze) 1965 renewal.
Monument Set -Brass cap erroneously set in 1965 is sawed off and a yellow
DCSO plastic cap is set in I.P. Now protrudes 17" above ground.
New Accessories - Bearing & distances taken to center of corner tree.
-11" now 18" dia. D.Fir with a fully healed double blaze bears
N.52°W., 25.4 ft. 1965 BT CONTINUED NEXT PAGE

Douglas County
Surveyor's Office
Randall Smith
Stephen Flause
Dec. 19, 1994
C.S. File 64/52