

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 1 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 97196

Art Boyer - Surv.
Ted Schatterkerk - Witness
Sept. 1949

Art Boyer - Engineer
December 27, 1950
Witnesses
Geo. Henderson
Joseph Jenks
c. s. #0/298

Jno. H. Markham Jr.
Oct. 10, 1951
c. s. #11//

County Surveyors
Office-Jin Byron
& Ray Irving
July 27, 1953
Filed Drawer 45,
Envelope 176

Robert M. Thompson
July 29, 1956
C. S. File No.
42/252.

John H. Markham, Jr.
Stomar Lbr.
ct. 11, 1960
S. File 51/142

SEC. COR. 34-35

Found two orig. B.T.s. for this cor. the two maples, the one to the Northeast still alive and standing and the one to the Northwest still standing but showing signs of decay; found also the tree to the SE, a fir snag, and found the stump of the B. T. to the SW. This cor. applies to secs. 34-35 so marked a new tree to the Northwest only.

12" Maple N 46° 30' W 16 1/2 ft. scribed S 3/4 1581 B.T.
Cor. raised a mound of rocks 12" high and a 4" x 4" cedar post. Corner is in a shallow rocky draw which drains into a creek approx. 600 ft. N. Cor. is 80 ft. S of old phone line.

SEC. COR. 33-34

Found rock in place for this section corner; all four recorded trees are alive and all are as given in the recorded field notes except the 40" Fir tree which is recorded as being S 40° E 45 lks, which measures from the corner rock 36 lks. This tree is marked or scribed distinctly "S 3". It is in Section 4 and not 3. This corner is of course for Sections 33-34 and not for either 3 or 4.

SEC. COR. 7-12

Set by proportionate measurement.
For Corner marked (scribed) a 6" maple "S 7" and "S 12" "1581" and marked (scribed) a 4" maple tree in Sec. 12 "S 12 T 31 S R 2 W" "1581 BT" --
N 51 1/2° W 15 ft.
Scribed a 12" Fir "S 7, T 31 S, R 1 W, 1581 BT" N 48 1/2° E 15 ft.
See 40 file 298

N.W. 1/4 of Section 19

The approximate center of N.W. 1/4 of Section 19, as determined by the intersection of the old blazed cutting lines as I ran them 3 years ago.

At corner point I set a 1 1/4" x 30" Iron Pipe, from which a Cedar 6" in diam. bears N 11 E, 47.0 feet distant mkd. P.C. B.T.

This corner is only approximately correct since in my original survey I didn't find the North 1/4 corner of Section 19. The East - West center line of Sec. 19 was run and measured I also tied into the N.W. corner of Section 19

South 1/4 corner to sec 32. T 31-1

Found 18" iron pipe-checks old B.T. snag still standing-recorded as 18" cedar-should be 12" cedar.

Blazed and scribed

A 10" white fir-N.10°W., 16.5 ft. - Mkd. 1/2 S32 CS B.T.
A 30" cedar - N.70°E., 4.5 FT. - Mkd. 1/2 S32 CS B.T.

1/4 corner to secs. 19 and 20.

I find the 2 original bearing trees as described in original G. L. O. field notes, but both dead.

I renew by scribing new bearing trees:

16 inch D. Fir, N.19°40'W., 17.3 feet.
16 inch D. Fir, S.48°10'E., 14.9 feet.

1/4 Corner Secs. 7 & 8, as det. by O.B.T.

44" Dead Pine Snag bears N.35°E. 38.9 ft. dist. O.B.T., fd. scribe.

At Corner Point Set 1 1/2" x 36" Steel Shaft from which:

36" Pine S.46°E. 47.0 ft. dist. mkd. 1/2 S 3 T 31 S R 1 W B.T.
12" Fir S.53°W. 26.6 ft. mkd. 1/2 S 7 B.T.

12" Fir West 32.9 ft. mkd. 1/2 S 7 B.T.
10" B. O. N. 8°W. 71.5 ft. mkd. 1/2 S 7 B.T.

Road bears North 37.0 feet

RE-RENEWED, SEE CORNER NO. #68
RE-RENEWED, SEE CORNER NO. 52
RE-RENEWED, SEE CORNER NO. 24
RE-RENEWED, SEE CORNER NO. 10
RE-RENEWED, SEE CORNER NO. #123
RE-RENEWED, SEE CORNER NO. #165

1
2
3
4
5
6
7