

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 1 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

49  
Closing Corner to Sections 3 and 2, T31-1W.  
Found - G.L.O. Brass Cap at Corner, properly marked in 1923.  
40", now 40" D.Fir, S. 24° E. 15.8 ft., shows good scar.  
38", now Stob, D.Fir, S. 27° W. 9.2 ft., shows good scar.  
New BT: 7" Maple S. 48° W. 29.5 ft. mkd. T31S R1W S3 CC CS BT.  
S. E. Bearing Tree O.K. and Tagged.  
Note - This cor. lies on W. slope 207.5 ft. W. of Sec. Cor. 34 & 35, T30-1W.  
7/5/68

50  
 $\frac{1}{4}$  Corner to Section 3 only, T31-1W.  
Found - U.S. G.L.O. Brass Cap, properly marked in 1923, from which:  
30" D.Fir, now Snag, S. 84° W. 239.0 ft. (Rec. 225.7) opened  
for scribe "3" BT.  
Reset Brass Cap at original distance from  $\frac{1}{4}$  corner of Section 34 only,  
180.2 ft. in large mound of stone.  
No trees within reason in south quadrant.  
New BT: 18" D.Fir N. 59° W. 129.0 ft. mkd.  $\frac{1}{4}$  S 3 CS BT.  
Note - Mound of Stone 2x2x2 south 19.2 of  $\frac{1}{4}$  corner.  
This corner lies on east slope in a large opening, all rock

51  
 $\frac{1}{4}$  Corner to Section 5 only, T32-1W.  
Found -  $\frac{3}{4}$ " Iron Pipe (prorated by Leland P. Lovejoy #262, see  
map in C. S. File 41/159. No trees set)  
New BT's: 6" W.Fir S. 28° E. 19.4 ft. mkd.  $\frac{1}{4}$  S 5 CS BT.  
7" W.Fir S. 38° W. 16.6 ft. mkd.  $\frac{1}{4}$  S 5 CS BT.  
Note - This corner lies at fence corner, fences E. & S. Also 159 ft.  
west of S.E. Corner Sec. 32, T31-1W.

52  
Witness Corner to Sec. Cor. to Sections 33 and 34 only, T31-1W.  
Found - No trace of Corner Stone, See Ren. #2.  
28", now 32" D.Fir, almost dead, N. 45° E. 29.7 ft., shows good scar.  
40" D.Fir, now burnt stob, S. 40° E., faint burnt scribe visible.  
12" Maple, now dead, N. 25° W. 19.8 ft., rotten face, old axe  
work and faint marks.  
This corner now lies on east edge of Elk Creek in dangerous place,  
therefore set Witness Corner 50.0 ft. East of True Corner Mkd:  
County Surveyor's Office 1968 W.C. 50.0' West to T 31 S R1W  
S 33 | S 34  
T32S S 4  
New BT's: 10" Ash S. 61° W. 11.4 ft. mkd. W.C. T32S R1W S4 CS BT.  
9" Ash N. 66° W. 16.8 ft. mkd. W.C. T31S R1W S34 CS BT.  
This cor. lies on top of creek bank 2.50 ft. south of fence line.

53  
Closing Corner Sec. 6, T32-1 and Sec. 1, T32-2W. Township Corner.  
Found - Broken Stone at Township Corner, no marks visible.  
55" D.Fir, now 33" splintered stob, S. 55° E. 3.3 ft., scribe vis.  
35" D.Fir, now down & out of place, S. 37° W. 9.9 ft., now root  
hole, found scribe CC T32S R2W.  
15" D.Fir, now rotten stump, N. 70° E. 7.3 ft.  
Set - Brass Cap at Township Cor. Mkd: County Office 1968  
R T 31 S R  
2 CC S 31 1  
W S 1 | S 6 W  
T 32 S  
New BT's: 32" D. Fir S. 37° W. 33.6 ft. mkd. CC T32S R2W S1 CS BT.  
32" D.Fir S. 33° E. 26.2 ft. mkd. CC T32S R1W S6 CS BT.  
Note - This corner lies 15.8 ft. East of  $\frac{1}{4}$  Cor. Sec. 31, T31-1W, below.

54  
 $\frac{1}{4}$  Corner to Section 31 only, T31-1W.  
Found - 30", now 36" D.Fir, N. 50° E. 17.8 ft., shows good scar with parts  
of scribing visible. Also faint bark scribe " $\frac{1}{4}$  S BT".  
Corner Tree & S.E. BT., down & out of place, a lot of trees  
fell out of the same area & slid down the mountain.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968  
T 31 S R 1 W  
 $\frac{1}{4}$  S 31  
T 32 S R 2 W  
New BT: 18" D.Fir N. 21° E. 55.8 ft. mkd.  $\frac{1}{4}$  S31 CS BT.  
This cor. lies 15.8 ft. W. of Township Corner above.

John M. Powell  
Frank Jones & W. Penley  
July, 1968  
C. S. File No. 54/59

John M. Powell  
Frank Jones & W. Penley  
July 25, 1968  
C. S. File No. 54/71

RE-NEWED SEE CORNER NO. #184