

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

John M. Powell & Vernon "Ray" Tracy
August, 1968
C. S. File No. 54/71

1/4 Corner to Section 10 only, (west side) 80
Found - 1923 GLO Brass Cap, in place.
48" D. Fir, now burnt snag, N. 58° E. 31.7 ft., opened
for fragments of scribe.
60" D. Fir, now down, S. 48° E. 61.4 ft.
New BT: 8" D. Fir N. 55° E. 16.5 ft. scribed "1/4 S10 CS BT".
7" D. Fir S. 69° E. 29.2 ft. scribed "1/4 S10 CS BT".
Note - This corner lies 129.4 ft. south of 1/4 corner sec. 9 only, Ren. #79.

Sec. Corner to Sections 16 and 21 only. 81
Found - 1923 GLO Brass Cap, in place.
40" D. Fir, now stump, N. 45° W. 2.6 ft., shows good scar. #205
16" D. Fir, now stump, S. 5° W. 29.7 ft., shows good scar.
Area to the west and south clear cut, therefore:
Set - 3/4" Iron Rod in top of Orig. 43" D. Fir Stump N. 45° W. 3.7 ft.
3/4" Iron Rod in top of Orig. 19" D. Fir Stump S. 5° W. 29.5 ft.
New BT: 28" D. Fir N. 40° E. 27.6 ft. scribed "T31S R1W S15 CS BT".
This corner lies 46.2 ft. north of CC. Secs. 15 & 22, & 15' S. of old road.

Section Corner to Sections 10 - 11 - 14 - 15. 82
Found - 1923 GLO Brass Cap, out of ground. Replaced Brass Cap at Sec. Cor.
18" Hemlock, now stump, N. 65° E. 19.1 ft., opened for scribed.
8", now 10" Hemlock, S. 41° E. 34.3 ft., shows good scar.
28" D. Fir, now stump, out of place. No trace of N.W. BT.
New BT's: 48" D. Fir S. 15° W. 64.4 ft. scribed T31S R1W S15 CS BT.
38" D. Fir N. 16° E. 41.0 ft. scribed T31S R1W S11 CS BT.
12" R. Fir N. 7° W. 50.4 ft. scribed T31S R1W S10 CS BT.

1/4 Corner to Sections 8 and 9. 83
Found - 1923 GLO Brass Cap, firmly set & in good condition.
Orig. 48", now 58" Pine, alive, N. 30° E. 24.4 ft., scribe marks
visible on unhealed blaze.
Orig. 40", now 60" Cedar, alive, N. 67° W. 30.4 ft., shows good scar.
We do not open.
Due to Large Size of Orig. BT's., we mark New BT's:
13" D. Fir N. 85° W. 6.4 ft. mkd: "1/4 S8 CS BT".
16" D. Fir S. 60° E. 17.5 ft. mkd: "1/4 S9 CS BT".
This corner lies on steep, southerly slope.

1/4 Corner to Sections 9 and 16. 84
Found - 1923 GLO Brass Cap, bent over. Straightened & Reset Brass Cap.
10" Yew, down, burnt S. 81° W. 28.8 ft., no scribe found. #178
8" Fir, now 13" Snag, N. 18° W. 15.2 ft., shows scar, we do not open.
New BT's: 42" D. Fir N. 65° E. 44.0 ft. mkd: "1/4 S9 CS BT".
7" Hemlock S. 5° W. 95.0 ft. mkd: "1/4 S16 CS BT".
This corner lies north of dry creek, course S. W.

1/4 Corner to Sections 15 and 22. 85
Found - 1922 GLO Brass Cap at 1/4 Cor., properly marked.
20", now 29" R. Fir S. 72° W. 15.2 ft., shows good scar.
40" D. Fir, now stump, N. 71° E. 14.5 ft., scribe visible.
New BT: 27" R. Fir N. 83° E. 25.4 ft. mkd: "1/4 S15 CS BT".

1/4 Corner to Sections 20 and 21. 86
Found - Orig. 6", now 18" Oak, alive, N. 52° W. 85.8 ft., opened,
reverse "4" on piece, center decayed. #214
No trace Orig. N. E. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 31 S R 1 W
1/4 S 20 | S 21
New BT's: 15" Sugar Pine S. 48 1/2° W. 31.6 ft. mkd: "1/4 S 20 CS BT".
15" Red Cedar S. 23° E. 64.6 ft. mkd: "1/4 S21 CS BT".
This corner lies on moderate westerly slope in scattered oak-fir-cedar-pine.