

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

12/92 OK  
Kaiser  
M 116-30

93

$\frac{1}{4}$  Corner to Sections 32 and 33.  
Found - 10", now 22" D. Fir, N. 37° W. 25.7 ft., scribe marks visible.  
10" D. Fir, now stump, S. 10° E. 7.3 ft., shows scar.  
Also unrecorded Iron Pipe at  $\frac{1}{4}$  Corner.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 31 S R 1 W S 32 S 33  
Reblzd. & Reschd: 22" D. Fir N. 37° W. 25.7 ft. scribed  $\frac{1}{4}$  S32 CS BT".  
New BT: 13" D. Fir S. 17° E. 15.9 ft. scribed  $\frac{1}{4}$  S33 CS BT.  
Note - N. W. Bearing Tree is in fence corner running S - E - W.

94

Section Corner to Sections 11 - 12 - 13 - 14.  
Found - GLO Brass Cap, properly marked in 1923  
36" D. Fir, now 38" Snag, S. 63° E. 11.9 ft., opened & found scribing.  
14" Fir, now stump hole, S. 58° W. 24.4 ft.  
No trace of BT's. in the north. Corner lies in old burn.  
New BT's: 8" D. Fir S. 12° E. 12 ft. scribed T31S R1W S13 CS BT.  
7" D. Fir S. 68 $\frac{1}{2}$ ° W. 15.2 ft. scribed T31S R1W S14 CS BT.  
6" D. Fir N. 68° W. 12.4 ft. scribed T31S R1W S11 CS BT.  
7" D. Fir N. 7° E. 31.7 ft. scribed T31S R1W S12 CS BT.

95

$\frac{1}{4}$  Corner to Sections 11 and 14.  
Found - GLO Brass Cap at  $\frac{1}{4}$  corner, properly marked in 1923.  
36", now 44" D. Fir, N. 18° W. 10.5 ft., shows good face.  
No trace of S. E. Bearing Tree.  
New BT: 10" Yew S. 30° W. 35.6 ft. scribed  $\frac{1}{4}$  S14 CS BT.  
Note - Logging Road bears west 330 feet.

96

Closing Corner for Sections 15 and 22.  
Found - GLO Brass Cap properly marked in 1923.  
30" D. Fir, now stump, N. 35° E. 21.8 ft., shows good scar. #163  
36" D. Fir, now stump S. 55° E. 4.6 ft.  
This corner lies in clear cut area 46.2 ft. S. of Corner for Secs. 16 & 21.  
Set -  $\frac{3}{4}$ " Iron Rod in top of 34" D. Fir Stump N. 35° E. 22.7 ft.  
 $\frac{3}{4}$ " Iron Rod in top of 38" D. Fir Stump S. 55° E. 4.1 ft.

97

$\frac{1}{4}$  Corner to Sections 15 and 14.  
Found - GLO Brass Cap properly marked in 1922.  
24" D. Fir, now stump, S. 37° E. 8.6 ft., shows good scar.  
30" D. Fir, now stump, S. 45° W. 8.6 ft., shows scribe visible "BT".  
New BT's: 11" R. Fir N. 23° E. 19.0 ft. scribed  $\frac{1}{4}$  S14 CS BT.  
13" Hemlock N. 71° W. 36.5 ft. scribed  $\frac{1}{4}$  S15 CS BT.

98

$\frac{1}{4}$  Corner to Sections 22 and 23.  
Found - No trace of 1923 GLO Brass Cap, after deligent search with a metal finder.  
10", now 15" R. Fir, S. 86° E. 13.9 ft., scribe visible.  
16", now 20" R. Fir, S. 83° W. 41.6 ft., shows good scar.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 31 S R 1 W S 22 S 23  
All Bearing Trees O. K. and Tagged.

99

$\frac{1}{4}$  Corner to Sections 14 and 23.  
Found - GLO Brass Cap at  $\frac{1}{4}$  Corner, properly marked in 1922.  
20" D. Fir, now stump, S. 65° W. 13.2 ft., opened for scribe "S23".  
No trace of 8" Fir N. 15° E.  
This corner lies in old clear cut unit. No trees for BT's.  
Set -  $\frac{3}{4}$ " I. Rod S. 65° W. 11.2 ft.  
Location tag on BT Stump S. 65° W. 5.0 ft. 13.2 ft.  
This corner lies 187.0 ft. west of deep ravine.

John M. Powell  
Frank Jones & W. Penley  
August, 1968 and September, 1968  
C. S. File No. 54/71

Fd. OK  
3/5/91 - SHANGE  
C.S. 43/129

WED. CORNER NO. 216

SEE CORNER NO. #163