

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 31 T. S. 1 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

198

1/4 Corner for Sections 19 and 30

CONDITION REPORT ONLY

Found - 1922 GLO brass cap marked U.S. Gen. Land Office 1/4 S19 S30
1922. (GLO notes says 1923) Firmly set projecting 8" above
ground. I.P. is leanly slightly westerly with brass cap
cocked to the west slightly more.

Herzstein, U.S.F.S.
Witness: J. Landrum
June 18, 1982
C.S. 61/32

18" D. Fir, N.10°E., 5.3 ft. with healed double blaze.
36" I. Cedar, S.60°E., 16.5 ft. with healed blaze.

Note: See also C.S. maps M 42 - 74 and M 70 - 23. L. Moffit, L.S. 944
has the bearings reversed to the BTs on his map M70-23.

Corner is + 150 ft. east of USFS Rd. #3132-C.

- File OK, R. Brown, 1994-0036, 2/94

2/18/82

REFERENCED CORNER-

Section corner for Secs. 7 & 18; and Secs. 12 & 13 of T.31-2

199

Found - 8" W. Oak corner tree with 4 healed blazes.

A 4" x 6" x 13" sandstone lying alongside tree with "+" on top
and 3, 6, 6 notches on 3 edges. See Ren.

Both tree and sandstone established by Ben Irving in 1931. # 12 in T.31-2

Searched for and did not find I.P. and brass cap set by John Powell, County
Surveyors Office in 1966. Ren. #19

Corner tree is actual corner position per Irving in 1931.

Found - Orig. 18" W. Oak, S.57°E., 58.0 ft. (Rec. 57.4 ft. to chaining
notch) with scribe marks "S18" visible on previously opened
double blaze and scribe marks "T3 R", marked by Irving in 1931,
visible on partially healed double blaze.

A roothole, S.07°W., 72.6 ft.

A roothole, N.10°E., 51.5 ft. (Rec. N.17°E., 49.5 ft.) with burned
15" oak stump alongside with old axe mark visible.

A 9" W. oak snag, N.37°W., 12.7 ft. (Rec. N.12°W., 10.6 ft. with
rotted healed blaze visible on inside of tree.

A 7" W. Oak, N.28°E., 12.2 ft. (Rec. 11.9 ft.) with healed double
blaze. 1931 Irving tree.

A 7" W. oak, S.42°W., 8.0 ft. (Rec. 8.6 ft.) with healed double
blaze. 1931 Irving tree.

A 16" D. fir, N.55°W., 42.2 ft. (Rec. 41.6 ft.) with previously
opened double blaze. 1931 Irving tree.

Set - Reset stone 12" in ground with "+" on top on north side of
corner tree.

New Accessories:

A 9" D. fir, N.43°E., 64.2 ft. scribed "T31S R1W S7 BT" on double
blaze.

A 7" D. fir, S.63°E., 78.2 ft. scribed "T31SR1WS18BT" on single
blaze.

A 7" W. oak, N.89°W., 9.4 ft. scribed "T31S R2W S12 BT" on
single blaze.

A 3/4" brass washer, stamped "LS 2024" is nailed in base of blaze on each
new BT.

Note: Existant BTs in NE, SE., and NW quadrants fall within the clearing
limits of new road construction (USFS Rd. #3131-860 & -865). Marked
new BTs that will be outside clearing limits. Corner to be checked &
brass cap set when road construction is finished in 1984 or 85.

3/28/8

200

1/4 Corner for Sections 16 and 17

Found - 1966 County brass cap, properly mkd. on 1 1/4" iron post, firmly
set, projecting 12" above a 3 ft. diam. mound of stone. Ren. #16

Orig. Black Oak, 18", N.15°E., 23.8 ft. (Rec. W. Oak, 23.1 ft. to
face) with healed blaze and rescribed by Powell in 1966 with a
healed blaze.

1966 BT, a 8" D. fir stump, N.27°W., 24.1 ft. with a healed blaze.

New BT - 6" D. fir, S.38 1/2°W., 10.2 ft. scribed "1/4 S17 CS BT" on a
single blaze.

Note: Corner is 60 ft. west of U.S.F.S. Road #3131.

6/21/83

Landrum, U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Leonard Herzstein,
Witness
June 21, 1983
C.S. 62/10

Jim Landrum, U.S. Forest Service
Deputy, Doug. Co. Surveyors Office
Leonard Herzstein
March 28, 1983
G.S. 59/30 Now see C.S. 62/15