

Douglas County Surveyor's Record of
Government Corners Renewed

T 31 T. S. R 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Roseburg Lumber Company
F. McCornack, Welker
Ohman & Carstenson
May 24, 1955
C.S. 58/188
(Info. filed 12/1/81)

CC corner for Sec. 6; and Sec. 31 T. 30 - 2
Found - Post obliterated.
Scribing plainly visible, Laurel 15", S.52°E., 27.7 ft.
Evidence of Fir stump, N.52 1/2°E., 19.8 ft.
Metal tag, N.20°W., 8 ft.

220

5/25/55

Gregory Quibell,
Deputy, Doug. Co.
Surveyors Office
Teresa Buley
C.S. 61/29
Nov. 23, 1981

CC corner for Sec. 6; and Sec. 31 of T.30-2
Found - 2" x 2" Fir post 24" long with nail in top, lying in approx.
vicinity of corner. (Probably from Rsbg. Lbr. survey) (SEE #220)
Original Post gone.
Probable remains of orig. 24" Fir now 28" rotted stump flush
with ground.
Metal tag nailed on slab of bark lying at base of rotted 40"
Fir snag approx. 3 ft. tall, per Rsbg. Lbr. survey.

221

I could not find any sign of orig. 6" madrone which was seen in 1955 with
scribing visible. Several small madrones are growing in the vicinity of
orig. madrone BT but I do not feel any of them are the BT.
Set - Using the 24" fir stump I believe to be the orig. fir BT and using
bearing & dist. mentioned in the 1955 Rsbg Lbr. survey (S.52 1/2°
W., 19.8 ft.) (Orig. 21.1 ft.) I SET a 1" x 30" I.P. with brasy
cap attached marked: Douglas Co. Surveyor CC S31 T30S 1981
S6 T31S

Metal tag & tree per Rsbg Lbr. survey was used only as a rough check.
Rec. stated N.20°W., 8 ft. I find center of tree 8 ft., face of tree 6.2 ft.
and bearing to center of base of tree N.2°W., The way the tree seemed to
be leaning when alive could have had a bearing of N.20°W., to the tag itself
if it were about 6 ft. high.

- New BT's- 13" Fir scribed "T30S R2W S31 CS BT" in double blaze bears
N.10°E., 21.4 ft.
- 11" Fir scribed "T30S R2W S31 CS BT" in double blaze bears
N.26°E., 29.8 ft.
- 9" Chingquapin scribed "T31S R2W S6 CS BT" in double blaze
bears S.89°E., 26.4 ft.
- 10" Chinquapin scribed "T31S R2W S6 CS BT" in double blaze bears
S.16°E., 11.7 ft.

Corner location fell on line with a very well blazed N-S line.
(Sketch in file C.S. 61/29)

11/23/81

Gregory Quibell
Doug. Co. Surveyors
Office
Karen Reed
John Powell
April 14, 1982
C.S. 61/30

1/4 Corner for Secs. 14 and 15
Found - 1/2" I.P. protruding 18" out of ground. Ren. #14 and 83
8" now 14" cedar with well healed double blaze bears S.71°W.,
8.0 ft.
9" now 13" cedar with well healed double blaze bears S.52°E.,
25.0 ft. (Rec. S.54°E.)
18" fir stump with scribed "BT" visible bears N.68 1/2°W.,
6.0 ft. (Rec. 5.3 ft.)
Set - At the location of the fd. 1/2" I.P. I SET a 1" x 30" I.P.
with brass cap attached mkd. "Douglas Co Surveyor T31S
S15 S14 1/4 R2W 1982". I place 1/2" I.P. along south
side of brass cap. Due to rocky soil I set I.P. with brass
cap 8" into the ground and build a mound of stone 18" tall
around pipe.

222

- New BT's- 10" fir scribed "1/4 S15 CS BT" in double blaze bears S.14°W.,
15.9 ft.
- 13" fir scribed "1/4 S14 CS BT" in double blaze bears N.44°E.,
42.0 ft.

Sketch in C.S. file.

4/14/82

C
O
N
T.
N
E
X
T
P
A
G
E