

Douglas County Surveyor's Record of  
Government Corners Renewed

T 31 T. S. R 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

223

Jim Landrum, U.S. Forest Service  
Deputy, Doug. Co. Surveyors Office  
Leonard Herzstein  
March 28, 1983  
C.S. 59/30 New See C.S. 62/15

REFERENCED OUT CORNER

Section corner for Secs. 12 & 13; and Secs. 7 & 18 of T.31-1

Found - 8" W. oak corner tree with 4 healed blazes.

A 4" x 6" x 13" sandstone lying alongside with "+" on top and 3, 6, 6 notches on 3 edges. See Ren. #12

Both tree and sandstone established by Ben Irving in 1931.

Searched for and did not find I.P. & brass cap set by John Powell, County Surveyors office in 1966. Ren. #42

Corner tree is actual corner position per Irving in 1931.

Found - 18" W. oak, S.57°E., 58.0 ft. (Rec. 57.4 ft. to chaining notch) with scribe marks "S18" visible on previously opened double blaze and scribe marks "T3 R" marked by Irving in 1931, visible on partially healed double blaze.

A roothole, bears S.07°W., 72.6 ft.

A roothole, bears N.10°E., 51.5 ft. (Rec. N.17°E., 49.5 ft. with burned 15" oak stump alongside with old axe mark visible.

a 9" W. oak snag, N.37°W., 12.7 ft. (Rec. N.12°W., 10.6 ft.) with rotted healed blaze visible on inside of tree.

7" W. Oak, N.28°E., 12.2 ft. (Rec. 11.9 ft. with healed double blaze.

7" W. oak, S.42°W., 8.0 ft. (Rec. 8.6 ft.) with healed double blaze.

16" D. fir, N.55°W., 42.2 ft. (Rec. 41.6 ft.) with previously opened double blaze.

Above three trees marked by Irving in 1931. Ren. #12.

Set - RESET stone 12" in ground with "+" on top on north side of corner tree.

New BTs - A 9" D. fir, N.43°E., 64.2 ft. scribed "T31S R1W S7 BT" on double blaze.

A 7" D. fir, S.63°E., 78.2 ft. scribed "T31S R1W S18 BT" on single blaze.

A 7" W. oak, N.89°W., 9.4 ft. scribed "T31S R2W S12 BT" on single blaze.

A 3/4" D. brass washer, stamped "L S 2024" is nailed in base of blaze on each new BT.

Note: Existant BTs in NE, SE, & NW quadrants fall within the clearing limits of new road construction (US FS RD.# 3131-860 & -865). Marked new BTs that will be outside the clearing limits. Corner to be checked and brass cap set when road construction is finished in 1984 or '85.

3/28/83

Section corner for Secs. 12 & 13; and Secs. 7 & 18 of T.31-1

Found - 8" W. Oak corner tree with 4 healed blazes and a 4" x 6" x 13" sandstone projecting 1" above ground on north side of corner tree with "+" on top, both mkd. by B. Irving in 1931. Ren. #12

Corner tree is actual corner position per Irving in 1931.

1" dia. iron pipe 6" long, 12" below ground, north of corner tree, which is the remains of I.P. and brass cap set by John Powell, County Surveyors Office in 1966. Ren. #42

Found remaining original bearing trees:

A roothole, bears S.07°W., 72.6 ft.

A 9" W. oak snag, N.37°W., 12.7 ft. (Rec. N.12°W., 10.6 ft) with rotted healed blaze visible on inside of tree.

And found BTs marked by Irving in 1931:

A 7" W. Oak stump, N.28°E., 12.2 ft. (Rec. 11.9 ft.) with healed blz

A 7" W. Oak, S.42°W., 8.0 ft. (Rec. 8.6 ft.) with healed double blaze.

And found BTs marked by Jim Landrum, LS 2024 in 1983: Ren. #223

A 9" D. fir, N.43°E., 64.2 ft. with scribe marks "T31S R1W S7 BT" visible on double blaze.

A 7" D. fir, S.63°E., 78.2 ft. with scribie marks "T31S R1W S18 BT" visible on single blaze.

A 7" W. Oak, N.89°W., 9.4 ft. with scribe marks "T31S R2W S12 BT" visible on single blaze.

Set - A reference monument: a 2 1/4" dia. iron pipe 32" long, set 28" in ground with brass cap mkd. T31S RM R2W S12 S13 S7 S18 R1W LS 1181 1984. A 2 ft. dia. mound of stone is flush to top of brass cap. Ref. mon. is north, 0.6 ft. from corner position. Remains of previous I.P. placed inside of new I.P. Buried stone alongside.

New Accessory:

Set 6 ft. steel fence post east, 2.1 ft. with USFS sign #54-4.

Corner is S.10°W., 50 ft. from junction of USFS Rds. #3131-860 and -865.

Maurice E. Farr, L.S. 1181  
U.S. Forest Service  
Leonard Herzstein; Randy Lopez Witnesses  
June 5, 1984  
C.S. 62/15

RE-RECEIVED, SEE CORNER NO. #224

224