

Douglas County Surveyor's Record of  
Government Corners Renewed

31 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

John H. Markham Jr.  
Work done for Stomar Lumber Co.  
Witness: Allen Kusler  
July 29, 1955.  
See C. S. File No. 42/23.

Section corner to secs. 25 and 36. (only)

35

Determined from O. B. T.s:

A 30" Fir bears S.30°E., 23.0 feet.

A 7" Fir snag bears N.39°W., 6.0 feet.

A 30" Fir bears S.18°W., 53.0 feet.

At corner point set a 1" x 30" Iron Pipe and large stone

CORNER NO. 187

from which:

A 16" Fir bears N.45°E., 1.0 feet dist. mkd. S 31 B.T.

A 30" Fir bears N.35°W., 28.0 feet dist. mkd. S 5x B. T.

East 1/4 section corner to section 36. (only)

36

Determined from O. B. T.s:

SEARCHED FOR - NOT FOUND - J.M.P. Aug. 1966

A 22" S. Pine Windfall bears N.76°W., 20.5 feet - O. B. T., found scribe.

A 33" Yellow Pine bears S.46°E., 27.0 feet - O.B.T., found scribe.

At corner point set a 1" x 30" Iron Pipe and large pile of stones

from which:

A 18" Cedar bears S.19°W., 48.5 feet dist., mkd. 1/4 S 36 B.T.

West 1/4 corner section 31, T 31 S, R 2 W., bears North 435.0 feet.

Centerline of logging road bears West 72.0 feet.

George J. Wenderoth  
1947  
C. S. File No.  
39/74.  
#27-14

Center 1/4 corner to section 30.

37

Point for corner located by intersection of the N - S and E - W centerlines of section.

Set a 1 inch iron pipe, from which:

14 inch Cedar, N.4°50'W., 26.5 feet.

12 inch Fir, S.58°45'E., 37.5 feet.

James W. Byron  
For Douglas County Rd. Dept.  
Jan. & Feb. 1957  
Road Drawer 48/ Rd.#36

1/4 Section Corner to Section 31, R3W, Section 36, R4W.

38

Found - 2" X 2" Sq. Post at corner. Also Both BTs. (stumps only now)

The S.W. BT. has visible scribe marks.

The N.E. BT. has burned face. BTs. check for bearings & distances.

Set Brass Cap at corner marked S36/S31 T31S County Surveyor's  
Corner Under 3 ft. log R4W R3W Office, 1957

From which: 16" W. Fir bears N.21°E. 79.5 ft. scribed 1/4 S31 T31S R3W CS BT.

12" W. Fir bears N.83 1/2°W. 53.2 ft. scribed 1/4 S36 T31S R4W CS BT.

1/4 Section Corner to Section 31, T31S R3W, & Section 6, T32S R3W.

38-A

Found - 1 1/2" I. P. at E. W. Fence Line. - REN.#11

The N.W. BT. good condition. checks for bearing & distance, scribe visible.

The S.W. BT. down.  
I blaze & scribe 10" Hemlock S.22 1/2°W. 24.3 ft. S6 T32S R3W. 1/4 Cor. CS BT.

Richard L  
Templin, Jr.  
Sept. 1958  
C.S. File No.  
42/390

1/4 Section Corner common to Secs. 24 & 25.

39

Found - Stone Mkd. 1/2 on North Face.

48" Fir S.27°E. 15 lks., dead & down.

30" Fir N.54°E. 66 lks., blaze healed.

Scribed : 10" Fir S.18°W. 35.4 ft. mkd. 1/4 S25 RE3024 BT.

CORNER NO. 85

John H. Markham, Jr.  
For Stomar Lbr. Co.  
Mit. R.G. Boyd  
Sept. 1958  
C.S. File No. 42/392

N.W. Corner Section 3.

40

Det. by O.B.T.'s.

16" Fir Snag bears S.44°W. 4.6 ft. dist. O.B.T. found scribe

16" Fir bears N.57°E. 22.4 ft. dist. O.B.T.

At Corner Point Set 1" X 30" Iron Pipe from which:

10" Fir bears S.59°W. 21.0 ft. dist. mkd. S4 BT.

6" Fir bears N.45°E. 16.0 ft. dist. mkd. S34 R3W BT.

6" Fir S.81°E. 26.6 ft. dist. mkd. S3 T31S BT.

South 1/4 Corner Sec. 34 bears East 441.5 ft.

CORNER NO. 121