

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

Corner to Sections 10, 11, 14 & 15.

94

Found - 3/4" iron pipe set by Markham. (Ren. # 68)

40" Doug. Fir S. 41° E. 38.3 ft. Some scribing visible through pitched over face.

18" Laurel N. 49° E. 31.4 ft. Shows faint scars.

The fir tree S. 33 1/2° W. 14.5 ft. is uprooted & down. Good scar visible.

The fir N. 59 1/2° W. 6.5 ft. is down & badly rotted. Axe marks found, but no scribing.

All trees marked by Markham in good condition, as follows:

4" pine S. 5° E. 21.6 ft.

5" Live Oak S. 37° E. 28.0 ft.

4" Chinq. S. 86° W. 10.1 ft.

13" Laurel N. 15° E. 5.6 ft.

(No scribing on upper blaze-"BT" bark scribed)

Set - Brass Cap marked: "County Surveyor's Office 1964

T. 31 S.R. 3 W. $\frac{S10}{S15} \frac{S11}{S14}$

Reset iron pipe alongside.

Reblaze & Scribe:

13" Laurel N. 15° E. 5.6 ft. Mkd: "T 31 S.R. 3 W. S 11 CS BT"
Corner lies on steep west slope

Section Corner to Sections 2, 3, 10 & 11.

95

Found - Wooden stake set by Markham. (Ren. # 47)

Incense Cedar (now 14" diam.) S. 25 1/4° E. 24.0 ft. Good scribing "3W S 11" visible on previously opened scar.

Incense Cedar (now 30" diam.) S. 63 3/4° W. 28.0 ft. Shows good axe scars.

33" Fir N. 59° W. 12.0 ft. Uprooted & down.

No trace found of original NE tree.

All trees mkd. by Markham in 1959 are alive & in good condition:

4" Fir S. 62° E. 3.7 ft.

3" Fir S. 84° W. 15.5 ft.

6" Fir N. 10° W. (not S. 10°W) 33.2 ft.

12" Chinq. N. 16° E. 62.0 ft.

Set - Brass Cap mkd: " County Surveyor's Office 1964

T. 31 S.R. 3 W. $\frac{S3}{S10} \frac{S2}{S11}$

Drive Markham's stake alongside.

No new trees scribed.

1/4 Corner to Sections 2 & 3.

96

Found - 30" Hemlock S. 75° W. 163.0 ft. (Slope dist. according to Ren. # 42 Markham) Uprooted & down. Scribing visible "1/4 S 3"

25" Alder S. 57° W. 137.0 ft. Dead, Leaning badly & blazes buried in sand, rocks & debris.

15" Fir with scribing lying alongside of road - could not tell where it had stood.

Corner falls in logging road near cut bank on N. side - Drove

3/4" iron rod in road at corner. (See Ren. # 42)

New BTs: 36" Doug. Fir N. 66° W. 181.0 ft. Mkd: "1/4 S 3 CS BT"

10" Doug. Fir N. 62° W. 411.9 ft. Mkd: "1/4 S 3 CS BT"

No trees near East of line. Location impractical to set

Witness Corner.

Fa. O.K. - Dec. 1965 J.M.P.

Milo E. Godfrey, Dep. Surv.
Wm. Stoffel, Mike Darby, Mike Stone
June, 1964
C. S. File No. 52/63

Ren. # 42
200

SEE CORNER NO.