

Douglas County Surveyor's Record of
Government Corners Renewed

T 31 T. S. R 3 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

222

Center 1/4 Corner for Section 28
Set - 2" x 30" Alum pipe with 2 1/2" magnetized alum. cap marked:
T31S R3W C 1/4 S28 PLS 866 1980.
New BT's- 12" W. Fir bears N.7°15'W., 19.8 ft. "C 1/4 S28 BT"
18" W. Fir bears N.6°18'E., 13.4 ft. "C 1/4 S28 BT".

223

1/4 Corner for Sections 27 and 28
Found - 2 1/2" Brass cap on 1" galv. i.p.mkd. County Surveyors Office T31S
R3W S28 S27 1/4 1966. Ren. #159
52" D. Fir, almost dead, bears N.52°30'E., 42.0 ft. "B" visible.
16" Pine N.76°45'E., 25.3 ft. healed scar.
34" Madrone S.26°15'W., 48.6 ft. down & rotted.
18" D. Fir S.78°15'W., 65.2 ft. down.
New BT- 6" D. Fir S.15°45'W., 35.6 ft. "1/4 S28 BT"

224

~~1/4 Corner for Sec. 33 only. (north) See
Found - 3" D. Fir stump, N.47°30'E., 47.5 ft. "1/4" visible. Ren. #1
Set - 2" x 30" Alum pipe with 2 1/2" magnetized alum. cap mkd. T31S
R3W 1/4 S33 only PLS 866 1980.
New BT's- 18" D. Fir, S.14°43'E., 75.4 ft. "1/4 S33 BT"
7" D. Fir S.46°00'W., 8.3 ft. "1/4 S33 BT". #219~~

225

1/4 Corner for Sec. 28 only. (See also Ren. #1)
Set - 2 1/2" Alum. cap on 2" x 30" Alum. pipe marked T31S R3W 1/4 S28 only.
PLS 866 1980.
New BT's- 9" W. Fir, N.45°45'W., 4.0 ft. "1/4 S28 BT"
8" W. Fir, N.75°35'E., 21.3 ft. "1/4 S28 BT".

2/80
226

1/4 Corner for Sec. 1 only of T.32-3.
Set - Alum. cap by proportion stamped: T31S R3W 1/4 S1 T32S R3W
1980 RLS 601.
New BT's-14" D. Fir bears S.16°15'E., 49.2 ft.
16" D. Fir bears S.38°45'W., 39.0 ft.
Both trees scribed "T32S R3W 1/4 S1 BT".

227

1/4 Corner for Secs. 23 and 24 Ren. #71
Fd - 3/4" x 24" Iron pipe with possible original stone alongside.
18" Madrone bears N.30°51'W., 32.1 ft. with good scars.
9" Madrone bears N.50°04'E., 12.3 ft. with good scars.
24" Pine bears N.87°51'E., 7.0 ft. with good scars.
12" Madrone bears S.69°02'E., 11.6 ft. with good scars.
8" Madrone bears S.30°21'W., 4.8 ft. with good scars.
18" Madrone bears S.29°18'E., 52.8 ft. Possible original B.T.,
another very rotten tree is close to this one.
Set - 2" x 30" Aluminum pipe with 2 1/2" Aluminum cap mkd: T31S R3W
Replaced 3/4" x 24" iron pipe on west side of aluminum pipe. PLS 866 1980

228

Center 1/4 Corner for Sec. 24 T31S R3W C1/4
Set - 2" x 30" aluminum pipe with 2 1/2" aluminum cap mkd: S24 PLS866 1980
BT's - 15" Cedar bears S.89°40'E., 123.6 ft. scribed "C1/4 S24BT".
12" Cedar bears N.71°50'E., 126.5 ft. scribed "C1/4 S24 BT".
Attached 3/4" Brass washer marked "LS866" to lower blaze of each BT.

229

1/4 Corner for Sec. 24 only. T31S R3W 1/4
Set - 2" x 30" aluminum pipe with 2 1/2" aluminum cap mkd: S24 PLS866 1980
BT's - 12" Fir bears S.88°40'W., 54.6 ft. scribed "1/4 S24 BT". Attached
3/4" brass washer marked "LS866" to lower blaze.
13" Cedar bears S.35°W., 56.6 ft. scribed "1/4 S24 BT". Attached
3/4" brass washer marked "LS866" to lower blaze.

William Ruppert
For: U.S. Forest Service
February 1980
M 79 - 29 and C.S. 58/143 n

Fd B.C.
7/81-82
Admin. Survey
SEE GIS FILE

Colm Clark
For: U.S. Forest
Service
April 1980
M 83 - 53 and
C.S. 58/227 (n)

William J. Ruppert
LS #866
For: U.S. Forest Service
April 1980
M 79 - 43 and C.S. 58/143N

Fd CAP 7/81 BLM
Admin. Survey - SEE
GIS FILE